LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C A D C P 1 2 0 0 - 0 0 0 0 - 0 0
0 1 7 8	SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	Prior to fuel load, during normal surveillance testing, the Steam Generator
0 3	Blowdown Tank Liquid Radiation Monitor RM-23 failed the quarterly functiona
0 4	test required by Technical Specification 4.3.3.9.1. Subsequent investiga-
0 5	tion revealed that the photo multiplier tube had failed. Technical Speci-
0 6	I fication Action Statements were satisfied. Since the plant has not attained
0 7	criticality and no effluents were being released via this pathway, this
0 8	event in no way affects public health and safety. (Continued on attachment)
0 9	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	LER/RO EVENT YEAR REPORT NO. 17 REPORT 8 2
1 0	Cause of photo multiplier tube failure is under investigation.
11	
1 2	
1]3	
7 8	9 80
F	B 28 0 0 0 29 NA NA ROUTINE SURVEILLANCE TESTING 32
1 6 RE	TIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36 NA NA NA
, 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7	PERSONNEL INJURIES
1 R	NUMBER DESCRIPTION (41) O O O O O NA
	OSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION Z (42) NA
2 0 15	PUBLICITY SUED DESC PDR ADOCK 05000275 PDR SO SEED DESC PDR ADOCK 05000275 PDR SEED DESC PDR SEED DE
	NAME OF PREPARER W. B. Scott PHONE (805) 595-7351

ATTACHMENT to LER 82-005/03L-0

Item 10, Event Description and Probable Consequences, continued

This event is reportable per Technical Specification 6.9.1.13.b.