

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I L Q A D I				2	0	0	0	-	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5	
7	8	9				14	15				25				26				30				57				58	
		LICENSEE CODE					LICENSE NUMBER									LICENSE TYPE				CAT								

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	5	4	7	0	4	1	2	8	2	3	0	1	2	2	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On April 12, 1982, while performing the High Drywell Pressure Auto Blowdown /  
HPCI monthly surveillance, QIS-8, pressure switch PS-1-1001-89B was found to  
trip at 2.025 psig. This was in excess of the 2.0 psig Technical Specification  
3.2.B. limit. This switch is arranged in a one-out-of-two-twice logic  
arrangement. The other three switches were found to be within limits and  
would have provided the high Drywell pressure initiation signal for Automatic  
Blowdown. Thus, plant operation was not affected.

SYSTEM CODE 0 9		CAUSE CODE I A		CAUSE SUBCODE E		COMPONENT CODE I N S T R U						COMP SUBCODE S		VALVE SUBCODE Z								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22							
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
23	24	25	26	27	28	29	30	31	32													
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50					
E	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	Y	24	N	25	S	3	8	2	26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this occurrence was instrument setpoint drift of PS-1-1001-09B

1 1 | (manufactured by Static-O-Ring, Buna-N type diaphragm, model number 12N-AA5-PP).

1 2 | The pressure switch was recalibrated to 1.95 psig and functionally tested.

1 3 | The present surveillance and recalibration schedule will continue to minimize

1 4 | drift frequency and severity.

8 9 FACILITY STATUS (28) 0 8 4 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) Surveillance Test

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33

2 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

NA

45 80

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	40 NA

1 9		7 42		LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION		(43)	
				NA					

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PUBLICATION INFORMATION

ISSUED (2) (0) (44) (45) DESCRIPTION NA

NRC USE ONLY

NRC USE ONLY

8205110221 820422  
PDR ADCK 05000254  
S PDR

Ken Medulan

PHONE 309-654-2241, ext. 179

UPO 917-920