LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T O 1 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) WHILE PERFORMING A ROUTINE TOUR IT WAS DISCOVERED THAT THE RECORDER (1-CS-001) USED
[0]3 FOR CONTAINMENT SUMP FLOW MONITORING HAD NOT BEEN INDICATING FOR APPROXIMATELY 12
HOURS. THIS EVENT WAS CONTRARY TO THE REQUIREMENTS OF TECHNICAL SPECIFICATION
ols 3.4.6.1b. THIS IS THE FIRST OCCURRENCE OF THIS TYPE.
06
0 7
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE COMPONENT CODE SUBCODE I E 11
17) REPORT NUMBER 2 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 0 0 0 0 0
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) INVESTIGATION FOUND THE RECORDER PEN HEATER RHEOSTAT DIRTY PREVENTING THE PEN FROM
INDICATING. THE RHEOSTAT WAS CLEANED, THE RECORDER VERIFIED OPERATING CORRECTLY AND
RETURNED TO SERVICE. TO PREVENT RECURRENCE, THE RECORDER PREVENTIVE MAINTENANCE
FREQUENCY HAS BEEN INCREASED FROM 18 MONTHS TO MONTHLY.
1 1 2 80
FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA N
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
LOSS OF OR DAMAGE TO PACILITY 43 TYPE DESCRIPTION NA
80 10 8205110227 820429 80 PDR ADOCK 05000315 NRC USE ONLY
R. A. PALMER 616-465-5901
NAME OF PREPARERPHONE: