

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N E C P R 1 2 0 0 - 0 0 C 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 4 1 5 8 2 8 0 5 0 6 8 2 9
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During diagnostic testing of mechanical snubbers by Wyle Laboratory, a Model PSA-10,
03 S/N 544, snubber exceeded the acceleration rate of 0.02g for the compression stroke
04 which identifies it as an inoperable snubber under Section 3.6.H.1 of the Tech. Spec.
05 Prior to the discovery of the event this snubber was removed and the seismic structure
06 redesigned during the 1981 Refueling under the Mark I Containment Program. This event
07 is not repetitive and there were no adverse effects to the public health and safety.

08
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

09 SYSTEM CODE X X 11 CAUSE CODE B 12 CAUSE SUBCODE B 13 COMPONENT CODE S U P P O R T 14 COMP. SUBCODE D 15 VALVE SUBCODE Z 16
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 LER/RO REPORT NUMBER 8 2 EVENT YEAR 8 2 SEQUENTIAL REPORT NO. 0 0 8 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0
21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT 4 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. 24 PRIME COMP. SUPPLIER X 25 COMPONENT MANUFACTURER P 0 2 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The snubber failed due to improper installation of the clutch spring in the snubber by
11 the manufacturer. The snubber is a Model PSA-10, Part No. 1801103-07, manufactured by
12 Pacific Scientific Company. This snubber was removed from service on 6-2-81 and failed
13 its recertification test on 4-15-82. It has been sent to the manufacturer for repair.

14
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

15 FACILITY STATUS Z 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Recertification Testing 32
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

16 ACTIVITY CONTENT RELEASED OR RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

19 LOSS OF OH DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

20 PUBLICITY NUMBER N 44 DESCRIPTION NA 45
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER Paul L. Tallinger

PHONE 402-825-3811

8205180 441

NRC USE ONLY