LICENSEE EVENT REPORT

U. D. MUDELMII HEUDENTUHT GUMMINGION

	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B E P 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 58
O 1 8	REPORT L 6 0 5 0 - 0 3 2 4 7 0 4 1 6 8 2 8 0 5 1 0 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	During plant operation, routine surveillance revealed that drywell floor drain (DWFD)
0 3	flow integrator, 2-G16-FQ-K601, was continuously indicating DWFD sump flow with no
0 4	DWFD pumps running. The DWFD integrator was declared inoperable in accordance with
0 5	technical specifications. Similar events have been reported in LERs 2-81-67, 1-82-1,
0 6	2-82-18, and 2-82-40. This event did not affect the health and safety of the public.
0 7	
0 8	Technical Specifications 3.4.3.1, 6.9.1.9b
0 9	SYSTEM CODE CODE SUBCODE SUBCO
	TO REPORT 8 2 - 0 7 5 0 3 L - 0
	ACTION FUTURE TAKEN ACTION ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP SUPPLIER MANUFACTURER [X] [8] [F] [9] [Z] [20] [Z] [21] [0] [0] [0] [Y] [23] [Y] [24] [N] [25] [G] [0] [8] [0] [26]
1 0	The false indications occurred because the integrator, Model No. 561, and the
11	integrator square root converter, 2-G16-FY-K601, Model No. 565, were both operating
1 2	out of calibration tolerances. FQ-K601 and FY-K601 were calibrated and returned to
1 3	service. To improve FQ-K601 reliability, a modification to install a vortex type
7 8	flow meter in place of the integrator transmitter will be implemented.
1 5	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 7 9 29 NA A 44 45 46 Operator Surveillance 80
	ACTIVITY CONTENT DELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA N
1 7	PERSONNEL EXPOSURES NUMBER O O O O O O O O O O O O O O O O O O O
(TIB)	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA
7 8	9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	TYPE DESCRIPTION NA NA 80
20	PUBLICITY ISSUED DESCRIPTION 45 8205 180 585 NA NA NRC USE ONLY
7 8	9 10 68 69 80-3 NAME OF PREPARER M. J. Pastva, Jr. PHONE 919-457-9521

LER ATTACHMENT - RO #2-82-75

Facility: BSEP Unit No. 2 Event Date: 4/16/82

During plant operation, routine operator surveillance revealed that drywell floor drain (DWFD) sump flow integrator, 2-Gl6-FQ-K601, General Electric Model No. 561, was showing continuous indication of DWFD sump pump flow with no DWFD sump pumps running. The investigation of this event revealed that the false indication occurred because the integrator and the integrator square root converter, 2-Gl6-FY-K601, General Electric Model No. 565, were both operating out of specified instrument tolerances, attributed to instrument setpoint adjustment drift. The integrator and square root converter were both calibrated and returned to normal service.

Due to several past similar events involving the drywell equipment drain and floor drain integrating systems on both Unit Nos. 1 and 2, a plant modification has been developed. The major objective of this plant modification will be to eliminate the transmitter utilized in the present integrator system and replace it with a flow meter. It is felt that this will help in the prevention of similar events. Presently, a target date for installation and completion of this modification has not been established.