

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)7CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)72487 87787 8

912-367-7781

LER No.: 50-321/1982-008.
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-321

Narrative Report
for LER 50-321/1982-008.

While the plant was in startup mode at 5 Mwt, 1T47-R612 (Drywell Temperature Recorder, was found to be inoperable. Tech Specs Table 3.2-11 requires two operable channels. Redundant recorder, 1T47-R611, was also inop placing the plant in a 30 day LCO. Plant operation was placed in a 7 day LCO as a result of this event. The health and safety of the public was not affected. This is a non-repetitive event.

The cause of the event has been attributed to component failure. The failure was due to a broken micro switch. The switch was replaced and the recorder was returned to service.