LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	G A E I H 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6
CON'T	REPORT L 6 0 5 0 0 0 3 2 1 7 0 4 2 2 8 2 8 0 5 1 3 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	While the plant was in steady state power operation at 2431 MWt, 1G11-N003,
0 3	Drywell Floor Drain Sump Flow Transmitter, would not calibrate. Tech Specs
0 4	Section 3.2-10 requires one subsystem to be operable. Redundant equipment
0 5	flow transmitter 1G11-NO12 was operable. Plant operation was not affected.
0 6	The health and safety of the public was not affected. This is a non-re-
0 7	petitive event.
0 8	80
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. OCCU
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER A 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 25 G 0 8 0 26 33 34 34 35 35 36 37 40 40 41 23 42 43 43 44 47
1 0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of the event has been attributed to component failure. The
111	failure was due to a bad amplifer and resistor assembly. The component
1 2	was replaced and transmitter recalibrated and returned to service.
1 3	
1 4	
7 8	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 [E] 28 1 0 0 29 NA B 31 Technical Specifications
	ACTIVITY CONTENT 12 13 44 15 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 6 NA
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	
1 9	LOSS OF OR DAMAGE TO FACILITY (42)
-	Z 42 NA
7 8	TYPE DESCRIPTION Z 42 NA PUBLICITY ISSUED DESCRIPTION 45 PDR ADOCK 05000321 SSUED DESCRIPTION 45 PDR ADOCK 05000321

LER No.: 50-321/1982-032

Licensee: Georgia Power Company

Facility: Edwin I. Hatch

Docket No.: 50-321

Narrative Report for LER 50-321/1982-032.

While the plant was in steady state power operation at 2431 MWt, 1G11-N003, Drywell Floor Drain Sump Flow Transmitter, would not calibrate. Since 1G11-N003 would not calibrate properly. Integrator 1G11-K601 read low and was out of tolerance per HNP-1-3964, Drywell Floor Drain Sump Instrument Functional Test and Calibration. Tech Specs Section 3.2-10 requires one sub-system to be operable. Redundant equipment flow transmitter 1G11-N012 was operable. Plant operation was not affected. The health and safety of the public was not affected. This is a non-repetitive event.

The cause of the event has been attributed to component failure. The failure was due to a bad amplifier and resistor assembly. The component was replaced and transmitter recalibrated per HNP-1-5210, GE Type 555 and 556 Pressure Transmitters, and returned to service. Performed surveillance on loop per HNP-1-3964 and found to be satisfactory.

CONFIRMATION STATEMENT

For Document

0 - 02//782 - 03(Description of Document)

I have checked the statements made in this document and, to the best of my knowledge, the statements made in this response are accurate.

(Signature)

(Date)

REGULATORY COMPLIANCE REVIEW
DOCUMENT # [ER 1-92-32
CHANGES NEEDED (W YES () NO
IF YES, SEE COMMENTS
COMMENTS: COMMENTS
COMMENTS: CONSTITUTE

REVIEWED BY: TRS
DATE: 5/7/82