

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	T	N	S	N	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
8	9	LICENSEE CODE						14	LICENSE NUMBER												25	LICENSE TYPE					30	CAT NO		

CON'T

0 1 8
REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
DOCKET NUMBER 0 5 0 0 0 3 2 7 7 0 6 1 5 8 1 8 0 7 1 5 8 1 9
EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On 6-15-81 at 0948(c) with Unit 1 at 100% RTP, an operator observed the loss of a
0 3 | green status light for turbine building sump discharge monitor 0-RM-90-212. The
0 4 | monitor failed to source check and was declared inoperable. On 6-29-81 at 0900 the
0 5 | malfunction alarm for 0-RM-90-212 was again initiated causing the monitor to be declared
0 6 | inoperable. Unit 1 entered action statement 32 of LCO 3.3.3.9 on both occasions.
0 7 | There was no effect on public health or safety. No previous occurrences.
0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE	
M C (11)		E (12)		E (13)		I N S T R U (14)		E (15)		Z (16)	
9 10		11		12		13 18		19		20	
LEA/RO REPORT NUMBER (17)		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
8 1 (21)		22		0 6 6 (24)		0 3 (28)		L (30)		2 (32)	
21 22		23		24 26		27		28 29		30 31	
ACTION TAKE/1		FUTURE ACTION/1		EFFECT OF PLANT		SHUTDOWN METHOD		HOURS (22)		ATTACHMENT SUBMITTED	
B (18) Z (19)		Z (20)		Z (21)		0 0 0 0 (37)		N (23)		N (24)	
33 34		35		36		37 40		41		42	
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		NPD-4 FORM SUB.		CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
L (25)		G 0 6 3 (44)		L (25)		43 47		43		44 47	
43		44		45		46		47		48	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 On each occasion the monitor failed due to sample pump housing wear. On the first

1 occasion the pump was replaced and declared operable at 1420 on 6-17-81. On the second

2 occasion, the pump housing was replaced and declared operable on 7-1-81. Problems with

3 the acid neutralization system (the root cause for the pump deterioration) are being

4 studied and necessary corrective actions will be implemented.

6 9
FACILITY STATUS: 5 E 28 10 12 13 29 NA 30 OTHER STATUS 31
METHOD OF DISCOVERY 32 Operator observation 33
ACTIVITY CONTENT 34 35
RELEASED OF RELEASE 36
AMOUNT OF ACTIVITY 37
PERSONNEL EXPOSURES 38
NUMBER TYPE DESCRIPTION 39
PERSONNEL INJURIES 40
NUMBER DESCRIPTION 41
LOSS OF OR DAMAGE TO FACILITY 42
TYPE DESCRIPTION 43
PURITY 44
ISSUED DESCRIPTION 45
NA 46
PDR ADOCK 05000327
S PDR
NRC USE ONLY

Name of Preparer: M. R. Harding/A. N. Wilkey

∴ (615) 842-8317