## LICENSEE EVENT REPORT

	CONTROL BLOCK:
0 1	I A D A C 1 2 0 0 - 0 0 0 0 - 0 0 0 0 - 0 0 0 0 57 CAT 56
CON'T	SQUACE 50 0 15 10 10 10 13 13 1 7 10 14 12 16 8 12 3 10 15 12 11 8 12 9
0 2	During normal operation while performing surveillance testing, the pressu
0]]	re differential switch which controls reactor building to suppression cha
04	mber vacuum breaker CV 4304 tripped at an out of spec. value. The switch,
0 5	PDS 4304, tripped at .9 psid. Tech. Spec. 3.7.A.3.a requires the setpoint
0 6	to be .5 psid. PDS 4305, which controls redundant vacuum breaker CV 4305,
0 7	L was operating properly. Six previous similar occurrences (See AO 75-33, R
0 8	0 77-55, R0 78-32, R0 79-18, R0 80-23, and R0 81-48).
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	TO SEQUENTIAL REPORT NO.  17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	Instrument drift. Contributing cause is large range of switch resulting
1 1	Lin decreased setpoint accuracy and difficulty in calibration. PDS 4304 i
1 2	Ls Barton press. diff. switch Model 288A. Switch was recalibrated and fun
1 3	ctionally tested sat. Range of PDS 4304 and 4305 to be decreased by repl
14	Lacing bellows unit assemblies. Increased surveil. testing continuing.
	STATUS SHOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Surveillance Test
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35
1 7	PERSONNEL EXPOSURES  NUMBER TYPE DESCRIPTION 39  O O O O O O O O O O O O O O O O O O O
7 4	PERSONNEL INJURIES NUMBER DESCRIPTION 41  O O O O NA  NA  NA  NA  NA
1 9	COSS OF OR DAMAGE TO FACILITY 43 8205280 137
2 0	ISSUED DESCRIPTION 45  NA  NA  NA  NA  NA  NA  NA  NA  NA  N
	NAME OF PREPARER David M. Varner 319-851-5611

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

Licensee Event Report - Supplemental Data

Docket No. 050-0331

Licer. vent Report Date: 5-21-82

Rep ccurrence No.: 82-031

## E ption:

normal operation while performing surveillance testing, the pressure differential switch which controls reactor building to suppression chamber vacuum breaker CV 4304 tripped at an out of specification value. The switch, PDS 4304, tripped at 0.9 psid. Technical Specification 3.7.A.3.a requires the setpoint to be 0.5 psid. PDS 4305, which controls redundant vacuum breaker CV 4305, was operating properly. There have been six previous similar occurrences (see AO 75-33, RO 77-55, RO 78-32, RO 79-18, RO 80-23, and RO 81-48).

## Cause Description:

The cause is attributed to instrument drift. A contributing cause is the relatively large range of the switch, which results in decreased setpoint accuracy and difficulty in calibration. PDS 4304 is a Barton pressure differential switch Model 288A.

## Corrective Action:

The switch was recalibrated and functionally tested with satisfactory results. To increase the accuracy or setpoint repeatability and make calibration less difficult, a design change has been initiated to decrease the range of switches PDS 4304 and 4305. This will be accomplished by replacing the bellows unit assembly on each switch. Installation of this design change is planned for the Fall 1982 refueling outage. Increased surveillance testing is continuing.