



SUPPLEMENTARY INFORMATION

Report No.: 50-302/82-018/03L-0

Facility: Crystal River Unit 3

Report Date: April 8, 1982

Occurrence Date: March 8, 1982

Identification of Occurrence:

Boric Acid System inoperable contrary to Technical Specification 3.1.2.2.a.

Conditions Prior to Occurrence:

Mode 1 power operation (75%).

Description of Occurrence:

At 1525, following recirculation of Boric Acid System tanks, it was discovered that both Boric Acid System tanks were isolated. Surveillance Procedure SP-320 was performed to place the Boric Acid System tanks in proper valve lineup. Redundancy was provided by borated water storage tanks.

Designation of Apparent Cause:

The cause of this event is attributed to a procedure deficiency.

Analysis of Occurrence:

Redundancy was provided by the borated water storage tanks. There was no effect upon the health or safety of the general public.

Corrective Action:

Operating Procedure OP-403 has been revised to prevent recurrence of this event. No further corrective action is deemed necessary.

Failure Data:

This is the first occurrence of this event, and this is the tenth event reported under this Specification.

/rc