LICENSEE EVENT REPORT

*	
,	CONTROL BLOCK:
0 1 7 8	C A S O S 2 2 0 O O O O O O O O O
CONT	REPORT L 6 0 5 0 0 0 3 6 1 7 0 4 2 4 8 2 8 0 5 2 4 8 2 9 SOURCE 60 61 COCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	While in Mode 4, during the monthly surveillance test of Train 'B'
0 3	of the Control Room Emergency Air Clean-Up System, the heater cycled
0 4	on and off. Public health and safety were not affected.
0 6	
0 6	
0 7	
0 8	80
7 8	SYSTEM CAUSE CAUSE CODE SUBCODE SUBCOD
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 1 2 0 3 L — 0
	ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPL'ER MANUFACTURER
	A (18) X (19) Z (20) Z (21) [0] 0 [0] [Y (23) [N] (24) [A] (25) [A] [2] [2] (26)
	33 34 36 36 36 37 40 41 42 43 44 47 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	Flow control switch and pitot tube did not operate reliably. The
111	flow switch was bypassed with a jumper and the system restored to
12	service April 26, 1982. Subsequently, the switch was replaced, pitot
1 3	tube reoriented, and the system recalibrated.
114	
7 8	FACILITY NOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B (28) O O (29) N/A B (31) Operator Observation
	9 10 12 13 44 45 46 80
1 6	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) N/A LOCATION OF RELEASE (36) N/A
7 8	9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
17	0 0 0 3 Z 38 N/A
	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	0 0 0 40 N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
7 8	9 PUBLICITY (45) 8206010377 NRC USE ONLY
2 0	N 44 N/A
7 8	9 10 ATBLAY PHONE (714) 492-7700 0
	NAME OF PREPARER PHONE