

LICENSEE EVENT REPORT

Unit 2

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | T | N | S | N | P | 2 | 7 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 1 | 0 | 1 | 0 | 0 | 3 | 2 | 8 | 7 | 0 | 3 | 2 | 7 | 8 | 2 | 8 | 0 | 4 | 2 | 3 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | Unit 2 in mode 1 at 100% RTP. During SI-566, ERCW Flow Verification Test, the
0 3 | ERCW flow through containment spray heat exchanger 2B was discovered to be 800 gpm.
0 4 | The required flow rate through the heat exchanger is 4935 gpm. This event required
0 5 | entry into 3.7.4. There was no effect upon public health or safety. Previous
0 6 | occurrences - none.

0 7 |

0 8 |

0 9 | SYSTEM CODE | S | B | 11 | CAUSE CODE | D | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | V | A | L | V | E | X | 14 | COMP SUBCODE | B | 15 | VALVE SUBCODE | G | 16

17 | LER/RO REPORT NUMBER | EVENT YEAR | 8 | 2 | 22 | SEQUENTIAL REPORT NO. | 0 | 4 | 7 | 26 | OCCURRENCE CODE | 0 | 3 | 29 | REPORT TYPE | L | 31 | REVISION NO. | 0 | 32

ACTION TAKEN | G | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NPD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | L | 25 | COMPONENT MANUFACTURER | X | 9 | 9 | 9 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | Containment spray heat exchanger outlet flow balancing valve 2-FCV-67-537B was
1 1 | adjusted to provide the proper ERCW flow. Testing found the new flow rate to be
1 2 | approximately 5400 gpm.

1 3 |

1 4 |

1 5 | FACILITY STATUS | B | 28 | % POWER | 1 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance test | 32

1 6 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

2 0 | PURCITY | N | 44 | ISSUED DESCRIPTION | NA | 45

8206010395

NRC USE ONLY

Name of Preparer: G. B. Kirk /M. R. Harding Phone: (615) 751-0349

LER SUPPLEMENTAL INFORMATION

SQRO-50-328/82047 Technical Specification Involved: 3.7.4

Reported Under Technical Specification: 6.9.1.13.c

Date of Occurrence: 03/27/82 Time of Occurrence: 0330 CST

Identification and Description of Occurrence:

During SI-566, ERCW Flow Verification Test, the ERCW flow through containment spray heat exchanger 2B was discovered to be 800 gpm. The required flow rate through the heat exchanger is 4935 gpm.

Conditions Prior to Occurrence:

Unit 2 in mode 1 at 100% reactor power.

Apparent Cause of Occurrence:

The most probable cause has been determined to be an incorrect procedure due to either incorrectly recorded pre-operational test data or incorrect data obtained during pre-operational testing.

Analysis of Occurrence:

Valve 2-FCV-67-537B, containment spray heat exchanger outlet flow balancing valve, was found positioned 27 turns from full open. The applicable Operations Section Instruction Letter requires the valve to be set 32 turns from full open.

Corrective Action:

2-FCV-67-537B was adjusted to 21 turns from full open and a new flow rate of 5400 gpm was obtained. The applicable procedure will be revised with any other required changes upon the completion of SI-566.

Failure Data:

None.