0 1	A L J M F 1 7 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 56
0	SOURCE L 6 0 5 0 0 0 3 4 8 7 0 5 1 0 8 2 3 10 5 2 4 8 2 0 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 .
0 2	At 0705 on 5/10/82, while conducting a shift turnover and main control board walkdown,
013	it was determined that both containment spray suction valves from the RWST were closed.
0 4	Tech. Spec. 3.6.2.1, in part, requires these valves to be open. Tech. Spec. 3.6.2.1
0 5	action statement requirements were met. Health/safety of the public was not affected.
0 6	
0 7	
0 8	
2 8	SYSTEM CAUSE CAUSE COMPONENT CODE COMP VALVE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
0 9	SA (1) A (1) VALVEX (4) D (5) LD (16)
	SEQUENTIAL OCCUPRENCE REPORT REVISION SEQUENTIAL OCCUPRENCE REPORT NO. (17) REPORT
	ACTION FUTURE EFFECT SHUTDOWN 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT
0	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER H 18 Z 9 Z 20 Z 21 O O O O Y 23 N 24 A 25 G 2 5 5
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	Immediately upon discovery, the valves were opened and position verification of the
	accessible containment spray system valves was conducted with no discrepancies noted.
1 2	An extensive investigation revealed that during the performance of FNP-1-STP-20.0
1 3	(Penetration Room Exhaust and Air Filtration System Train (A)B Operability and Valve
1 4	Inservice Test), the plant operator mistakenly closed the containment spray suction
1 5	FACILITY STATUS TO DISCOVERY DESCRIPTION (32) [E [28] [1 0 0 0 29] NA [A (31)] Operator Observation
7 8	9 10 12 13 44 45 46 83 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6	Z (33) Z (34) NA NA NA NA NA NA
EVE	NUMBER TYPE DESCRIPTION (39)
7 8	PERSONNEC INJURIES 13
1 8	NUMBER DESCRIPTION (41) NA
	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 8206010 6 Z;0
7	9 ID PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
2 0	NA 68 69 80
	NAME OF PREPARER W. G. Hairston, III PHONE (205) 899-5156
	BOOK BOOK BOOK BOOK BOOK BOOK BOOK BOOK

May 24, 1982

LER 82-021/01T-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

valves instead of turning off the penetration room filtration recirculation and exhaust fans. When the valves were closed, a main control board annunciator sounded. This annuniciator was not properly acknowledged by the plant operators which resulted in the cause of the annunciator not being investigated properly. If the annunciator had been properly investigated using the Annunicator Response Procedure, the mispositioned valves would have been discovered at this time. The valves were closed for a period of six hours and fifty-five minutes.

It has been emphasized to the operators that they should ensure that the action they initiate gives the desired result. Operations personnel were also instructed in the proper acknowledgement of Main Control Board Annunciators and the need for investigation into their cause was emphasized.