NRC FOR (7-77)	U. S. NUCLEAR REGULATORY COMMISSION
	CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) G A E I H 2 2 0 0 - 0 0 0 0 0 - 0 0 0 0 0 - 0 0 0 0
CON'T 0 1 7 8	REPORT LL 6 0 5 0 0 5 6 6 0 0 5 8 2 8 0 2 5 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During a load reduction, while performing main steam isolation valve trip
03	Itest per HNP-2-3111, outboard MSIVs 2B21-F028B and D closed faster than J
0 4	allowed by Technical Specifications. This type event was last reported
05	on reportable occurrence No. 50-366/1981-101. No significant occurrence
06	took place as a result of this event. Unit 1 was not affected by this
07	event. No redundant systems were available. This event posed no threat
08	to public health or safety.
7 8 0 9 7 8	SYSTEM CAUSE CAUSE CAUSE COMPONENT CODE COMPONENT CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE COMPONENT CODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE COMPONENT CODE SUBCODE SU
	(17) REPORT NUMBER 8 2 23 0 1 5 27 0 3 1 0 32 ACTION FUTURE TAKEN ACTION ON PLANT EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER E 18 Z 35 20 Z 21 0 0 0 0 40 41 23 N 24 26 27 ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER ATTACHMENT 34 18 Z 10 0 0 0 141 23 N 24 10 25 R 3 4 4 26 ATTACHMENT 34 34 37 37 40 41 23 43 43 44 47 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 37 40 41 47 44 47
10	The cause of this event was setpoint drift on the needle valve which
1 1	controls MSIV closing speed. The needle valve on each MSIV was adjusted J
12	to bring closing time to within the Technical Specifications limit. No
13	further corrective action or reporting is required.
14	80
1 6	FACILITY STATUS 9 0 7 2 0 7 2 2 0 7 2 2 13 0 THER STATUS 30 NA 44 45 45 46 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32 44 45 46 46 46 46 46 46 46 46 46 46
1	LOCA ION OF RELEASE AMOUNT OF ACTIVITY 35 LOCA ION OF RELEASE 36 NA NA
17	PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 DESCRIPTION 39 NA 80
	PERSONNEL INJURIES NUMBER 9 11 12 NA
1 9 7 8	LOSS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION NA 8206010647 10 80
20	PUBLICITY ISSUED DESCRIPTION (45) NA 10 NRC USE ONLY NRC USE ONLY 10 10 10 10 10 10 10 10 10 10
	NAME OF PREPARER C. L. Coggin - Supt. Plt. Eng. Serv. PHONE 912-367-7851

LER #: 50-366/1982-015 Licensee: Georgia Power Company Facility Name: Edwin I. Hatch Docket #: 50-366

Narrative Report for LER 50-366/1982-015

During a load reduction to about 72% power, while performing the main steam isolation valve trip test per plant procedure HNP-2-3111, two outboard MSIVs closed faster than is allowed by Technical Specifications. MSIVs 2B21-F028B and D closed in 1.5 seconds and 2.7 seconds, respectively. Technical Specifications section 3.6.3 requires a closing time of 3 to 5 seconds. This is a repetitive event and was last reported on reportable occurrence report No. 50-366/1981-101. No significant occurrence took place as a result of this event. Unit 1 was not affected by this event. No redundant systems were available. This event posed no threat to public health or safety.

The cause of this event was setpoint drift on the needle valve which controls MSIV closing speed by restricting the flow of the hydraulic control fluid. The needle valve on each MSIV was adjusted to bring closing time to within the Technical Specifications limit. No further corrective action or reporting is required.