

## LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	E	C	P	R	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4	5																
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34																
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										CAT 58									

CONT

0	1	L	6	0	5	0	0	0	2	9	8	7	0	4	2	8	2	8	0	5	2	8	8	2	9																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34																
REPORT SOURCE														DOCKET NUMBER										EVENT DATE										REPORT DATE									

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, suppression chamber level instrument PC-LI-13 failed full  
03 scale. Tech. Spec. Table 3.2.F requires all level instruments operable. All other lev-  
04 el indicators were indicating properly. There were no significant occurrences as a  
05 result of this event and there were no adverse effects to public health and safety.  
06 This event is not repetitive.

07  
08

0	9	I	F	11	A	12	B	13	I	N	S	T	R	U	14	T	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE			
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.											
8 2		0 0 9		0 3		L		0											
21 22		23 24		25 26		27 28		29 30											
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS											
H 18		Z 19		Z 20		Z 21		0 0 0 0											
33 34		35 36		37 38		39 40		41 42											
ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER													
N 23		24		N 25		H 2 6 0													
43 44		45 46		47 48		49 50													

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The level indicator failed because of personnel error. The reference water leg was  
11 drained while attempting to collect a torus water sample. PC-LT-13 is a Honeywell Mod-  
12 el 29213-01-1 level transmitter. The level transmitter was replaced due to sticking  
13 at full scale. Proper sampling valve was tagged. Error was reviewed with technicians  
14 concerned.

1	5	E	28	0	8	8	29	NA	30	A	31	Operator Observation	32																																								
7	8	9	10	11	12	13	14	15	16	17	18	19	20																																								
FACILITY STATUS														% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
ACTIVITY CONTENT														RELEASED OR RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																			
Z 33														Z 34										NA										NA																			
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																					

1	7	0	0	0	37	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES									
NUMBER TYPE DESCRIPTION									
0 0 0 37 Z NA									
7 8 9 10 11 12 13 14 15 16									

1	8	0	0	0	40	L	41	NA	42
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES									
NUMBER DESCRIPTION									
0 0 0 40 L NA									
7 8 9 10 11 12 13 14 15 16									

1	9	Z	47	NA	48
7	8	9	10	11	12
LOSS OF OR DAMAGE TO FACILITY					
TYPE DESCRIPTION					
Z 47 NA					
7 8 9 10 11 12 13 14 15 16					

2	0	N	44	8206070136	820528	PDR	ADOCK	05000298	PDR
7	8	9	10	11	12	13	14	15	16
PUBLICATION									
NUMBER DESCRIPTION									
N 44									
7 8 9 10 11 12 13 14 15 16									

NAME OF PREPARER L. I. Lawrence

PHONE 402-825-3811

GB 69