TABLE OF CONTENTS

Emergency Telephone Numbers - (03/01/82, Rev. 6) AF/0/A/1000/01 Event index - (03/09/82) AP/0/A/1000/02 Unusual Event - (03/09/82) AP/0/A/1000/03 Alert - (03/09/82) AP/0/A/1000/04 Site Area Emergency - (03/09/82) AP/0/A/1000/05 General Emergency - (03/09/82) AP/0/A/1000/06 Procedure for Initiating Protective Action Guides for the General Public in the Emergency Planning Zone - (03/09/82) AP/0/A/100C/07 Procedure for Offsite Dose Calculations by Control Room Personnel or Emergency Coordinator during a Loss of Coolant Accident - (02/26/82) AP/0/A/1000/08 Procedure for Response Actions for Accidents/ Emergencies - (10/15/81) AP/0/A/1000/10 Procedure for Emergency Evacuation of Station Personuel - (02/02/82) Station Directive 2.9.1 Station Assembly and Evacuation Procedure -(04/14/82)Station Directive 2.9.2 Emergency Response Organization and Training -(08/20/81, Qriginal Issue) Station Directive 5.1.3 Personal Injury Procedure - (10/19/81) Procedure for Establishment and Inspection PT/0/B/2000/04 of the Technical Support Center - (04/25/82) CP/1/A/2002/04A Post Accident Liquid Sampling of the Reactor Coolant System (12/01/81) CP/2/A/2002/04A Post Accident Liquid Sampling of the Reactor Coolant System (12/01/81) CP/3/A/2002/04A Post Accident Liquid Sampling of the Reactor Coolant System (12/01/81) CP/1/A/2002/04B Post Accident Liquid Sampling of the Low Pressure Injection System (12,'01/81)

EPM001/A

Revision, May 7, 1982

8206070214 820527 PDR ADDCK 05000269 F PDR Table of Conterts (Implementing Procedures - Continued)

CP/2/A/2002/04B	Post Accident Liquid Sampling of the Low Pressure Injection System (12/01/81)
CP/3/A/2002/04B	Post Accident Liquid Sampling of the Low Pressure Injection System (12/01/81)
CP/0/A/2004/2C	Post Accident Determination of Chioride by Specific Ion Electrode Using Beckman 4500 Meter (04/26/82, Original Issue)
CP/0/A/2004/2E	Post Accident Determination of Boron Concentration Using Carminic Acid (04/26/82, Original Issue)
CP/0/A/2005/2D	Post Accident Determination of Gamma Isotopic Activity (04-26-82, Original Issue)
CP/0/B/4003/01	Procedure for Environmental Surveillance Following a Large Unplanned Release of Gaseous Radioactivity - (01/13/82)
CP/0/B/4003/02	The Determination of Plume Direction and Sector(s) to be Monitored Following a Large Unplanned Release of Gaseous Activity - (08/20/81)
HP/O/B/1009/09	Procedure for Determining the Inplant Airborne Radioiodine Concentration During Accident Conditions - (07/09/81)
HP/O/B/1009/10	Procedure for Quantifying Gaseous Releases Through Steam Relief Valves Under Post- Accident Conditions - (07/03/81)
HP/O/B/1009/11	Projection of Offsite Dose from the Uncon- trolled Release of Radioactive Materials Through a Unit Vent - (07/08/81)
HP/0/B/1009/12	Distribution of Potassium Iodide Tablets in the Event of a Radioiodine Release - (03/02/82)
HP/O/B/1009/13	Procedure for Implementation and Verification for the Availability of a Back-Up Source of Meteorological Data - (04/23/82)
HP/0/B/1009/14	Project Offsite Dose from Releases other than Through a Vent - (01/29/82)
HP/0/B/1009/15	Procedure for Sampling and Quantifying High Level Gaseous Radioicdine and Particulate Radioactivity - (04/29/82)

Table of Contents (Implementing Procedures - Continued)

HP/0/B/1009/16

Procedure for Emergency Decontamination of Personnel and Vehicles on-site and from Off-site Remote Assembly Area - (03/02/82)

IP/0/B/1601/03

Environmental Equipment Checks - (04/08/82)

ONS STATION DIRECTIVE 2.9.1 (LP) (TS) Thread and APPROVAL DATE 8/20/81 4 REVISED DATE

5

DUKE POWER COMPANY

OCONEE NUCLEAR STATION

STATION ASSEMBLY AND EVACUATION PROCEDURE

	Pa	ge
I.	PURPOSE	2
II.	REFERENCES	2
III.	DESCRIPTION	2
IV.	PROCEDURES	2
	A. Procedure for Station Assembly	2
	B. Procedure for Station Evacuation	5
v.	ENCLOSURES	
	A-1 Site Assembly Locations	3
	A-2 Station Personnel Accountability	3
	B-1 Emergency Evacuation Route)

I. PURPOSE

1. 1. 2

This directive provides procedures to be used when responding to station assembly and preparatory to evacuation from the station if a radiological emergency is declared.

II. REFERENCES

- A. Oconee Nuclear Station Emergency Plan
- B. NUREG-0654, FEMA. Rep-1, Rev. 1, Criteria for Preparation and Evaluation of Radiological Emergency Response Plans and Preparedness in Support of Nuclear Power Plants
- C. Technical Specifications 6.4.2

III. DESCRIPTION

It is the intent of this directive to identify preplanned responses necessary to quickly and professionally respond to a station assembly and for evacuation from the station if a radiological emergency is declared. By being prepared, the effects of an evacuation from the station can be minimized and can facilitate faster action by station management and personnel.

IV. PROCEDURE

- A. Procedure for Conducting a Station Assembly
 - 1.1 A Station Assembly encompasses the assembly of all onsite personnel at designated assembly points for the purpose of accounting for personnel within station boundaries. Reasons for initiating a Station Accembly would include:
 - A) A test of response time and procedures employed in completing an accounting of onsite personnel.
 - B) A station incident occurs and:
 - Fortions of the Protected area may require evacuation or
 - 2) A station evacuation may be required, or
 - Portions of the Emergency Planning Zone may require evacuation.
 - 1.2 A station assembly is initiated by activating the Personnel Assembly Signal in the Units 1 & 2 Control Room. This signal is a warble signal which is heard over the Public Address (PA) System. The Shift Supervisor is responsible for initiating a Station Assembly and will assure that the following announcement is made throughout the station twice each time it is made.

This is a station assembly. This is a station assembly. All visitors <u>outside</u> security are to report to the Receptionist Lobby. All visitors <u>inside</u> security are to report to the Security Lobby. All other badged personnel shall report to your supervisor in the area designated on the back of your security badge.

If any particular area of the plant is found to be radiologically unsafe during an emergency, and a site assembly is held, warnings should be sounded through the public address system the "safe" corridors to use.

The alarm and announcements shall be continued for a duration long enough to ensure all onsite personnel are aware of the Station Assembly and are responding.

- Action Plan for onsite personnel in responding to a Station Assembly Alarm.
 - 1.3.1 Each person (except those noted in 1.3.4 below) shall assemble with their supervisor. Assembly points for personnel onsite at Oconee Nuclear Station are identified in Table A-1. Additionally, these locations are on the back of the security badge for those personnel inside security.
 - 1.3.2 During normal working hours on Monday through Friday (except holidays) each supervisor shall be responsible for accounting for all personnel reporting to him. Station Superintendents and the Senior Supervisors of various organizations working at Oconee (e.g., SSD, QA) shall make an accountability report to the Station Manager for their areas of responsibility. Security will make an accountability report for in-plant visitors. When reports from all areas are received, the Station Manager will notify the Shift Supervisor that all persons have been accounted for.

Table A-2 is available to aid in accounting for onsite personnel. Each reporting supervisor is to report location, his name, telephone number, number of people assembled, and any missing persons.

1.3.3 During the hours not covered by 1.3.2 above, an accountability report should be made by the designated responsible person in each functional work group present at the Station to the Shift Supervisor. The Senior Guard Force representative will report visitors.

- 1.3.4 Persons working in Radiation Control Areas in protective clothing should leave their work areas and go to the appropriate change room. In the change room, they should contact the appropriate persons as designated by 1.3.2 or 1.3.3 above for personnel accountability reporting. Judgment should be used concerning the advisability of changing clothes and reporting to normal assembly areas.
 - NOTE: In case of a Reactor Building evacuation alarm, the reporting requirements in 1.3.4 above apply.

1.4 Action plan for Station Security

- 1.4.1 When alerted of a Station Assembly requirement, the Security Shift Lieutenant will be responsible for initiating a patrol of the general station areas within station boundaries, both inside and outside of the restricted area, to assure that personnel in remote and noise restrictive areas are aware of the Station Assembly requirement.
- 1.4.2 Security will restrict traffic in and out of the station during Site Assembly. Should Site Assembly be initiated during high traffic ingress and egress, normal traffic flow will not be restricted.
- 1.5 Action plan for Shift Health Physics Representative
 - 1.5.1 Account for Health Physics personnel as directed in 1.3 above.
 - 1.5.2 Provide assistance to personnel exiting contaminated areas or the Protected Area, as necessary, with proper frisking and contamination control.
 - 1.5.3 If Health Physics supervisory personnel are not onsite, direct available Health Physics personnel in controlling or monitoring the radiological situation as required.
- 1.6 Action Plan for Shift Supervisor/Station Manager (Emergency Coordinator)
 - 1.6.1 Receive Accountability reports from onsite supervisors using Table A-2 as an aid.
 - 1.6.2 Direct necessary actions to account for any missing personnel. Emergency Coordinator will dispatch

Search and Rescue Team(s) that may be composed of personnel from Security, Safety and/or Operations, and Health Physics.

- 1.6.2.1 Health Physics will be responsible for monitoring and will be in charge.
- 1.6.2.2 Security will provide radio support and will be in a position to open controlled access doors.
- 1.6.2.3 Safety and/or Operations will provide medical support.
- 1.7 When personnel accountability has been completed following a Station Assembly, one of the following will occur.
 - 1.7.1 If the requirement for an assembly no longer exists, permission to return to normal duties will be given by the Shift Supervisor/Station Manger or:
 - 1.7.2 Plant conditions may require evacuation of the station and implementation of an emergency organization or;
 - 1.7.3 Other instructions will be given by the Emergency Coordinator.
- B. Procedure for Conducting a Station Evacuation
 - 1.0 A station evacuation shall be conducted when any unplanned radiological condition may result in whole body doses or internal exposures in excess of 10CFR20 limitations for areas outside the Radiation Control Area. Unplanned radiological releases contained within various portions of the Radiation Control Area may require evacuation of local areas only.
 - 1.1 Station Evacuation levels are as listed below.
 - A. All members of the general public, and other persons who are not subject to occupational radiation exposure at Oconee Nuclear Station must be evacuated if they are likely to be exposed to doses in excess of:
 - 1) External Radiation Level > 2 mrems in any one hour
 - Airborne Radioactivity > 1 x mpc for an unrestricted area (10CFR20, Appendix B, Table II)
 - B. Personnel subject to occupational radiation exposure at Oconee Nuclear Station must be evacuated if they are likely to be exposed to unplanned doses in excess of:
 - External Radiation Level > 2.5 mrem/hr, 100 mrems/week, or 1250 mrems in a guarter

- Airborne Radioactivity > equivalent amount inhaled for 40 hours/week for 13 weeks at 1 mpc (10CFR20 Section 20.103 and Appendix B, Table 1)
- 2.0 When it is determined that a station evacuation is necessary, the station evacuation alarm will be sounded. This alarm is a continuous, single-tone siren that can be heard throughout the station. Evacuation will be by designated preplanned routes which avoid contaminated locations or other locations that may be affected by the emergency situation. Evacuation routes, assembly locations, and other pertinent information shall be passed over the FA system or by telephone.
- 3.0 When directed, evacuees will evacuate using personal cars to the greatest extent possible. Remote assembly locations, and entrance/exit routes will be provided with evacuation instructions. (Enclosure B-1)

Should personal cars be unavailable due to contamination, bus transportation will be made available. The Shift Supervisor/ Station Manager (Emergency Coordinator) is responsible for arranging bus transportation as required.

Health Physics will survey evacuees and vehicles for contamination at designated locations as directed by the Shift Supervisor or Technical Support Center. Decontaminants and extra clothing will be provided for by Health Physics at designated survey locations. Fire hydrants may be used for decontamination of vehicles leaving the site.

- 4.0 Station evacuations are activated only after station personnel have been assembled through a Station Assembly.
 - A. Various groups of personnel at the station are considered nonessential to the safe operation of the station and would be evacuated when directed. Groups of personnel in this category include:

Substation Maintenance SMS SSD QA Visitors B&W Design Engineering Keowee Visitors Center Wometco Chem-Nuclear Vendors (other than HP) General Office personnel Duke personnel (other than ONS) All others (not listed in B&C below)

B. The following groups of personnel are considered essential to the safe operation of the station. When a requirement exists to evacuate the station, these essential personnel

. 10.0

will be provided instructions as to where to report to assist in the safe operation of the station. Groups of personnel in this category include:

Operations Health Physics Health Physics Vendors Biologists Licensing and Projects NRC Southern Security Resident B&W Representative

C. The following groups of personnel may selectively be identified as essential to the safe operation of the station. When a requirement exist to evacuate the station, station management will identify which of the following personnel will be required to aid in the operation of the station. The remaining personnel will be instructed to evacuate. Groups of personnel in this category include:

> Administration Maintenance Chemistry Performance K-Mac

5.0 After the initial evacuation of the station has been completed, adjustments to station staffing requirements will be made as the situation warrants by the Station Manager or his designee. Control of station activities will be through the Technical Support Center. TABLE A-1 SITE ASSEMBLY LOCATIONS

DUKE OCONEE NUCLEAR STATION PERSONNEL

Respective Offices

Section

Assembly Point

Station Manager/Superintendents: and Assigned Clerks

Administrative Services:

Administrative Services Training Safety Medical Contract Services

Maintenance:

I&E Engineers I&E Supervisors & Technicians Mechanical Maintenance Engineers Mechanical Maintenance Supervisors & Technicians Planners Materials



Operations: All

Technical Services:

Licensing & Projects Performance (All) Health Physics (All) Chemistry (All) Environmental

Quality Assurance: All

Training Services: All Personnel at Training Center Administration Clerical Office Training Office Training Office Training Office Contract Service's Offices

I&E Engineers Offices I&E Shops Mechanical Maintenance Engineers Office

Maintenance Shop Planning Office Materials Office

Control Rooms/Unit 1 & 2 Operating Engineer Office

Licensing & Projects Office Performance Engineers Office Health Physicist Office Station Chemist Office Environmental Office

Quality Assurance Office

Oconee Training Center

DUKE NON-OCONEE NUCLEAR STATION PERSONNEL

Administration Visitors: All

Operations Visitors: All

SMS: Those Inside Security Those Outside Security

Station Support Division:

Keowee: All

Visitors' Center: All

Administration Clerical Office

Units 1 & 2 Operating Engineers Office

Sheet Metal Shop SMS Office

SSD Office

Keowee Hydro Station

Visitors' Center Office

TABLE A-1 SITE ASSEMBLY LOCATIONS

DUKE NON-OCONEE NUCLEAR STATION PERSONNEL (Continued)

SectionAssembly PointSubstation Maintenance:Substation Maintenance OfficeQuality Assurance:AllChemistry:AllChemistry:AllHealth Physics:AllHealth Physics:AllDesign Engineering:AllMaintenance Visitors:Service Building Mezzanine (I&E,
Meintenance Disconting Physics:

Mechanical Maintenance, or Planning Office)

NON-DUKE OCONEE NUCLEAR STATION PERSONNEL

Southern Security:

K-Mac: Those Inside Security Those Outside Security

Chem-Nuclear:

B&W Resident Engineer:

NRC: All

.......

Wometco: All

Main Guard House

Canteen South End, Turbine Building K-Mac Office

Station Chemist Office

Control Room

Licensing & Projects Office

Administration Building Canteen

NON-DUKE, NON-OCONEE NUCLEAR STATION PERSONNEL

Health Physics Vendors:

Rad-Services NUMANCO Health Physicist Office Health Physicist Office

Babcock & Wilcox Personnel:

B&W Offices, Trailer

Visitors:

Inside Security with Permanent BadgeReceptionist LobbyInside Security with EscortSecurity Lobby, Administration BuildingOutside SecurityReceptionist Lobby

OTHER PERSONNEL OUTSIDE PROTECTED AREA

All personnel not identified above will report to the Receptionist Lobby between 0800 - 1630, Monday through Friday. On weekends, holidays, and after hours, report to Security Lobby.

•	. BEL SETING		TABI STATION PERS	SONNEL ACCOUNTABILITY	DATE		
- CROUP	NAME	NUMBER TELEPHONE	Number FEOFLE	CROUP	REPORTING NAME NUMBER TELEPHONE	MABER	
Administration Contract Services: K-Hac Southern Security Training & Safety: Administrative Secvices: Wometco Visitors' Center: Keowee Hydro: Station Visitors: Receptionist Lobby				Technical Services Performance: Environmental: Licensing & Projects: Design Engineering NRC Mealth Physics: Chemistry: Others:			
Operations Operations Operators On-Shift: Engineers/Staff: Training Center:	TOTAL ADMIN'STRATION CROUP			TDHE: TOTA Quality Assurance TIME: Station Support Division TIME: Others:	L TECHNICAL SERVICES GROUP Quality Assurance Total Station Support Division Total		
BSW Personnel: Others: TIME: Maintenance Planning & Materials: I&E: Machanical Maintenance: System Maintenance Support:	TOTAL OPERATIONS CROUP			BEGINNING ENDING TIME: TIME: Unaccounted Personnel Grou REMARKS:	Others Total: <u>TOTAL PEOPLE ON-SITE</u> : <u>P Action Taken Person Reporting</u>	Telephon	

Others:

Substation Maintenance:

TIME: _____ TOTAL MAINTENANCE GROUP

MAJOR REVISION

2

-9-

To Pickens To Salem 183 18 183 (188 0 160 Keowee School To Seneca 130 EMERGENCY EVACUATION ROUTES FROM STATION ASSEMBLY AREAS: To be determined by Emergency Coordinator 1. Keowee School 133 2. Daniel High School

ENCLOSURE B-1

STATION DIRECTIVE 2.9.1

-10-

11

1

Daniel High School 133

INFORMATION ONLY

Form SPD-1002-1

	DUKE POWER COMPANY PROCEDURE PREPARATION PROCESS RECORD	(1) ID No:PT/O/B, Change(s) 0 Incorport	/2000/04 0_to rated
(2)	STATION: Oconee		
(3)	PROCEDURE TITLE: Procedure for Establis Technical Support Center	shment and Inspection of the	2
(4)	PREPARED BY: Loglemon la Inning	DATE: + 21/82	
(5)	REVIEWED BY: Gran Gran Cross-Disciplinary Review By:	DATE: 4/21/82 N/R: M	
(6)	TEMPORARY APPROVAL (IF NECESSARY):		
	By: (SRO)	Date:	
	By:	Date:	
(7)	APPROVED BY: 1 dry B. Chu-	Date: 4 25 82	
(8)	MISCELLANEOUS:	•	
	Reviewed/Approved By: R.V. B.P.	Date: 4/23/82	

Reviewed/Approved By:_____ Date:_____

PT/0/B/2000/04 Page 1 of 3

DUKE POWER COMPANY OCONEE NUCLEAR STATION PROCEDURE FOR ESTABLISHMENT AND INSPECTION OF THE TECHNICAL SUPPORT CENTER

1.0 Purpose

PThis procedure provides for the establishment of the Technical Support Center and for quarterly inspection of emergency equipment and supplies necessary to activate the Technical Support Center and specifies the inspection frequency and documentation requirements.

2.0 References

2.1 Oconee Nuclear Station Emergency Plan

2.2 NUREG 0654, FEMA-REP-1, REV., Criteria for Preparation and Evaluation of Radiological Emergency Plans and Preparedness in Support of Nuclear Power Plants.

3.0 Time Required

3.1 Varied/quarterly test.

4.0 Prerequisite Test

4.1 Not applicable

5.0 Test Equipment

5.1 Not applicable

5.0 Limits and Precautions

6.1 Maintain record of all documentation for a minimum of five years.

6.2 Ascertain availability of the phone line to be checked.

7.0 Required Station Status

7.1 Not applicable

8.0 Prerequisite System Conditions

8.1 Not applicable



9.0 Test Method

9.1 All emergency supplies, equipment, and telephone numbers that would be used upon activation of the Technical Support Center are to be inspected and/or reviewed on a quarterly basis.

10.0 Data Required

10.1 Not applicable

11.0 Acceptance Criteria

11.1 Periodic quarterly inspection of supplies and emergency equipment and quarterly review of telephone directories must comply with the regulations as specified in the Oconee Nuclear Station Emergency Plan and as required by NUREG 0654.

12.0 Procedure

Time/Date

Name

- 12.1 The Emergency Preparedness Coordinator or his/her designee shall use enclosures listed in 13.0 as a guide to inspect the following emergency equipment and supplies:
 - ____12.1.1 Verify all items for the Technical Support Center Telephone Communication System on Enclosure 13.2 are available and operational.
 - 12.1.2 Verify that the Emergency Telephone Directories are current.
 - ____12.1.3 Verify that all supplies as designated in Enclosure 13.1 are on hand for the activation of the Technical Support Center.
 - ____12.1.4 Verify that all drawings located in the Technical Support Center are up to date. Use 13.7 as a guide.
- _12.2 The Emergency Preparedness Coordinator or his/her designee shall use enclosures listed in 13.0 as a guide for setting up the Technical Support Center during an emergency, drill, and/or exercise:
 - 12.2.1 Each Superintendent shall be responsible for having his emergency telephone system switched to the Technical Support Center and/or Operational Support Center.
 - 12.2.1.1 The phones for the Technical Support Center/ Operational Support Center shall be set up according to the Check-Off List in Enclosure 13.2.

12.2.2

Follow Check-Off List for setting up the Technical Support Center, Enclosure 13.6, to determine that equipment, supplies, documents, manuals, procedures are in place. Time/Date Name

> _12.2.3 All supplies shall be inspected after the emergency, drill and/or exercise and replenished as necessary.

13.0 Enclosures

13.1 Inventory List Checkoff

13.2 Check-off List for Setting up the Phone System in the Technical Support Center

13.3 General Arrangement of Technical Support Center

13.4 General Arrangement of Operational Support Center

13.5 Emergency Telephone Switching Diagram

13.6 Check off List for Setting up the Technical Support Center

13.7 Drawings in the Technical Support Center

TECHNICAL SUPPORT CENTER INVENTORY LIST ENCLOSURE 13.1

	Name	
13.1.1		24 Telephones
13.1.2		Drawings (Enclosure 13.6)
13.1.3		2 Base Station Radios (a) Battery - Check dates and/or replace
13.1.4		Telephone Directories
		25 Station Directories5 Corporate Directories25 Emergency Telephone Directories1 NRC Directories2 Local Municipal Directories
13.1.5		4 Reams Copy Machine Paper
13.1.6		1 Box Telecopier Paper
13.1.7		20 Pads (writing)
13.1.8		1 Bottle Nashua X-D 3159A Developer
13.1.9		2 Boxes Pencils
13.1.10	<u></u>	4 Bottles Nashua 3100 Dry Imager
13.1.11		2 Boxes Ball Point Pens
13.1.12		1 7½ volt hand-held light
13.1.13		' Staplers
13.1.14		2 Boxes Staples
13.1.15		1 Box Chalk
13.1.16		1 Eraser
13.1.17		4 Grease Pencils
13.1.18		2 Logbooks
13.1.19		1 Package Rubber Bands
13.1.20		1 Box Colored Magic Markers
13.1.21		50 Bottles KI Tablets
13.1.22		1 Box 12" Printer Paper
13.1.23		1 Box Diskettes

NOTE: Emergency supplies (minimum quantities inventoried) will be restocked after any emergency or after any drill or exercise where the Technical Support Center was activated.



OCONEE NUCLEAR STATION PT/0/B/2000/04 <u>ENCLOSURE 13.2</u> CHECK-OFF LIST FOR SETTING UP THE PHONE SYSTEM IN THE TECHNICAL SUPPORT CENTER AND OPERATIONAL SUPPORT CENTER

Date/Time Name

13.2.1

Contact the following members of the Emergency Response Organization. Make them aware that the phone line will be switched to the Technical Support Center/Operational Support Center and that the line will be out of service for approximately 2 hours. After everyone has been notified, switch phone lines in accordance with directions given on Enclosure 13.5.

-	1669	VAX	1670	VAX
	1105	S&C	1108	NRC Res. Insp.
	1138	Data Evaluator	1140	B&W
	1417	Environmental	1244	Communicator
-	1177	H.P. Supvr.	1212	Administration
	1409	Performance	1227	Maintenance
1	1229	L&P '	1219	I&E
	1220	Chemistry	1216	P&M ·
_	1210	Operations	1223	M.M.
_	1213	Tech. Serv.	1211	Station Manager
	1234	Station H.P.	882-7076	Station Manager
_	NRC Red	Phone	HPN Black	: Phone
_	Duke Rin	gdown	1151 Medi	cal

____13.2.2

Secure key from Shift Supervisor to Technical Support Center Cabinet. Check each phone to make sure that a dial tone exists and that the line is operable -- incoming and outgoing.

13.2.3 Note : y problems encountered and list below.

13.2.4 Lock telephone boxes.

13.2.5 Return telephone systems to normal service.

PT/0/B/2000/04

DUKE POWER COMPANY EMERGENCY RESPONSE FACILITIES OCONEE NUCLEAR STATION

Enclosure 13.3

TECHNICAL SUPPORT CENTER

Communication System Includes: Outside Line (Southern Bell System) ONS Switchboard Microwave Radio Computer (OAC, VAX, TSO) Telecopier UNIT 1&2 CONTROL ROOM ENS (Red Phone) HPN (Health Physics - NRC) Ringdown phone to Offsite Agencies (State FEOC, Oconee EOC, Pickens EOC)





F

1388

DUKE POWER COMPANY EMERGENCY RESPONSE FACILITIES OCONEE NUCLEAR STATION

Enclosure 13.4

OPERATIONAL SUPPORT CENTER*

Location: Unit #3 I & E Shop

COMMUNICATION:

ſ .,

ONS Switchboard Microwave



*The areas designated as the Operational Support Center has the same ventilation and shielding as the Control Room. Provisions for protective clothing and breathing apparatus have been established.

PT/0/B/2000/04

×

EMERGENCY TELEPHONE SWITCHING DIAGRAM ENCLOSURE 13.5



1. Red - Indicate switches thrown at onset of TSC activation 2. Blue - Indicate switches thrown as needed in TSC

'To Switch All Phones Marked Red Or Blue To: . a. Unit 1 & 2 TSC throw switch to the right -> . b., Unit 3 _____ throw switch to left +.

.

OCONEE NUCLEAR STATION

Check-off list for setting up the Technical Support Center

ENCLOSURE 13.6

Date/Time Name	
13.6.1	Set up phones - (Determine that phones have been switched in the telephone roon)
13.6.2	Set up radio.
13.6.3	Check off list of Documents needed.
	Emergency Plan & Implementing Procedures
	Crisis Management Plan
	Pickens & Oconee Emergency Plan
	Technical Specifications
	FSAR
	General Arrangement Drawings
	Emergency Planning Zone maps and nomographs
	Safety related structures, systems and components
	Station Directives
	Administrative Policy Manual
	Various I&E Drawings
	Site Drawings
	Emergency Procedures
	Plant Operations Drawings
	Fire Plan
13.6.4	Paper & pads, pencils & pens, notebooks.
13.6.5	Set up TSC Logbook - record names of people in Technical Support Center
13.6.6	Determine if everyone has been called that is a part of the emergency response organization.
13.6.7	Notification Procedures
	Message forms
	Authentication Procedures

OCONEE NUCLEAR STATION

Check-off list for setting up the Technical Support Center

ENCLOSURE 13.6 (Cont'd)

Date/Time Name

Crisis Telephone Directory

____13.6.8

Contact Security - make sure Security is at the Control Room entrances.

Sign people in and out at that point.

13.6.9 Set up Data Displays for information update in TSC, HPC, OSC.

Assign someone to keep the information posted.

13.6.10 VAX system on line and operable.

Plant Data system

ODCAR system

13.6.11 Transmission of information

Telecopier

Copier

- _____13.6.12 Drawings listed on Enclosure 13.6 taken out of cabinet and placed in TSC.
- 13.6.13 Operational Support Center

Personnel in place

Supplies/first aid kits available

Survey instruments available

Dosimetry

Protective Cabinet



PT/0/B/2000/04 Page 1 of 2

DRAWINGS IN TECHNICAL SUPPORT CENTER

ENCLOSURE 13.7

DRAWING NU	MBER	TIT	LE
0-1		13.7.1	Site Plan
0-2		13.7.2	General Plan
0-3		13.7.3	Plot Plan
0-5		13.7.4	General Arrangement, Plan Elevation 758 + 0
0-6		13.7.5	General Arrangement, Plan Elevation 771 + 0
0-7		13.7.6	General Arrangement, Plan Elevation 783 + 9
0~8		13.7.7	General Arrangement, Plan Elevation 796 + 6
0-9		13.7.8	General Arrangement, Plan Elevation 809 + 3
0-10		13.7.9	General Arrangement, Plan Elevation 822 + 0
0-11		13.7.10	General Arrangement, Plan Elevation 838 + 0
0-12-A		13.7.11	General Arrangement, Cross Section
0-12-B		13.7.12	General Arrangement, Cross Section
0-12B-V		13.7.13	General Arrangement, Cross Section
0-12-C	<u></u>	13.7.14	General Arrangement, Longitudinal Section
0-13		13.7.15	General Arrangement, Turbine Basement
0-14		13.7.16	General Arrangement, Turbine Mezzanine
0-15	<u></u>	13.7.17	General Arrangement, Turbine Operating Floor
0-16	<u> </u>	13.7.18	General Arrangement, Auxiliary 758 + 0
0-17A		13.7.19	General Arrangement, Auxiliary 771 + 0
0-17B		13.7.20	General Arrangement, Auxiliary 771 + 0
0-18A		13.7.21	General Arrangement, Auxiliary 783 + 9
0-18B		13.7.22	General Arrangement, Auxiliary 783 + 9
0-18C		13.7.23	General Arrangement, Spent Fuel Pool
0-460		13.7.24	Unit 1 Reactor Building Basement 777 + 6
0-461		13.7.25	Unit 1 Reactor Building Ground Floor 797 + 6



* *

Date/Time

PT/0/B/2000/04 Enclosure 13.7 Page 2 of 2

Da	t	e	1	T	í	m	e
	N	a	m	e	7	-	-

.

No.

1. - E.

DRAWING NUMBER	TITLE	
0-462	13.7.26 Unit 1 Reactor	Building Intermediate Floor 825 + 0
0-463	13.7.27 Unit 1 Reactor	Building Operating Floor 844 + 6
0-464	13.7.28 Unit 1 Reactor	Building Shielding 861 + 6
0-465	13.7.29 Unit 1 Reactor	Building Sectional View North
0-466	13.7.30 Unit 1 Reactor	Building Sectional View East
0-467	13.7.31 Unit 1 Reactor	Building Sections
0-468	13.7.32 Unit 1 Reactor	Building Accessible Areas
0-1013	13.7.33 General Arrang	ement Turbine Building - Basement
0-1014	13.7.34 General Arrang	ement Turbine Building - Mezzanine
0-1015	13.7.35 General Arrange	ement Turbine Building - Operating Floo
0-1460	13.7.36 Unit 2 Reactor	Building Basement 777 + 6
0-1461	13.7.37 Unit 2 Reactor	Building Ground 797 + 6
0-1462	13.7.38 Unit 2 Reactor	Building Intermediate 825 + 0
0-1463	13.7.39 Unit 2 Reactor	Building Operating Floor 844 + 6
0-1464	13.7.40 Unit 2 Reactor	Building Top of Shielding 861 + 6
0-1465	13.7.41 Unit 2 Reactor	Building Sectional View South
0-1466	13.7.42 Unit 2 Reactor	Building Sectional View East
0-1467	13.7.43 Unit 2 Reactor	Building Section
0-1468	13.7.44 Unit 2 Reactor	Building Accessible Areas
0-2460	13.7.45 Unit 3 Reactor	Building Basement 777 + 6
0-2461	13.7.46 Unit 3 Reactor	Building Ground Floor 797 + 6
0-2462	13.7.47 Unit 3 Reactor	Building Intermediate Floor 825 + 0
0-2463	13.7.48 Unit 3 Reactor	Building Operating Floor 844 + 6
0-2464	13.7.49 Unit 3 Reactor	Building Top of Shielding 861 + 6
0-2465	13.7.50 Unit 3 Reactor	Building Sectional View South
0-2466	13.7.51 Unit 3 Reactor	Building Sectional View Fast
0-2467	13.7.52 Unit 3 Reactor	Building Section

Form SPD-1002-1

CONTROL COPY INFORMATION ONLY

DUKE POWER COMPANY PROCEDURE PREPARATION PROCESS RECORD (1) ID No: CP/0/A/2004/03C Change(s) NA to NA' Incorporated

(2)	STATION:	Oconee	Nuclear	Station	

(3) PROCEDURE TITLE: Post Accident Determination of Chloride by Specific

ton bicctrode osting beckman 4500 necer	
PREPARED BY: Bruce Fender	DATE: 423 82
REVIEWED BY:	DATE: 4/23/82
Cross-Disciplinary Review By:	N/R:
TEMPORARY APPROVAL (IF NECESSARY):	
By:(SRO)	Date:
By:	Date:
AFPROVED BY: 10mg B.C. win	Date: 4 26 82
MISCELLANEOUS:	
Reviewed/Approved By:	Date:
Reviewed/Approved By:	Date:



DUKE POWER COMPANY

OCONEE NUCLEAR STATION

POST ACCIDENT DETERMINATION OF CHLORIDE BY SPECIFIC

ION ELECTRODE USING BECKMAN 4500 METER

1.0 Discussion

1.1 Scope

This procedure describes the specific ion electrode method for the post accident determination of chloride ion concentration ([C1]) in the RCS when fuel damage is estimated to be greater than 1%.

1.2 Principle

The chloride ion-sensitive electrode is a solid-state ion sensor. The electrode uses a HgS/Hg_2Cl_2 sensing crystal at the tip of the electrode. A potential is developed by chloride ions across this crystal in much the same manner as a glass electrode responds to hydrogen ions. The potential varies with the chloride ion concentration. At 25°C it exhibits a 59 mV decrease in potential for each ten-fold increase in chloride ion concentration. A plot of mV vs. chloride concentration is prepared from standards of known chloride concentration. The chloride concentration of unknown samples can then be determined from this curve. A typical calibration curve is shown in Enclosure 6.4.

1.3 Limits

1.3.1 This method is applicable in the range of 0.05 ppm to 1.00 ppm Cl .

1.4 Interferences

- 1.4.1 Exposing the chloride electrode to a pH > 7 will produce an oxide film on the sensing crystal reducing the electrode sensitivity. Accurate measurements can be made from pH 1 to 7. Treating all samples, standards and soak solutions with ISA will reduce the pH to ~ 2 and prevent the oxide film formation.
- 1.4.2 Variations in total ionic strength will affect the chloride electrode response. Maintaining a constant total ionic strength over a wide concentration range by treating all samples and standards with ISA will enhance the electrode sensitivity and accuracy.

1.4.3 Ions which form very insoluble salts with mercury (such as S², I, Br, CNS) or chromates will poison the sensing crystal reducing the electrode sensitivity. However none are expected to be present at the concentrations necessary for the poisoning to occur.

- 2 -

1.5 Precautions

- 1.5.1 DO NOT ATTEMPT ANY PHASE OF ANALYIS WITHOUT HEALTH PHYSICS COVERAGE!
- 1.5.2 Radiation exposure to an individual during all phases of analysis should be limited so as not to exceed a quarterly accumulative exposure of 3 rems whole body; 7.5 rems skin of wholebody; or 18 3/4 rems extremities respectively All personnel will need prior authorization from 133 to knowingly exceed any exposure limit. The exposure received may require an occupational exposure penalty and/or a medical decision as to whether an individual can continue in radiation work.
 - 1.5.2.1 If necessary to remedy a situation immediately hazardous to life and property, the Planned Emergency Exposure for Duke Power Personnel will not exceed 5 rems wholebody; 30 rems skin of wholebody; or 75 rems extremities.
 - 1.5.2.2 If necessary to save lives or prevent loss of life and/or extensive damage to property (voluntary basis only), the Planned Emergency Exposure for Duke Power Personnel will not exceed 25 rems wholebody; 150 rems skin of wholebody; or 375 rems extremities.
 - 1.5.2.3 For Outside Services Personnel the Planned Emergency Exposure will not exceed 5 rems wholebody; 30 rems skin of wholebody; 75 rems extremities; or 15 rems other single organ.
- 1.5.3 Radiation levels of the lab area shall be measured continuously during all phases of analysis.
 - 1.5.3.1 Air activity should be determined by use of installed air monitors or through the use of portable air sampling equipment.
 - 1.5.3.2 Area dose rates should be established by the use of installed radiation monitors or by portable radiation survey instrument.
 - 1.5.3.3 Portable shielding, remote handling equipment, video equipment, etc., should be used where practical during sample preparation and sample analysis.

-



1.5.4 Samples and standards shall be stirred during measurement using a magnetic stirrer to reduce electrode response time.

- 3 -

- 1.5.5 Since electrode potentials are affected by changes in temperature, samples and standards should not differ more than ± 5°C.
 - NOTE: Temperature and slope controls are inoperative in the mV and mV abs mode.
- 1.5.6 Samples containing more than 1 ppm chloride should be diluted to less than 1 ppm using demin water.
- 1.5.7 Mercuric salts are poisonous! Gloves shall be worn when handling the chloride electrode.
- 1.5.8 Never store both electrodes together in the same solution.
- 1.5.9 The electrodes need not be immersed more than one (1) inch for accurate readings. However, they maybe immersed further to obtain more rapid temperature equilibrium.
- 1.5.10 Always keep the reference electrode filling solution levels higher than the level of solution being measured.
- 1.5.11 Never operate the reference electrode with the filling hole obstructed.
- 1.5.12 This procedure shall be done in a fume hood and/or other precautions shall be taken to avoid the release of gaseous activity.

2.0 Apparatus

- 2.1 Beckman 4500 Digital pH/mV Meter
- 2.2 Chloride Electrode (Graphic Controls PHI91100 or equivalent)
- 2.3 Double Junction Reference Electrode (Graphic Controls PHE54473 or equivalent)
- 2.4 Beckman 583540 Multiple Electrode Selector
- 2.5 Electrode Holder
- 2.6 Magnetic Stirrer and Teflon-Coated Stirring Bars
- 2.7 Stopwatch, Clock or Timers
- 2.8 150 ml Glass Beakers
- 2.9 Eppendorf Pipettes with appropriate tips: 50, 100, 250, 500, 1000 µ2

2.10 Graduated Cylinder, 100 ml

2.11 Thermometer

2.12 Polishing Kit (Graphic Controls PHA76518 or equivalent)

- 4 -

2.13 1 liter volumetric flask (as needed)

2.14 Erlenmeyer flask or as equivalent

2.15 Parafilm for covering beakers

2.16 Analytical balance

2.17 Shielded Sample Container

2.18 Sample Tongs

2.19 Carboy - ~ 1 gal.

3.0 Reagents

- 3.1 Ionic Strength Adjustment Solution (ISA Solution) slowly add about 63 mls (± 1 ml) of concentrated nitric acid to about 437 mls (± 1 ml) of demin water. Mix thoroughly. Stable for six (6) months.
- 3.2 Chloride stock standard solution (100 ppm C1⁻) use purchased (Orion 94-17-07 or equivalent) 100 ppm C1⁻ standard or prepare as follows: dry sodium chloride (NaC1) to constant weight at ~ 105^o. Dissolve 0.1649 g (± 0.0001) of the dry NaC1 in demin water and dilute to 1 liter in a volumetric flask and mix. Purchased standard is stable indefinitely. Prepared standard is stable for six (6) months.
- 3.3 Double Junction Reference Electrode Filling Solutions
 - 3.3.1 Upper filling solution use the upper filling solution supplied (Graphic Controls PHB1322 or equivalent) with the double junction reference electrode. Stable indefinitely.
 - 3.3.2 Lower filling solution use the lower filling solution supplied (Graphic Controls PHB1326 or equivalent) with the double junction reference electrode. Stable indefinitely.

4.0 Procedure

4.1 Initial Condition

- 4.1.1 Evaluate the use of portable shielding, remote handling equipment, video equipment, etc., to minimize the exposure to personnel, in the lab for the analysis.
- 4.1.2 Request HP to perform a constant radiation survey during the analysis.

- 4.1.3 Determine and use the required respiratory equipment and protective clothing to prevent or minimize internal exposure in any Planned Emergency situation. Use high range and/or extremity dosimetry if required by HP.
- 4.1.4 Prepare one (1) carboy (~ 1 gal.). Label as "Post Accident Lab Waste". This container must be shielded and used as interim liquid waste disposal container for all liquid analytical waste.
- 4.1.5 Prepare a shielded work area in a fume hood. This area must be used for handling the sample when it is removed from the shielded sample container.
- 4.1.6 Prepare a waste disposal container for all solid analytical waste. Label as "Post Accident Lab Waste".
- 4.1.7 Ensure both chambers of the reference electrode are filled.
- 4.1.8 Insure that the chloride electrode and the reference electrode is connected to back of multiple electrode selector (MES). Place Cl channel of the MES inservice.
- 4.1.9 Place the mV meter in STANDBY and in the mV mode of operation.
- 4.1.10 Prepare a sample dilution using the post-accident sample panel or by the manual method described in Enclosure 6.5. Ensure 100 ml of diluted sample for the analysis.
- 4.2 Concentration Measurements.
 - 4.2.1 Place the mV meter in STANDBY.
 - 4.2.2 If necessary, polish the chloride electrode as follows:
 - 4.2.2.1 Wet the cloth-covered acrylic polishing block with demin water and shake off excess water.
 - 4.2.2.2 Place a small amount of alumina powder on the polishing block to form a polishing paste.
 - 4.2.2.3 Using light pressure and circular motion polish the surface of the sensing crystal for \sim 30 seconds.
 - 4.2.2.4 Rinse the electrode thoroughly with demin water.
 - 4.2.2.5 Soak the electrode in 100 ml of demin water containing 1 ml of ISA solution for about 20 minutes to pre-condition the sensing crystal.
 - 4.2.3 Rinse the elctrodes with demin water.
 - 4.2.4 Immerse electrodes and thermometer into 99 ml of demin water containing 1 ml of ISA solution and a stirring bar.







- 4.2.5 Adjust stirring rate so that there is no vortex and release the mV meter from STANDBY.
- 4.2.6 Record the temperature of the calibration solution.

- 6 -

- 4.2.7 Add 50 μℓ of 100 ppm Cl standard (0.05 ppm). Wait 2 minutes, then adjust the MES controls so that the display reads + 500 mV.
- 4.2.8 Add an additional 100 µl of 100 ppm Cl standard (0.15 ppm). Wait 2 minutes and record the mV reading.
- 4.2.9 Add an additional 100 µl of 100 ppm Cl standard (0.25 ppm). Wait 2 minutes and record the mV reading.
- 4.2.10 Add an additional 250 µ2 of 100 ppm Cl stardard (0.50 ppm). Wait 2 minutes and record the mV reading.
- 4.2.11 Add an additional 500 µ2 of 100 ppm Cl standard (0.99 ppm). Wait 2 minutes and record the mV reading.
- 4.2.12 Place the mV meter in STANDBY.
- 4.2.13 Plot the data obtained in 4.2.7 thru 4.2.11 on semi-log graph paper as shown in Enclosure 6.1. Record the temperature of the calibration solution, measured in section 4.2.6, on this graph.

NOTE: There should be \sim 14 mV between the 0.05 ppm and the 0.15 ppm CL standards.

- 4.2.14 Place the mV meter in STANDBY.
- 4.2.15 Rinse the electrodes with demin water.
- 4.2.16 Add 1 ml of ISA solution to 100 ml of the sample dilution.
- 4.2.17 Immerse electrodes, thermometer, and a stirring bar into sample/ISA solution. Adjust stirring rate so that there is no vortex.
- 4.2.18 Check the temperature of the sample and compare to that listed on the calibration curve. The temperature should be within ± 5°C of that listed on the calibration curve.
- 4.2.19 Release the mV meter from STANDBY. Wait 2 minutes and compare the mV reading to the calibration curve.
 - 4.2.19.1 If the sample concentration is > 1.00 ppm repeat 4.2.14 thru 4.2.19 using a more dilute sample.
 - 4.2.19.2 If the sample concentration is < 1.00 ppm but > 0.05 ppm apply the necessary dilution factor and record on the calibration curve.





- 4.2.19.3 If the sample concentration is < 0.05 ppm consider repeating 4.2.14 thru 4.2.19 using a less dilute sample or apply the necessary dilution factor to < 0.05 and record the "less than" value on the calibration curve.
- 4.2.20 Place the mV meter in STANDBY and either repeat sections 4.2.15 to 4.2.19 for additional Cl measurements or proceed to 4.2.21.

- 7 -

- 4.2.21 Rinse the electrodes with demin water and store the electrodes as follows:
 - 4.2.21.1 Store the Cl electrode in 100 ml of demin water containing 1 ml of ISA solution.
 - 4.2.21.2 Store the reference electrode in a separate portion of demin water.
- 4.3 Waste Disposal
 - 4.3.1 Dispose of all liquid analytical waste in the "Post Accident Liquid Lab Waste" carboy. This container must be shielded and used as an interim liquid waste disposal container for all liquid analytical waste.
 - 4.3.2 Dispose of all solid analytical waste in the "Post Accident Solid Lab Waste" container.
 - 4.3.3 Request HP to designate an area where both post accident lab waste containers may be stored until final disposal.
 - 4.3.4 In the event an area is grossly contaminated and cannot be decontaminated, evaluate the need for shielding or protectvie covering to prevent the spread of airborne activity.
- 4.4 Dose Exposure Evaluation
 - 4.4.1 Evaluate the exposure to all personnel involved and complete all records, internal-body burden analysis, etc., as required. The exposure received may require an occupational exposure penalty. Higher doses will require a medical decision as to whether an individual can continue in radiation work.

5.0 References

- 5.1 Beckman Model 4500 Digital pH Meter Instruction Manual (1976)
- 5.2 Graphic Controls PHI9100 Chloride Electrode Instruction Manual
- 5.3 I. Sekerka, J. F. Lechner, and L. Harrison, Analysis for Chloride Ion in High Purity Water and Heavy Water of Pressurized Reactors and Cooling Systems by Ion Selective Electrode (1977)

. .

.

- 5.4 BAW Water Chemistry Manual, BAW-1385 (1975)
- 5.5 NUREG-0737
- 5.6 DPC System Health Physics Manual
- 5.7 Radiological Health Handbook, U.S. Dept. of HEW (1970)
- 5.8 Radiation Safety Technician Training Course, H.J. Moe, ANL-7291 Rev. 1 (1972)

- 8 -

6.0 Enclosures

r

- 6.1 Shield Thickness
- 6.2 E, A, and R valves for 1% Failed Fuel and DBA
- 6.3 Conversion Factors
- 6.4 Typical Calibration Curve
- 6.5 Manual Sample Dilution
SHIELD THICKNESS

The following equations can be used as an aid in determining shielding requirements for a sample of RCS after an accident.

given: $I = I_0 e^{\mu x}$ where: $\mu = \mu_m \rho$ $I/I_{o} = \bar{e}^{\mu}m^{\rho x}$ $ln(I/I_{o}) = -\mu_{m}\rho x$ $x = \frac{\ln(I_0/I)}{\mu_0}$ (eq. 6.1.1) where: x = thickness of absorber (cm) μ = linear attenuation coefficient (cm¹) μ_m = mass attenuation coefficient (cm²/g) @ the energy level (Mev) of the source ρ = density of the absorber material (g/cm³) I = source intensity w/zero thickness of the absorber (mR/hr or R/ur) I = source intensity w/an x thickness of the absorber (mR/hr or R/hr) given: (HVL) $I/I_0 = 1/2 = \bar{e}^{\mu} m^{\rho x}$ $ln(1/2) = -\mu_{m} \rho x$ (eq. 6.1.2) $x = \frac{0.693}{\mu_m \rho}$

A half value layer (HVL) is that thickness (x) of an absorber that will reduce the intensity of the Source to 1/2 of its initial value. As a general rule we add one HVL to our absorber thickness calculations for conservatism:

(eq. 6.1.3) $x_{total} = \frac{\ln(I_0/I) + 0.693}{\mu_m o}$





 $\bar{\text{E}},$ A and R Values for 1% Failed Fuel and DBA

1% Failed Fuel:

 $\tilde{E} \sim 0.34 \text{ MeV/dis}.$ A $\sim 0.293 \text{ mCi/ml}$

 $R = 0.18 \text{ mR/hr-mCi} @ 1m \text{ for } E \sim 0.34 \text{ MeV}$

100% Failed Fuel or Design Basis Accident (DBA)

 $\bar{E} \sim 1.14 \; \text{MeV/dis}. \qquad A \sim 1.324 \; x \; 10^5 \; \mu \text{Ci/ml}$

R = 0.58 R/hr-Ci @ lm for $\bar{E} \sim 1.14$ MeV

A direct proportion should exist between $\bar{\rm E}$ and R for any failed fuel value greater than 1% and less than 100%.

÷.,

40 0°

ENCLOSURE 6.3

CONVERSION FACTORS

Source Activity - (A)

			h	r-Ci		hr-mCi				
		-		R		mR				
1	µCi		=	3.7	x	10 ⁴ dps	=	2.22	x	10 ⁶ dpm
1	mCi		=	3.7	x	10 ⁷ dps	=	2.22	x	10 ⁹ dpm
1	Curie	(Ci)	=	3.7	х	10 ¹⁰ dis./sec.	=	2.22	x	10 ¹² dpm

Density - (ρ)

(ρ) for elements and common materials can be found on pg 65 and 66 of the "Radiological Health Handbook." ρ for lead (Pb) = 11.35g/cm3

Mass Attenuation Coefficient - (μ_m)

 $(\mu$) for elements and common materials at varying energy levels (MeV) for the source can be found on pg. 137 thru 139 of the "Radiological Health Handbook."

Distance - (d)

given: $I_0/I = d^2/d_0^2$ where: I_0 = Source intensity (mR/hr or R/hr) @ distance (d_0) I = Source intensity (mR/hr or R/hr) @ distance (d) 1 m. = 3.281 ft. = 39.37 in.

1 ft.= 0.305 m 3 ft. = 0.914 m





C2/0/A/2004/03C



MANUAL SAMPLE DILUTION

6.5.1 Place a magnetic stirrer in the shielded work area.

. . . .

. .

- 6.5.2 Partially fill a glass volumetric flask with demin water and place on the magnetic stirrer in the shielded work area.
- 6.5.3 Using tongs remove the sample from the shielded sample container and place in the shielded work area.
- 6.5.4 Using a pipette transfer enough sample to the volumetric flask to produce the desired dilution.
- 6.5.5 Fill the volumetric flask to the mark with demin water, insert a stirring bar and cap.
- 6.5.6 Using tongs place the sample back into the shielded sample container.
- 6.5.7 Stir the diluted sample for ~ 5 min and allow to remain in the shielded work area until ready for analysis or disposal.

6.5.8 Repeat 6.5.1 thru 6.5.7 for additional samples.

Form SPD-1002-1

C	0	N	T	R	0	L	C	0	P	Y



DUKE POWER COMPANY PROCEDURE PREPARATION PROCESS RECORD (1) ID No:<u>CP/0/A/2004/02E</u> Change(s) NA to NA Incorporated

- (2) STATION: Oconee Nuclear Station
- (3) PROCEDURE TITLE: <u>Post Accident Determination of Boron Concentration</u>
 <u>Using Carminic Acid</u>
 (4) PREPARED BY: <u>Accident Determination of Boron Concentration</u>
- (5) REVIEWED BY: _____ DATE: _____ 4/23/82 Cross-Disciplinary Review By: ECo. lu _____ N/R:_____
- (6) TEMPORARY APPROVAL (IF NECESSARY):

	By:()	SRO)	Date:
	By:		Date:
(7)	APPROVED BY: 18hu, BC 145-		Date: 4 26- 82
(8)	MISCELLANEOUS:		
	Reviewed/Approved By:		Date:
	Reviewed/Approved By:		Date:

CP/0/A/2004/02E Page 1 of 12

DUKE POWER COMPANY

OCONEE NUCLEAR STATION

POST ACCIDENT DETERMINATION OF BORON CONCENTRATION

USING CARMINIC ACID

1.0 Discussion

1.1 Scope

This procedure describes the colormetric method for the post accident determination of boron concentration ([B]) in the RCS when fuel damage is estimated to be greater than 1%.

1.2 Principle

In concentrated sulfuric acid, boron forms a red colored chelation complex with carminic acid by splitting off water. Due to its hygroscopic nature, sulfuric acid aids in splitting off the water and prevents the reaction from reversing. Hydrochloric acid is added to inhibit the interference of nitrates. The intensity of the red color is proportional to the concentration of boron ([B]) in the sample, that is, it obeys Beer's law.

- 1.3 Limits
 - 1.3.1 This method is applicable in the range of 0.1 to 2.0 ppm B.
 - 1.3.2 Refer to CP/0/B/2001/03 for the laboratory quality control of the spectrophotometer.
- 1.4 Interferences
 - 1.4.1 Substances normally present in reactor coolant do not interfere with this test.
 - 1.4.2 Colors at 590 nm interfere, however, none are expected.
- 1.5 Precautions
 - 1.5.1 DO NOT ATTEMPT ANY PHASE OF ANALYIS WITHOUT HEALTH PHYSICS COVERAGE!
 - 1.5.2 Radiation exposure to an individual during all phases of analysis should be limited so as not to exceed a quarterly accumulative exposure of 3 rems whole body; 7.5 rems skin of wholebody; or 18 3/4 rems extremities respectively. All personnel will need prior authorization from TSC to knowingly exceed any exposure limit. The exposure received may require an occupational exposure penalty and/

or a medical decision as to whether an individual can continue in radiation work.

- 1.5.2.1 If necessary to remedy a situation immediately hazardous to life and property, the Planned Emergency Exposure for Duke Power Personnel will not exceed 5 rems wholebody; 30 rems skin of wholebody; or 75 rems extremities
- 1.5.2.2 If necessary to save lives or prevent loss of life and/or extensive damage to property (voluntary basis only), the Planned Emergency Exposure for Duke Power Personnel will not exceed 25 rems wholebody; 150 rems skin of wholebody; or 375 rems extremities.
- 1.5.2.3 For Outside Services Personnel the Planned Emergency Exposure will not exceed 5 rems wholebody; 30 rems skin of wholebody; 75 rems extremities; or 15 rems other single organ.
- 1.5.3 Radiation levels of the lab area shall be measured continuously during all phases of analysis.
 - 1.5.3.1 Air activity should be determined by use of installed air monitors or through the use of portable air sampling equipment.
 - 1.5.3.2 Area dose rates should be established by the use of installed radiation monitors or by porta³, ie radiation survey instrument.
 - 1.5.3.3 Portable shielding, remote handling equipment, video equipment, etc., should be used where practical during sample preparation and sample analysis.
- 1.5.4 Water droplets or smudge marks on the cuvettes will cause an error in absorbance. Ensure light path surfaces of cuvettes are clean and dry.
- 1.5.5 Matched cuvettes shall be used in order to correct for absorption due to the glass surfaces of the cuvette.
- 1.5.6 Clean cuvettes with dilute nitric acid (1 + 99), air dry, and rinse with several small portions of standard or sample before filling and reading the absorbance.
- Samples containing more than 2 ppm B should be diluted to less than 2 ppm usign demineralized water.
 - 1.5.8 The carminic acid solution is hygroscopic (absorbs water). Keep tightly capped except when using.

- 1.5.9 This procedure shall be done either in a fume hood and/or other precautions shall be taken to avoid the release of gaseous activity.
- 1.5.10 Maximum color development requires approximately one hour with the color intensity decreasing slightly thereafter, but is of little consequence if standards are run simultaneously with the samples.

2.0 Apparatus

- 2.1 Spectrophotometer suitable for measurement at 590 nanometers (nm) - (Bausch and Lomb Spectronic 70 or equivalent).
- 2.2 50 mm cuvettes, matched, nitric acid washed, and air dried
- 2.3 5 ml glass pipettes nitric acid washed
- 2.4 Dispensers, preset for 5 ml and 30 ml
- 2.5 Dropper bottle
- 2.6 Disposable beakers
- 2.7 100 ml glass volumetric flasks nitric acid washed
- 2.8 Eppendorf pipettes with appropriate tips: 10, 25, 50, 100 µl
- 2.9 Parafilm for covering beakers
- 2.10 Analytical balance
- 2.11 Shielded Sample Container
- 2.12 Sample Tongs
- 2.13 Poly bottles 60ml (2 oz.) size

2.14 Carboy - ~ 1 gal.

3.0 Reagents

- 3.1 Carminic Acid Solution Dissolve 0.50 g (± 0.01 g) of carminic acid in 100 mls of concentrated sulfuric acid. Mix thoroughly until solution is complete. Store in a plastic bottle. This solution is relatively stable for several days, but exercise care to prevent water absorption. Discard after seven (7) days.
- 3.2 Boron Standard (~ 1000 ppm B) Standardize either the purchased or prepared standard before use per CP/0/A/2004/02A or CP/0/A/2004/02B.
 - 3.2.1 Purchased Standard Use Fisher SO-B-155 or equivalent. Check the expiration date before use and discard if expired.
 - 3.2.2 Prepared Standard Dissolve about 5.72 g (± 0.01 g) of boric acid in demin. water and dilute to 1 liter with

demin. water in a volumetric flask and mix. Stable for two (2) weeks.

- 3.3 Concentrated Hydrochloric Acid Use from dropper bottle. Sp. Gr. 1.19.
- 3.4 Concentrated Sulfuric Acid Sp. Gr. 1.84.
- 3.5 Nitric Acid (1 + 99) Mix 1 volume of concentrated nitric acid (Sp. Gr. 1.42) to 99 volumes of water.
- 4.0 Procedure
 - 4.1 Initial Conditions
 - 4.1.1 Evaluate the use of portable shielding, remote handling equipment, video equipment, etc., to minimize the exposure to personnel, in the lab for the analysis.
 - 4.1.2 Request HP to perform a constant radiation survey during the analysis.
 - 4.1.3 Determine and use the required respiratory equipment and protective clothing to prevent or minimize internal exposure in any Planned Emergency situation. Use high range and/or extremity dosimetry if required by HP.
 - 4.1.4 Prepare one (1) carboy (~ 1 gal.). Label as "Post Accident Lab Waste". This container must be shielded and used as interim liquid waste disposal container for all liquid analytical waste.
 - 4.1.5 Prepare a shielded work area in a fume hood. This area must be used for handling the sample when it is removed from the shielded sample container.
 - 4.1.6 Prepare a waste disposal container for all solid analytical waste. Label as "Post Accident Lab Waste".
 - 4.1.7 Check the serial numbers of the cuvettes to ensure that they are matched. Visually check the cells for scratches, cracks, chips and discoloration. Replace or clean as necessary.
 - 4.1.8 Clean cuvettes with dilute (1 + 99) nitric acid and air dry.
 - 4.1.9 Prepare a 1:2000 sample dilution using the post-accident sample panel or by the manual method described in Enclosure 6.5. Ensure 5 ml of diluted sample for the analysis.
 - 4.2 Concentration Measurements

CP/0/A/2004/02E Page 5 of 12

4.2.1 Prepare a series of boron standards in 100 ml volumetric flasks by diluting measured volumes of 1000 ppm boron standard with demin. water to produce 100 ml solution of the concentrations as follows:

> μl of 1000 ppm stock diluted to 100 ml = ppm B 10 μl 0.10 25 μl 0.25 50 μl 0.50 100 μl 1.00 200 μl 2.00

- 4.2.2 Pipet 5 ml of demin. water (reagent blank) and each standard to separate beakers and cover.
- 4.2.3 Pipet 5 ml of the 1:2000 sample dilution(s) to separate beaker(s) and cover.
- 4.2.4 To each beaker, add 5 drops of conc. HCl and 30 ml of conc. H₂SO₄, swirl to mix and cover. Allow approximately 15 minutes for cooling (less time will be needed for cooling if an ice bath is used to cool the samples).
 - CAUTION: Hydrogen chloride fumes and large amounts of heat may be generated during this phase. Add the conc. H₂SO₄ slowly and exercise care.
- 4.2.5 Add 5 ml of carminic acid solution to each beaker and swirl to mix. Cover and allow to stand approximately 45 minutes for full color development.
- 4.2.6 Rinse a clean and dry 50 mm cuvette with several small portions of the reagent blank before filling the cuvette completely.
- 4.2.7 Set the Spec-70 wavelength to 590 nm and set the absorbance to zero with the reagent blank.
- 4.2.8 Record the absorbance of each reacted standard in order of increasing concentration - rinse the matched 50 mm cuvette with several small portions of each standard before filling the cuvette completely and reading the absorbance of that standard.
- 4.2.9 Record the absorbance of each reacted sample rinse a clean and dry 50 mm cuvette with several small portions of each sample before filling the cuvette completely and reading the absorbance.
- 4.2.10 Plot the data obtained in 4.2.8 on linear graph paper as shown in Enclosure 6.4.

CP/0/A/2004/02E Page 6 of 12

- 4.2.11 Compare the abs. reading(s) from 4.2.9 to the calibration curve.
 - 4.2 '1.1 If the sample concentration is > 2.00 ppm repeat 4.2.1 thru 4.2.11 using a more dilute sample.
 - 4.2.11.2 If the sample concentration is < 2.00 ppm but > 0.10 ppm apply the necessary dilution factor and record on the calibration curve.
 - 4.2.11.3 If the sample concentration is < 0.10 ppm consider repeating 4.2.1 thru 4.2.11 using a less dilute sample or apply the necessary dilution factor to < 0.10 and record the "less than" value on the calibration curve.
- 4.3 Waste Disposal
 - 4.3.1 Dispose of all liquid analytical waste in the "Post Accident Liquid Lab Waste" carboy. This container must be shielded and used as an interim liquid waste disposal container for all liquid analytical waste.
 - 4.3.2 Dispose of all solid analytical waste in the "Post Accident Solid Lab Waste" container.
 - 4.3.3 Request HP to designate an area where both post accident lab waste containers may be stored until final disposal.
 - 4.3.4 In the event an area is grossly contaminated and cannot be decontaminated, evaluate the need for shielding or protective covering to prevent the spread of airborne activity.
- 4.4 Dose Exposure Evaluation
 - 4.4.1 Evaluate the exposure to all personnel involved and complete all records, internal-body burden analysis, etc., as required. The exposure received may require an occupational exposure penalty. Higher doses will require a medical decision as to whether an individual can continue in radiation work.

5.0 References

- 5.1 ASTM, Part 31, D 3082-79 Method A (1980)
- 5.2 B&W Water Chemistry Manual, BAW-1385 (1973)
- 5.3 NUREG-0737
- 5.4 DPC System Health Physics Manual

- 5.5 Radiological Health Handbook, U.S. Dept. of HEW (1970)
- 5.6 Radiation Safety Technician Training Course, H.J. Moe, ANL-7291 Rev. 1 (1972)
- 6.0 Enclosures
 - 6.1 Shield Thickness
 - 6.2 E, A, and R valves for 1% Failed Fuel and DBA
 - 6.3 Conversion Factors
 - 6.4 Typical Calibration Curve
 - 6.5 Manual Sample Dilution

CP/0/A/2004/02E Page 8 of 12

34

ENCLOSURE 6.1

SHIELD THICKNESS

The following equations can be used as an aid in determining shielding requirements for a sample of RCS after an accident.

 $I = I_0 e^{\mu x}$ where: $\mu = \mu_m \rho$ given: $I/I_{o} = \bar{e}^{\mu}m^{\rho x}$ $ln(I/I_{o}) = -\mu_{m}px$ $x = \frac{\ln(I_0/I)}{\mu_0 \rho}$ (eq. 6.1.1) x = thickness of absorber (cm) where: μ = linear attenuation coefficient (cm¹) μ_m = mass attenuation coefficient (cm²/g) @ the energy level (Mev) of the source ρ = density of the absorber material (g/cm³) I = source intensity w/zero thickness of the absorber (mR/hr or R/hr) I = source intensity w/an x thickness of che absorber (mR/hr or R/hr) (HVL) $I/I_{o} = 1/2 = \bar{e}^{\mu}m^{\rho x}$ given: $ln(1/2) = -\mu_{m} \rho x$ (eq. 6.1.2) $\mathbf{x} = \frac{0.693}{\mu_{\rm p}\rho}$

A half value layer (HVL) is that thickness (x) of an absorber that will reduce the intensity of the Source to 1/2 of its initial value. As a general rule we add one HVL to our absorber thickness calculations for conservatism:

(eq. 6.1.3) $x_{total} = \frac{\ln(I_0/I) + 0.693}{\mu_m \rho}$







E, A and R Values for 1% Failed Fuel and DBA

1% Failed Fuel:

·. ··

 $\bar{E} \sim 0.34 \text{ MeV/dis.}$

A № 0.293 mCi/ml

R = 0.18 mR/hr-mCi @ 1m for $\bar{E} \sim 0.34$ MeV

100% Failed Fuel or Design Basis Accident (DBA)

 ${f \bar E} \sim 1.14$ MeV/dis. A ~ 1.324 x 10⁵ µCi/ml

R = 0.58 R/hr-Ci @ lm for $\bar{E} \sim 1.14$ MeV

A direct proportion should exist between $\bar{\rm E}$ and R for any failed fuel value greater than 1% and less than 100%.

CONVERSION FACTORS

Source Activity - (A)

1 Curie (Ci) = 3.7×10^{10} dis./sec. = 2.22×10^{12} dpm 1 mCi = 3.7×10^{7} dps = 2.22×10^{9} dpm 1 µCi = 3.7×10^{4} dps = 2.22×10^{6} dpm $\frac{R}{hr-Ci} = \frac{mR}{hr-mCi}$

Density - (p)

(ρ) for elements and common materials can be found on pg 65 and 66 of the "Radiological Health Handbook." ρ for lead (Pb) = 11.35g/cm³

Mass Attenuation Coefficient - (μ_m)

 $(\mu$) for elements and common materials at varying energy levels (MeV) for the source can be found on pg. 137 thru 139 of the "Radiological Health Handbook."

Distance - (d)

given: $I_0/I = d^2/d_0^2$ where: I_0 = Source intensity (mR/hr or R/hr) @ distance (d_0) I = Source intensity (mR/hr or R/hr) @ distance (d) 1 m. = 3.281 ft. = 39.37 in. 1 ft.= 0.305 m 3 ft. = 0.914 m



.



46 0780

Not HUPFEL & ISSEN CO WARMAN .

MANUAL SAMPLE DILUTION

6.5.1 Place a magnetic stirrer in the shielded work area.

.

- 6.5.2 Partially fill a glass volumetric flask with demin water and place on the magnetic stirrer in the shielded work area.
- 6.5.3 Using tongs remove the sample from the shielded sample container and place in the shielded work area.
- 6.5.4 Using a pipette transfer enough sample to the volumetric flask to produce the desired dilution.
- 6.5.5 Fill the volumetric flask to the mark with demin water, insert a stirring bar and cap.
- 6.5.6 Using tongs place the sample back into "he shielded sample container.
- 6.5.7 Stir the diluted sample for ~ 5 min and allow to remain in the shielded work area until ready for analysis or disposal.
- 6.5.8 Repeat 6.5.1 thru 6.5.7 for additional samples.

	PROCEDURE PREPARATION PROCESS RECORD	Change(s) <u>NA</u> to <u>NA</u> Incorporated
2)	STATION: Oconee Nuclear Station	
3)	PROCEDURE TITLE: Post Accident Determinati	lon of Gamma Isotopic Activity Y
4)	PREPARED BY: Bruch Jander	DATE: 4 23 82
5)	REVIEWED BY: Alalus	DATE: 4/23/82
	Cross-Disciplinary Review By Dada	N/R:
)	TEMPORARY APPROVAL (IF NECESSARY):	
	By:(SRO)	Date:
	By:	Date:
)	APPROVED BY: 10mg Br Chun	Date: 4/26/82
)	MISCELLANEOUS:	
	Reviewed/Approved By:	Date:
	Reviewed/Approved By:	Date:

DUKE POWER COMPANY

CONTROL COPY INFORMATION ONLY

(1) ID No: CP/0/A/2005/02D

Form SPD-1002-1

DUKE POWER COMPANY

OCONEE NUCLEAR STATION

POST ACCIDENT DETERMINATION OF GAMMA ISOTOPIC ACTIVITY

1.0 Discussion

- 1.1 Scope This procedure describes the post accident determination of gamma isotopic activity as measured by gamma ray spectrometry in the RCS when fuel damage is estimated to be greater than 1%.
- 1.2 Principle Gamma interact with lithium drifted germanium diodes or Ge(Li) detectors, having an applied electric field, to produce electric charge pulses. These pulses are proportional to the energy lost by the incident gamma. Amplifiers amplify these electric pulse to produce voltage pulses. The multichannel analyzer (MCA) determines the amplitude of each voltage pulse and accumulates in a memory the number of pulses (or counts) in each amplitude band (or channel) in a given period of time. The number of counts accumulated in each channel forms a continuous curve of photopeaks called a "gamma spectrum".

The location of a photopeak in the gamma spectrum is proportional to the gamma energy of the incident gamma and is the basis for identifying a particular isotope in a sample. The area or total counts under a photopeak then represents the gamma activity of that particular isotope in the sample. Isotopes and their gamma activity are identified and calculated by computer program using the sample data stored in the MCA memory and reference data stored in a library file on magnetic disc. The results of the "pulse-height analysis" is presented on a paper printout. See Enclosures 6.1 and 6.2.

Certain conditions may require manual identification of photopeaks and calculation of gamma activity for isotopes not listed in the nuclide library as identified by computer program. The process of identifying photo peaks and calculating gamma activity is presented in this procedure.

- 1.3 Limits
 - 1.3.1 The sample size and geometry must be selected such that less than 15% deadtime is encountered at the Analog to Digital Converter (ADC).
 - 1.3.2 The lower limit of detectability is dependent on the background of the detector system in use, elapsed count time, sample size, sample geometry, detector efficiency and isotopes present.





1.4 Interferences

- 1.4.1 Variations in sample geometry can cause both qualitative and quantitative variations in the gamma ray spectrum. Calibration sources duplicating standard sample geometries can account for geometry effects.
- 1.4.2 Electronic characteristics such as deadtime, resolution and pulse pile-up degrade with increasing sample activity. Maintaining the deadtime below 15% by reducing the sample activity via decay or volume reduction and interpreting the gamma spectrum via computer program can provide easier and more reliable sample analysis.

1.5 Precautions

- 1.5.1 DO NOT ATTEMPT ANY PHASE OF ANALYSIS WITHOUT HEALTH PHYSICS COVERAGE!
- 1.5.2 Radiation exposure to an individual during all phases of analysis should be limited so as not to exceed a quarterly accumulative exposure of 3 rems whole body; 7.5 rems skin of wbolebody; or 18 3/4 rems extremities respectively. All personnel will need prior authorization from TSC to knc ingly exceed any exposure limit. The exposure received may require an occupational exposure penalty and/ or a medical decision as to whether an individual can continue in radiation work.
 - 1.5.2.1 If necessary to remedy a situation immediately hazardous to life and property, the Planned Emergency Exposure for Duke Power Personnel will not exceed 5 rems wholebody; 30 rems skin of wholebody; or 75 rems extremities.
 - 1.5.2.2 If necessary to save lives or prevent loss of life and/or extensive damage to property (voluntary basis only), the Planned Emergency Exposure for Duke Power Personnel will not exceed 25 rems wholebody; 150 rems skin of wholebody; or 375 rems extremities.
 - 1.5.2.3 For Outside Services Personnel the Planned Emergency Exposure will not exceed 5 rems wholebody; 30 rems skin of wholebody; 75 rems extremities; or 15 rems other single organ.
- 1.5.3 Radiation levels of the lab area shall be measured continuously during all phases of analysis.
 - 1.5.3.1 Air activity should be determined by use of installed air monitors or through the use of portable air sampling equipment.



- 2 -

- 1.5.3.2 Area dose rates should be established by the use of installed radiation monitors or by portable radiation survey instrument.
- 1.5.3.3 Portable shielding, remote handling equipment, video equipment, etc., should be used where practical during sample preparation and sample analysis.
- 1.5.4 Ensure sample container has not leaked prior to sealing in poly bag.

- 3 -

1.5.5 This procedure shall be done in a fume hood and/or other precautions shall be taken to avoid the release of gaseous activity.

2.0 Apparatus

- 2.1 15 cc glass gas vials with rubber septum
- 2.2 Hypodermic syringe assorted sizes
- 2.3 Plastic Petri Dishes (2")
- 2.4 Poly bottles: 50 ml, 500 ml, 1000 ml and 3500 ml.
- 2.5 Ge(Li) detector and multichannel analyzer (ND6600 or equivalent)
- 2.6 Shielded Sample Container
- 2.7 Sample Tongs
- 2.8 Carboy ~ 1 gal.
- 3.0 Reagents None
- 4.0 Procedure

4.1 Initial Conditions

- 4.1.1 Evaluate the use of portable shielding, remote handling equipment, video equipment, etc., to minimize the exposure to personnel, in the lab for the analysis.
- 4.1.2 Request HP to perform a constant radiation survey during the analysis.
- 4.1.3 Determine and use the requir d respiratory equipment and protective clothing to prevent or minimize interal exposure in any Planned Emergency situation. Use high range and/or extremity dosimetry if required by HP.
- 4.1.4 Prepare one (1) carboy (~ 1 gal.). Label as "Post Accident Lab Waste". This container must be shielded and used as intedim liquid waste disposal container for all liquid analytical waste.

4.1.5 Prepare a shielded work area in a fume hood. This area must be used for handling the sample when it is removed from the shielded sample container.

- 4 -

- 4.1.6 Prepare a waste disposal container for all solid analytical waste. Label as "Post Accident Lab Waste".
- 4.1.7 Prepare a sample dilution using the post-accident sample panel or by the manual method described in Enclosure 6.6.
- 4.2 Preparation of Gas Samples for Counting
 - 4.2.1 Remove about 10 cc of air from a sealed and labeled gas vial using a syringe to extract the air.
 - 4.2.2 Insert the syringe needle through the rubber septum of the sample gas bomb. Adjust the volume of sample in the syringe to the desired volume (based on activity).
 - 4.2.3 Quickly remove the syringe from the sample gas bomb and insert the syringe needle through the rubber septum of the gas vial, inject the sample and remove the syringe from the gas vial.
 - 4.2.4 Seal the vial in a poly bag and store in a plastic bag. Allow the vial to remain in the shielded work area until ready for analysis or disposal.
- 4.3 Preparation of Liquid Samples for Counting
 - 4.3.1 Transfer the desired volume of the sample dilution (based on activity) to a labeled poly bottle. The Ge(Li) system is calibrated for 50 ml, 500 ml, 1000 ml and 3500 ml geometries.
 - 4.3.2 Seal the poly bottle in a poly bag and store in a plastic bag. Allow the poly bottle to remain in the shielded work area until ready for analysis or disposal.

4.4 Waste Disposal

- 4.4.1 Dispose of all liquid analytical waste in the "Post Accident Liquid Lab Waste" carboy. This container must be shielded and used as an interim liquid waste disposal container for all liquid analytical waste.
- 4.4.2 Dispose of all solid analytical waste in the "Post Accident Solid Lab Waste" container.
- 4.4.3 Request HP to designate an area where both post accident lab waste containers may be stored until final disposal.
- 4.4.4 In the event an area is grossly contaminated and cannot be decontaminated, evaluate the need for shielding or protective covering to prevent the spread of airborne activity.





- 4.5 Dose Exposure Evaluation
 - 4.5.1 Evaluate the exposure to all personnel involved and complete all records, internal-body burden analysis, etc., as required. The exposure received may require an occupational exposure penalty. Higher doses will require a medical decision as to whether an individual can continue in radiation work.

5.0 References

- 5.1 BAW Water Chemistry Manual, BAW-1385 (1973)
- 5.2 BAW Radiochemistry Manual, BAW-1410 (1975)
- 5.3 ASTM, Part 31, D3649-78
- 5.4 ASTM, Part 31, ANSI/ASTM D2459-72
- 5.5 NUREG-0737
- 5.6 DPC System Health Physics Manual
- 5.7 Radiological Health Handbook, U.S. Dept. of HEW (1970)
- 5.8 Radiation Safety Technician Training Course, H.J. Moe, ANL-7291 Rev. 1 (1972)

6.0 Enclosures

- 6.1 Title Page of ND6600 Print-out
- 6.2 Summary Page of ND6600 Print-out
- 6.3 Shield Thickness
- 6.4 E, A, and R valves for 1% Failed Fuel and DBA
- 6.5 Conversion Factors
- 6.6 Manual Sample Dilution



**************************************	41:13 AM ***********************************
CHEM. 2 LPI CRUD SRWP	4 (NOTE 2) ENCLOSURE 6.1
MPLE DATE: 7NOV80 1820:00 MPLE IDENTIFICATION: CRUD FILTE TYPE OF SAMPLE: SOLIDS SAMPLE QUANTITY: 100.0000 SAMPLE GEOMETRY: FILTER AT 6CM EFFICIENCY FILE NAME: EFF. CFILT6	R UNITS: ML
ACQUISITION DATE: 13NOV80 29:37 PRESET TIME(LIVE): 600. SEC ELAPSED REAL TIME: 644. SEC ELAPSED LIVE TIME: 600. SEC	* * FWHM(1332) 1.856 * SENSITIVITY: 5.000 * SHAPE PARAMETER: 35.0 % * NER ITERATIONS: 10. *
DETECTOR: GELI-C DATE CALIBRATED: 12NOVSO 29:45 KEV/CHNL: 0.5004218 OFFSET: -0.1842307 KEV	* * LIBRARY: NUCL. MASTER * ENERGY TOLERANCE: 1. 750KV * HALF LIFE RATIO: 8.00 * ABUNDANCE LIMIT: 80.00% *
COLLECTED BY:	**************************************
RWP/SRWP/LWR/GWR: SPIRATORY EQUIP USED: CONTROL GROUP USE)	* COMMENTS: * *

DEAD TIME: 7. 33% ACTION REQUIRED: NONE

				ENERGY	WINDOW	32. 343	TO 204	46. 54	1			
P	ĸ	IT	ENERGY	AREA	BKGND	FWHM	CHANNEL	LEFT	PW	CTS/SEC	%ERR	FIT
	1	0	67.07	1451	. 17278.	1.71	134. 39	130	9	2. 418E 00	13.1	
	2	0	80. 27	17243	25599.	1.66	160.77	154	14	2. 874E 01	1.5	
	3	0	109.63	294	11084.	1.24	219.45	218	6	4. 900E-01	51.0	
	4	0	140.56	7004	. 23187.	1.73	281. 25	275	12	1. 167E 01	3.3	
	5	0	145. 32	790). 13928.	1. 52	290.77	283	7	1. 317E 00	21. 4	
	6	:0	153. 31	656	. 16112.	2.09	306.73	304	7	1. 093E 00	27.7	,
	7	0	162. 33	9200	. 27129.	1. 61	325. 75	320	12	1. 533E 01	2.7	
	8	0	176.99	2423	20205.	1.91	354.05	350	9	4 038E 00	8 5	
	9	0	273. 52	610	9725.	1. 56	546 94	543	9	1 0165 00	23.2	
1	0	0	284. 35	20076	. 15503.	1. 78	568.59	561	15	3 344E 01	1 1	
1	1	0	304. 87	3257	. 12620.	1.83	609 59	603	13	5 4295 00	5 2	
1	2	0	319.36	1954	10192	1.54	639 55	634	11	3 2545 00	7 7	
	3	0	328. 84	13920	15892	1 74	457 43	457	1.4	2 2205 01	1 5	
	4	Ó	340. 51	2337	9485	1 44	480 81	4.74	11	2 9945 00	4. 2	
1	5	0	364. 51	205590	15875	1 79	728 78	771	10	3 4745 00	0	
1	i.	0	423 56	2150	6074	1 54	844 77	240	12	3 5975 00	0. 2 E /	
-	7	3	432 50	1577	2220	2 00	944 44	050	24	3. 36/E 00	0.0	
;	5	5	437 54	1091	2705	1 70	974 70	000	24	1 9195 00	0. /	1. SEE 00
	5	0	497 05	22420	7550.	1.07	072 44	0.0		1. 5132 00	1. 3	
-	in	0	467.05	170	2006.	1. 37	000 40	200	18	3. 737E 01	0.9	
			E.0. 07	1.50	3142.	1.03	1005 04	1000	0.0	2. 9/EE-01	45.0	

CP/0/A/2005/02D Page 1 of 2

ENCLOSURE 6.1

LEGEND FOR ENCLOSURE 6.1

NOTE 1: Date print-out generated.

NOTE 2: Title of sample.

SAMPLE DATE: Date sample collected.

SAMPLE IDENTIFICATION: Description of sample container (vial, bottle or filter).

TYPE OF SAMPLE: Gas, liquid or solid.

SAMPLE QUANTITY: Number of units and unit type for sample distributed in sample container.

SAMPLE GEOMETRY: Sample container at the specified distance from the detector.

EFFICIENCY FILE NAME: Describes the efficiency curve referenced as a function of the geometry.

ACQUISITION DATE: Date data acquisition began.

PRESET TIME (LIVE): User specified count time in seconds.

ELAPSED REAL TIME: Elapsed clocktime in seconds.

ELAPSED LIVE TIME: Elapsed ADC time in seconds.

FWHM: During detector calibration, the ratio of the peak width at half its maximum height of the 1332 KeV (Co-60) peak is calculated. The Peak Search program applies this value to each peak to determine if it is a single or multiplet peak.

SENSITIVITY: The Peak Search program will ignore a peak whose height is less than the selected number of standard deviations above the average background in the region of the peak.

SHAPE PARAMETER: A channel must be greater than the average background in the region of the peak by the specified percentage to be considered as part of the peak area.

NBR ITERATIONS: To analyze multiplet peaks, the Peak Search program will successively refine the shape of the peaks (run a line thru the points) until successive "passes" over the peaks do not differ significantly or until the maximum number (NBR) of passess as specified are reached.

DETECTOR: The user-selected detector used.

DATE CALIBRATED: Detector/ADC calibration date.

KEV/CHANL: Slope of the energy calibration curve in KeV/Channel.

OFFSET: Intercept of the energy calibration curve in KeV.

LIBRARY: Library file used for identification of peaks.

ENERGY TOLERANCE: The ND program compares the KeV of detected peaks with the KeV of known nuclides from the selected library file. A detected peak will be accepted as a known nuclide if its KeV is within (±) the selected energy tolerance of the known nuclides KeV.

HALF LIFE RATIO: For a nuclide to be considered genuine, 8 half-lives must not be exceeded between the Sample Date and the Acquisition Date.

ABUNDANCE LIMIT: The ND program will accept the identification of a nuclide having multiple gammas if the total detectable abundance exceeds the selected percentage of the nuclides absolute abundance. SUMMARY OF NUCLIDE ACTIVITY

PAGE 4 .

ENCLOSURE 6.2

TOTAL LINES IN SPECTRUM	58
LINES NOT LISTED IN LIBRARY	13
IDENTIFIED IN SUMMARY REPORT	42 72. 41%



FISSION GAS

NUCLIDE	HLIFE			HLSEC			DECAY			UC/UT			ERROR			%ERR		
XE-131M	1.	19E	OID	1.	028E	06	2.	264E	-3	2.	297E	-2	6.	289E	-4	2.	74	
XE-133	5.	25E	OOD	4.	536E	05	З.	338E	-3	З.	115E	-3	4.	726E	-5	1.	52	

ACTIVATION PRODUCT

NUCLIDE		HLIFE			HLSEC			DECAY			UC/U	Г	ERRO	%ERR	
CR-51	2.	77E	OID	2.	393E	06	1.	901E	-3	1.	645E	-3	1. 258E	-4	7.65
MN-54	3.	12E	02D	2.	700E	07	1.	686E	-3	8.	840E	-5	1. 100E	-5	12.44
CO-59	7.	3SO	OID	6.	117E	05	1.	755E	-3	5.	703E	-3	3. 462E	-5	0. 61
FE-59	4.	46E	OID	3.	853E	06	1.	809E	-3	1.	457E	-4	2. 329E	-5	15.99
CO-60	5.	27E	OOY	1.	663E	03	1.	670E	-3	1.	415E	-4	1. 247E	-5	8. 81
AG-110M	2.	51E	020	2.	167E	07	1.	691E	-3	4.	230E	-4	1. 263E	-5	2.99

HALOGEN FISSION PRODUCT

NUCLIDE		H	IFE		HLSE	2		DECAY	1		UC/U	Г		ERROP	2	7.8	ERR
I-131	8	04E	OOD	6.	947E	05	2.	623E	-3	3.	294E	-2	7.	806E	-5	0.	24
I-133	2.	0:8E	01H	7.	488E	04	1.	119E	-1	3.	218E	-2	1.	142E	-3	З.	55

FISSION PRODUCT

NUCLIDE HLIFE		HLSEC	DECAY	UC/UT	ERROR	%ERR	
ZR-95	6. 40E 01D	5. 528E 06	1.764E -3	1. 276E -4	1. 616E -5	12.66	
NB-95	3. 52E 01D	3. 037E 06	1.849E -3	2. 312E -4	1. 514E -5	6. 55	
RU-103	3. 93E 01D	3. 400E 06	1.828E -3	2. 556E -5	1. 151E -5	45.04	
CS-134	2. 06E 00Y	6. 501E 07	1. 675E -3	1. 186E -3	2. 063E -5	1. 74	
CS-136	1. 31E 01D	1. 132E 06	2. 202E -3	7.144E -4	1. 683E -5	2.36	
CS-137	3. 02E 01Y	9. 521E 08	1. 667E -3	1. 259E -3	1. 776E -5	1. 41	
BA-140	1. 28E 01D	1. 105E 06	2. 216E -3	8. 845E -3	1. 221E -4	1. 38	
LA-140	4. 02E 01H	1. 448E 05	1. 468E -2	4. 826E -2	4. 068E -4	0.84	



LEGEND FOR ENCLOSURE 6.2

TOTAL LINES IN SPECTRUM: Total number of peaks found by Peak Search program.

LINES NOT LISTED IN LIBRARY: Number of peaks not identifiable by the ND program.

IDENTIFIED IN SUMMARY REPORT: Number of peaks identified and accepted.

NUCLIDE: The nuclides identified by the ND program.

HLIFE: The half life of the identified nuclides in scientific notation with the appropriate time.

HLSEC: The half life of the identified nuclide converted to seconds in scientific notation.

DECAY: The ratio of the elapsed time between the Sample Date and the Acquisition Date to the HLSEC.

UC/UT: The activity of the identified nuclides in µCi per unit of volume or weight.

ERROR: The confidence level (standard deviation) at 1 sigma, of the activity of the identified nuclides in µCi/unit volume or weight.

% ERR: The standard deviation (± 1 sigma) in percentage.

....

SHIELD THICKNESS

The following equations can be used as an aid in determining shielding requirements for a sample of RCS after an accident.

given:
$$I = I_0 e^{\mu x}$$
 where: $\mu = \mu_m \rho$
 $I/I_0 = \bar{e}^{\mu} m^{\rho x}$
 $\ln(I/I_0) = -\mu_m \rho x$
(eq. 6.1.1) $x = \frac{\ln(I_0/I)}{\mu_m \rho}$
where: $x = \text{thickness of absorber (cm)}$
 $\mu = \text{linear attenuation coefficient (cm^1)}$

 μ_m = mass attenuation coefficient (cm²/g) @ the energy level (Mev) of the source ρ = density of the absorber material (g/cm³)

I = source intensity w/zero thickness of the absorber (mR/hr or R/hr)

I = source intensity w/an x thickness of the absorber (mR/hr or R/hr)

given:

HVL)
$$I/I_0 = 1/2 = e^{\mu_m \rho x}$$

 $ln(1/2) = -\mu_m \rho x$

 $x = \frac{0.693}{\mu_m \rho}$

A half value layer (HVL) is that thickness (x) of an absorber that will reduce the intensity of the Source to 1/2 of its initial value. As a general rule we add one HVL to our absorber thickness calculations for conservatism:

(eq. 6.1.3) $x_{total} = \frac{\ln(I_0/I) + 0.693}{\mu_m \rho}$

4

ENCLOSURE 6.4

Ē, A and R Values for 1% Failed Fuel and DBA

1% Failed Fuel:

 $\bar{E} \sim 0.34 \text{ MeV/dis.}$

÷. ;

A ~ 0.293 mCi/ml

 $R = 0.18 \text{ mR/hr-mCi} @ 1m \text{ for } E \sim 0.34 \text{ MeV}$

100% Failed Fuel or Design Basis Accident (DBA)

 $\bar{E} \sim 1.14 \text{ MeV/dis.}$ A $\sim 1.324 \times 10^5 \text{ } \mu\text{Ci/ml}$

R = 0.58 R/hr-Ci @ lm for $E \sim 1.14$ MeV

A direct proportion should exist between \bar{E} and R for any failed fuel value greater than 1% and less than 100%.

CONVERSION FACTORS

Source Activity - (A)

			h	c-Ci		hr-mCi				
			_	R		mR				
1	μCi		=	3.7	x	10 ⁴ dps	=	2.22	x	10 ⁶ dpm
1	mCi		=	3.7	x	10 ⁷ dps	=	2.22	x	10 ⁹ dpm
1	Curie	(Ci)	=	3.7	х	10 ¹⁰ dis./sec.	=	2.22	х	10 ¹² dpm

Density - (ρ)

(ρ) for elements and common materials can be found on pg 65 and 66 of the "Radiological Health Handbook." ρ for lead (Pb) = 11.35g/cm³

Mass Attenuation Coefficient - (μ_m)

 $(\mu$) for elements and common materials at varying energy levels (MeV) for the source can be found on pg. 137 thru 139 of the "Radiological Health Handbook."

Distance - (d)

given: $I_0/I = d^2/d_0^2$

where: I_0 = Source intensity (mR/hr or R/hr) @ distance (d_0) I = Source intensity (mR/hr or R/hr) @ distance (d)

1 m. = 3.281 ft. = 39.37 in.

1 ft.= 0.305 m 3 ft. = 0.914 m



. .

MANUAL SAMPLE DILUTION

- 6.5.1 Place a magnetic stirrer in the shielded work area.
- 6.5.2 Partially fill a glass volumetric flask with demin water and place on the magnetic stirrer in the shielded work area.
- 6.5.3 Using tongs, remove the sample from the shielded sample container and place in the shielded work area.
- 6.5.4 Using a pipette, transfer enough sample to the volumetric flask to produce the desired dilution.
- 6.5.5 Fill the volumetric flask to the mark with demin water, insert a stirring bar and cap.
- 6.5.6 Using tongs, place the sample back into the shielded sample container.
- 6.5.7 Stir the diluted sample for ~ 5 min. and allow to remain in the shielded work area until ready for analysis as disposal.
- 6.5.8 Repeat 6.5.1 thru 6.5.7 for additional samples.



. .

. .



INFORMATION ONLY

DUKE POWER COMPANY PROCEDURE PREPARATION PROCESS RECORD ID No: <u>HP/O/B/1009/13</u> Change(s) 2 to <u>N/A</u> Incorporated

Form SPD-1002-1

2

STATION:	Oconee		
PROCEDURE T	ITLE: Procedure for Im	plementation and	Verification for th
Availability	of a Back-Up Source	of Meteorologica	1 Data
PREPARED BY	: Smah A. Cou	A DATE:_	4/22/52
REVIEWED BY	: Charle you go	DATE:	4-22-82
Cross-Disci	plinary Review By:		N/R: 64
TEMPORARY A	PPROVAL (IF NECESSARY):	<u> </u>
By:		(SRO) Date:	
Ву:	~	Date:_	
APPROVED BY	: Jony B. Omer	Date:	4) 23/82
MISCELLANEO	US:	1	,
Reviewed/Ap	proved By	The Date:	64/23/52
Portionad / An	proved By:	Date:	/ /



HP/0/B/1009/13 Page 1 of 3

DUKE POWER COMPANY

OCONEE NUCLEAR STATION

PROCEDURE FOR IMPLEMENTATION AND VERIFICATION FOR

THE AVAILABILITY OF A BACK-UP SOURCE OF METEORO-

LOGICAL DATA

1.0 Purpose

To provide a procedure for implementation and verification for the availability of a back-up source of meteorological data needed to make an offsite dose projection should the station's meteorological data equipment become unavailable.

2.0 References

- 2.1 NUREG 1.23, Proposed Revision 1* to Regulatory Guide 1.23, Meteorological Programs in Support of Nuclear Power Plants.
- 2.2 NUREG 0654, Annex 1 to Appendix 2, (o), Criteria for Preparation and Evaluation of Radiological Emergency Response Plans and Preparedness in Support of Nuclear Power Plants.
- 2.3 Oconee Nuclear Station Emergency Plan.

3.0 Limitations and Precautions

- 3.1 Maintain record of notification (Enclosure 5.1) for a minimum of two years. This procedure will be superseded as acceptable backup measures are developed by Oconee Nuclear Station.
- 3.2 Contact the National Weather Service at the Greenville-Spartanburg Airport by telephone using Enclosure 5.1. The telephone number listed on the Enclosure is a 24 hour number.
- 3.3 These contacts shall be made monthly and alternate among shifts.

4.0 Procedure

- 4.1 Record the following meteorological information on Enclosure 5.1.
 - 4.1.1 Wind direction (in tens of degrees).
 - 4.1.2 Wind speed (in knots).
 - 4.1.3 Air temperature.
 - 4.1.4 Weather conditions (clear, partly cloudy, etc.)
- 4.2 Record concurrent on-site meteorological information on Enclosure 5.1.

HP/0/B/1009/13 Page 2 of 3

5.0 Enclosure

5.1 Communications Check, Meteorological Data.




HP/0/B/1009/13

Meteorological Data Back-Up Source: National Weather Service, Greenville - Spartanburg Airport Telephone Number: 803-877-6998 Communication Check Enclosure 5.1

	SNO	SNO	SNO	NWS	SNO	SNO	SNO	SNO	SMO	SNO	SNO	SNO
Weather Conditions			 									
Air Temperature			1	 	.							
Wind Speed (Knots)	1			1			1]
Wind Direction (Ten of Degrees)												
Person Calling												
Date												
Time												0
Month	Jan.	Feb.	farch	pr11	A EJ	lune	July	ueust	ept.	.)ct.	ov:)ec.

INFORMATION ONLY

(1) ID No: <u>HP/0/B/100</u>9/15 Change(s) 4_to

Form SPD-1002-1

*

	PROCESS RECORD		<u>N/A</u> Incorporated
2)	STATION: Oconee		
3)	PROCEDURE TITLE: Procedure for Sampling an	nd Quanti	fying High Level Gaseou
	Radioiodine, and Particulate Radioactivi	ty	
•)	PREPARED BY: E. D. Harch	DATE:	4-24 32
5)	REVIEWED BY: Charles 4 mgam	DATE:	4-29-82
	Cross-Disciplinary Review By:		N/R: 5
)	TEMFORARY APPROVAL (IF NECESSARY):		0
	By:(SRO)	Date:	
	By:	Date:	
)	APPROVED BY: 7. B. Javan 15. 7. P.	Date: 4	2/29/82
)	MISCELLANEOUS:		-
	Reviewed/Approved By:	_ Date:	
	Reviewed/Approved By:	Date:	

DUKE POWER COMPANY PROCEDURE PREPARATION



DUKE POWER COMPANY

OCONEE NUCLEAR STATION

PROCEDURE FOR SAMPLING AND QUANTIFYING HIGH

LEVEL GASEOUS, RADIOIODINE, AND PARTICULATE RADIOACTIVITY

1.0 Purpose

This procedure describes methods for collecting samples to evaluate effluent and containment noble gas and radioiodine activities during accident conditions.

2.0 References

- 2.1 System Health Physics Manual, Section I, M, Radioactive Waste Control Requirements
- 2.2 Technical Specifications Oconee Nuclear Station, Appendix A. Section 3.10 Release of Gaseous Radioactive Waste
- 2.3 HP/0/B/1000/60/A, Procedure for Gaseous Waste Sampling and Analysis
- 2.4 HP/0/B/1000/60/D, Procedure for Unit Vent Sampling and Analysis
- 2.5 HP/0/B/1000/57, Air Sampling, Counting and Calculating Procedure
- 2.6 HP/0/B/1000/60/B, Procedure for Reactor Building Gaseous Purge
- 2.7 HP/0/B/1000/60/H, Procedure for Changeout and Analysis of Reactor Building Iodine Cartridges and Particulate Filters
- 2.8 HP/0/B/1000/55, Instrument Monitoring and Survey Procedure
- 2.9 HP/O/B/1001/14, Procedure for Nuclear Data 6600 System Operation
- 2.10 HP/0/B/1006/07. Procedure for Preparation of Gas Calibration Sources

3.0 Limits and Precautions

- 3.1 This procedure is written for use under abnormal conditions which could involve extremely high radiation levels. Only Health Physics management should authorize the use of this procedure when needed and should provide appropriate surveillance and control of people taking the samples.
- 3.2 Whenever the effluent monitor goes offscale, appropriate grab samples or radiation level measurements should be taken to estimate effluent release rates and the amount of effluent released.

NOTE: No samples will be taken unless authorized by Health Physics management. When samples are taken, use protective clothing, gloves, respiratory protective equipment, portable shielding, high range dosimeters and survey instruments as determined by prejob ALARA planning.

- 2 -

3.3 Should effluent concentrations exceed those values specified in Enclosure 5.5, notify the emergency coordinator of possible technical specification violation.

4.0 Procedure

- 4.1 Conduct planning session. Consider the guidance provided in Enclosure 5.1 in preplanning.
- 4.2 Use an ion chamber to measure the radiation dose rate from the reactor building or unit vent RIA supply line.
- 4.3 When contact dose rate readings at Iodine RIA sample holder (RIA-44 for Vent/RIA-48 for Reactor Building` and middle point of Gaseous RIA supply line (RIA 45/46 for Vent/RIA 49 for Reactor Building) are less than 3 R/hr, collect gas and Iodine samples as described in Steps 4.4.1 to 4.4.6.
- 4.4 Sample Collection
 - 4.4.1 Prepare a flow path in the following order:

NOTE: During an accident, the containment building is isolated. Contact Shift Supervisor for manual override to open valves for sampling.

Supply \rightarrow particulate filter paper \rightarrow CP-100G silver zeolite sample cartridge \rightarrow vacuum pump \rightarrow flow meter (0-80LPM) \rightarrow 100 ml Argonne gas bomb \rightarrow return line.

See Enclosure 5.2 for apparatus setup.

- 4.4.2 Collect sample. Minimum sample volume is 5 liters.
- 4.4.3 Upon completion, turn off sample pump, close exhaust valve of gas bomb, close intake valve of gas bomb, close supply valve, then close return valve.
- 4.4.4 Remove filter and cartridge; monitor sample and place in protective wrapper (poly bag). Indentify with

4.4.4.1 Start time

4.4.4.2 Stop time

4.4.4.3 Flow rate

4.4.4.4 Sample location

- 4.4.5 Place samples in shielding container for return to the counting laboratory.
- 4.4.6 If contact reading on sample is greater than .01 R/hr, Count Room personnel will make decision on counting sample.
- 4.5 If the dose rate at the gaseous RIA (RIA 45/46 for Vent/RIA 49 for Reactor Building) supply line is greater than 3R/hr, obtain gaseous concentration (μCi/ml) corresponding to the radiation dose rate (R/hr) from Enclosure 5.3.
- 4.6 If the dose rate at the Iodine RIA (RIA 44 for Vent/RIA 48 for Reactor Building) sample holder is between 3 R/hr and 15 R/hr, follow Step 4.6.1 to 4.6.5. If the dose rate exceeds 15 R/hr, no samples will be taken.
 - NOTE: Contact Shift Supervisor for manual override.
 - 4.6.1 Remove charcoal cartridge from the Iodine RIA sample holder. Survey removed charcoal cartridge and save to be counted if possible.
 - 4.6.2 Collect sample through silver zeolite cartridge for two (2) minutes. Collect data from RIA flow meter for correct volume.
 - 4.6.3 Remove cartridge from sample holder, monitor sample and place cartridge in poly bag and put bag into a shielded container for transport to a lower background area for counting. Place new cartridge in sample holder for future use if desirable.
 - 4.6.4 Take a contact dose rate measurement on the sample cartridge using an ion chamber. Obtain Iodine concentration (µCi/ml) corresponding to the radiation dose rate (R/hr) from Enclosure 5.4.
 - 4.6.5 If the contact reading is below .01 R/hr, perform a gamma isotopic analysis of the sample.
- 4.7 Isotopic Analysis of Sample
 - 4.7.1 <u>Iodine + Particulate</u> Separate filter and cartridge and seal in wrappers. Label cartridge with data. Analyze particulate and iodine cartridge by Reference 2.9.





- 3 -

4.7.2

Gaseous - Gas bomb is labeled for desired data and processed for gamma spectroscopy.

- 4 -

- 4.7.2.1 Test gas bomb for excessive dead time by Reference 2.9.
 - 4.7.2.1.1 If the dead time is greater than 15% at the 9cm geometry for gas bombs, dilute the gas sample by Ref. 210. Further dilutions may be necessary until the desired dead time value < 15% is achieved.</p>
- 4.7.3 Review spectral display versus printout to assure correct gamma isotopic analysis report.
- 4.8 Results
 - 4.8.1 Forward MCA results to TSC for review and further distribuiton.
 - NOTE: For rapid assessment of technical specifications compliance, use Enclosure 5.5.

5.0 Enclosures

1

36

- 5.1 Guidelines for Collecting, Transporting, Analyzing, and Disposing of High Level Samples
- 5.2 Apparatus setup for sample collection.
- 5.3 Conversion of gaseous RIA supply line dose rate (R/hr) to gaseous effluent concentration (µCi/ml)
 - 5.4 Conversion of Iodine sample dose rate (R/hr) to Iodine effluent concentration (µCi/ml)
 - 5.5 Conversion of Vent Sample Results to Curies per second

ENCLOSURE 5.1

GUIDELINES FOR COLLECTING, TRANSPORTING, ANALYZING,

ADD DISPOSING OF HIGH LEVEL SAMPLES

- 1. Before entering sampling points, be aware and prepare for high radiation levels and possible airborne areas.
- 2. Preplan and stage sampling apparatus in a low background area.
- 3. Take samples expeditiously.
- Handle samples with either the source handling tools available in the H.P. Source Room or with tongs from station supply area.
- 5. Transport hot samples to counting lab with good ALARA practices.

Examples: A. sample sitting on a cart or hand truck ---- distance.

- B. Sample surrounded by a lead blanket or lead bricks (all of which are availabe in the H.P. Lab areas or supply) --- shielding.
- 6. Contamination control should be maintained by double bagging the sample during transport and analysis.
- Disposal or storage of the high level samples in the Counting Facility should merit the same controls as sampling, i.e., ALARA transportation, shielded storage, or storage at a remote location.

ENCLOSURE 5.2

HP/0/B/1009/15

SAMPLE COLLECTION



A) Set up sample system according to diagram.

B) Before opening supply and return valves

ENSURE

- 1) Tight hose fittings.
- 2) Correct valve positions.
- 3) Open flow rate meter (a couple of full turns).
- 4) Regulate flow rate with supply valve (when possible).
- C) Turn on sample pump.
- D) Shut system down if pressure or vacuum meters build up.
- E) Check gas collector for build up of back pressure.
- F) Sample time is an important consideration in the validity of the sample results.
- G) Upon completion of sample:
 - a) Turn off sample pump.
 - b) Close exhaust valve of gas bomb.
 - c) Close intake valve of gas bomb.
 - d) Close supply valve.
 - e) Close return valve.





ENCLOSURE 5.5

CONVERSION OF VENT SAMPLE RESULTS TO VENT ACTIVITY RELEASE RATE

 Determine vent activity release rate in Ci/sec for iodine, in Ci/sec tor noble gases, and in Ci/sec for particulates by the following equation:

 $Ci/sec = V_{p} \times Conc. \times 4.72 \times 10^{-4}$

where, V = Vent flow rate in CFM

Conc. = sample concentration results in Ci/m^3

NOTE: $1 \text{ uCi/ml} = 1 \text{ Ci/m}^3$

 4.72×10^{-4} = conversion of ft³/min to meters/sec

$$\frac{ft^3}{min} \times \frac{0.02832m^3}{ft^3} \times \frac{1 min}{60 sec}$$

NOTE:

Should any other gaseous waste releases be in process, calculate Ci/sec values as above and sum station total Ci/sec of iodine, noble gases, and particulates.

 Average the calculated vent activity release rates over the period of a calendar quarter to determine Ci/sec/qtr for iodine, Ci/sec/qtr for noble gases, and Ci/sec/qtr for particulates by the following equation:

 $Ci/sec/qtr = Ci/sec \times \frac{duration of release in seconds}{7.88 \times 10^6}$

where,

Ci/sec = vent activity release rates calculated in 1). 7.88 x 10^6 = seconds in a calendar guarter

3) Compare results to the following values:

When rate of gaseous waste release in Ci/sec when averaged over a calendar quarter exceeds:

a) iddine - 2.4 x 10^{-8} Ci/sec/gtr

noble gas - 3.2 x 10⁻³ Ci/sec/qtr

particulates - 7.0 x 10⁻⁸ Ci/sec/qtr

(Compliance with Tech. Spec. 3.10.1 required.)

b) iodine - 9.6 x 10⁻⁸ Ci/sec/qtr noble gas - 1.28 x 10⁻² Ci/sec/qtr particulates - 2.8 x 10⁻⁷ Ci/sec/qtr (Compliance with Tech. Spec. 3.10.2 required.)



c) iddine - 1.2×10^{-6} Ci/sec/qtr

· · · · · · ·

. . . .

particulates - 3.5 x 10⁻⁶ Ci/sec/qtr

(Compliance with Tech. Spec. 3.10.2 required)

d) noble gas - 8.0 x 10^{-2} Ci/sec/qtr

(Compliance with Tech. Spec. 3.10.2 required)

 Should any of the above values be exceeded, notify the emergency coordinator of condition.

- 2 -

Form SPD-1002-1

		PROCEDURE PREPARATIO PROCESS RECORD	N	Change(s)Incorp	orated
(2)	STATION: Ocon	ee			
(3)	PROCEDURE TITLE:	Environmental Equipme	nt Checks		
(4)	PREPARED BY:	ne Rutnam	DATE:	4-6-82	
(5)	REVIEWED BY:	the p	DATE:	4/6/82	<u> </u>
	Cross-Disciplinary	Review By:		N/R:	
(6)	TEMPORARY APPROVAL	(IF NECESSARY):			
	By:	(SRO)	Date:		
	By:		Date:		
(7)	APPROVED BY:	Blaughn	_ Date:	4-8-82	
(8)	MISCELLANEOUS:				
	Reviewed/Approved	By:	_ Date:		
	Reviewed/Approved	By:	Date:		

SITTE DOLTED COLDING

TO MAL



IP/0/B/1601/03

DUKE POWER COMPANY

OCONEE NUCLEAR STATION

ENVIRONMENTAL EQUIPMENT CHECKS

1.0 Purpose

 To furnish a procedure for documentation of weekly data collection and equipment functional checks.

2.0 References

2.1 Duke Dwg. 0-714-D, 0-829, 0-829-A

- 3.0 Test Equipment Required
 - 3.1 Portable psychrometer
- 4.0 Prerequisites (Sign-offs on Enclosure 11.1)
 - 4.1 This procedure should not be performed during a gaseous waste release period.
 - 4.2 Supervisor has reviewed and initialed all portions of this procedure which are not applicable to the activity being performed. The Supervisor's review is not required if the procedure specifies sections to be omitted.
 - 4.3 Verify that all changes in the Control Copy are incorporated in the Working Copy.
- 5.0 Limits and Precautions
 - 5.1 Use proper precautions while working with components that have high voltage or high pressure present.
- 6.0 Unit Status

N/A

7.0 General Description

The environmental equipment monitors the following parameters and records the information on individual chart recorders; wind speed, wind direction, air temperature, humidity, and amount of rainfall.

There are two meteorological monitoring stations for the wind speen and direction. Site #1 is located at the micro-wave tower and Site #2 is located adjacent to the river below Keowee discharge.



8.0 Major Components

9.0

	Description	Man. Ref.
8.1	Four Esterline Angus Series "A" Analog Recorders	
8.2	One Leeds and Northrup Speedomax H&W Multipoint Recorder	OM-267-514
8.3	Two Teledyne Geotech Series 40 Wind Speed Modules	OM-333-274
8.4	Two Teledyne Geotech Series 40 Wind Direction Modules	OM-333-275
8.5	Two Teledyne Geotech Series 40 AC Power Supplies	OM-333-276
8.6	One Leeds and Northrup 3-Lead Resistance Temperature Detector (RTD) Air Temperature System	
3.7	One Belfort Instrument Company Hygro- thermograph Recorder	
3.8	One Belfort Instrument Company weighing Rain Gauge Recorder	
Equi	pment Specifications	
Wind	1 Speed	0-30 mph \pm .04 mph (60 and 90 mph selectable ranges)
Wind	Direction	0-540 degrees ± 5.7°
Ambi	ent Air Temperature	-15 to $105^{\circ}F \pm 0.7^{\circ}F$
Temp	perature Differential	-30 to $30^{\circ}F \pm 0.9^{\circ}F$
Rair	ufall Gauge	0-12 in. ± .03 in. (0-6 in.) ± .06 in. (6-12 in.)

2 -

10.0 Procedure Instructions (Sign-offs on Enclosure 11.1)

NOTE: Use Control Room computer clock for all time recordings. Mark on charts all as found calibration points (R_Found, T_Found and F.S. Found) before adjustments are made. If adjustments are made, mark all as left calibration points (R_Left, T_Left and F.S. Left) on charts.

Perform as found string checks using the following procedure and complete Enclosure 11.3.a and b.



10.1 ONS Site 1

- Check recorder zero on wind speed and direction recorders by turning translator power off. Rotate charts slowly and individually for good trace. Verify positions on recorders and note time and date. Mark "R Found" on each chart beside the trace.
- Return power on translator and check wind speed and direction Lo Cal. by placing modules in the Lo Cal. position. Rotate charts slowly and individually for good trace. Verify positions on recorders. Mark "T_ Found" on each chart beside the trace.
- Place the wind direction module in the Hi Cal. position. Rotate chart slowly and verify position on recorder. Mark "F.S. Found" on each chart beside the trace.
- Place wind speed and direction modules in operate position. Verify normal response on recorders. Insure ink wells are full.
- Change the charts on recorders. Document start time and date on the charts.

10.2 ONS Site 2

- Place Control Room switch in the Lo position. Verify Lo Cal. positions on the wind speed and direction recorders. Rotate charts slowly and individually for good trace. Label chart "T, Found".
- Place Control Room switch in the Hi position. Verify Hi Cal. positions on the wind speed and direction recorders. Rotate charts slowly and individually for good trace. Label "F.S. Found".
- 3. Check recorder zero on wind speed and direction recorders by disconnecting field inputs in back of recorders and installing a jumper wire across the terminals. Label chart "R Found". Document time and date on charts. Rotate charts individually and slowly for good trace. Verify position on recorders.
- 4. Remove jumpers and reconnect field inputs to recorders.
- 5. Place Control Room switch to the operate position. Verify normal response on recorders. Insure ink wells are full.
- 6. Change charts on recorders. Document starting time and date on charts.

If all string checks are within tolerance, remove and staple together the front approval sheet, list of enclosures, and sign off sheet. Insure all equipment mentioned above is returned to service and continue.

If all string checks are not within tolerance, continue with Section 10.6.



10.3 Air Temperature Recorder

1. Turn off chart recorder. Document time and date on chart.

- 4 -

- Remove weeks run of chart paper. Replace chart paper as necessary.
- Restart chart and recorder. Verify proper response. Document time and date on chart.

NOTE: If there are any problems or you think there may be something wrong with the air temperature system, please note this on the chart from Step 2.

10.4 Hygro-Thermograph Recorder

- Check the temperature with a thermometer and humidity with a portable psychrometer.
- 2. Remove old chart from recorder noting time and date on chart.
- Change the chart on the hygro-thermograph recorder. Document start time and date on chart.
- Prepare recorder for another week of operation by rewinding clock mechanism, inking the pens, and aligning chart for correct time. Document the temperature and humidity readings from Step 1 on chart.

If the temperature or humidity is found, upon comparison with a thermometer and psychrometer, to be incorrect proceed to Section 10.6 for adjustment procedures.

10.5 Rain Gauge Recorder

- 1. Open the sliding door and lift the pen from the chart by pulling the pen arm shifter away from the mechanism support column.
- Next remove the collector and empty the bucket slowly from the platform so that the gauge mechanism will not be subject to any sudden shock as the pen returns to the zero reading.
- 3. Replace the collector.
- Lift the chart cylinder and remove old chart noting time and date on chart.
- 5. Change the chart on the rain guage recorder. Document start time and date on chart.
- 6. Prepare recorder for another week of operation by rewinding clock mechanism, inking the pen, and aligning chart for correct time.
- Verify pen on zero point. If not, adjust the zero knob until zero is obtained.

- Ink the pen, set the chart to correct time. Press the pen arm shifter all the way in and verify pen is making contact with chart.
- 9. Close sliding door.

10.6 Calibration Procedures

- A. Wind System
 - To adjust recorder zero, ensure power supply on translator is off. The zero adjustment arm is located on the inside bottom of recorder under the chart take-up reel. Make adjustments until recorder reads zero. Mark "R Left" on chart beside the trace after the final adjustment.
 - 2. To adjust the translator full scale, turn the power supply on and the translator mode switch to the Hi Cal position. Adjust the Hi Cal adjusting screw on front of module to achieve a full scale reading. Mark "F.S. Left" on chart beside the trace after the final adjustments.
 - 3. To adjust the translator zero, turn the mode switch to the Lo Cal position. On the wind direction module adjust the Lo Cal adjusting screw on the front of the module to obtain a zero reading. Mark "T_Left" on chart beside the trace after the final adjustment.
 - NOTE: The translator zero for the wind speed module should be performed in a lab since the adjustments necessary must be made internal of the translator and requires a considerable amount of time and accuracy.

If translator zero for wind speed exceeds tolerances contact the E.S.S. (Environmental Services Section).

B. Hygro-Thermograph Recorder

- If the temperature indication is found to be incorrect an adjustment may be made by turning the thumb screw nearest the front of the case until the thermometer and instrument pen are in agreement.
- 2. If the humidity is found to be incorrect, wet the hairs by stroking them gently with a camel hair brush wetted with distilled water. Continue this wetting for several minutes until no further rise of the pen can be observed. When a stable position is reached, set the humidity pen to read 92% by adjusting the thumbscrew in the base of the instrument located beside the temperature setting

- 5 -

screw. Do not set the pen to read 100% humidity. No amount of artificial wetting seems to wet the hair to the same extent as actual exposure to saturated air. If after several checks an error is found in humidity indication, the rear adjustment thumbscrew can be used to correct error per psychrometer reading.

10.7 As Left String Checks (Enclosure 11.5a and b)

Perform as left string checks as required due to maintenance action or calibration in Section 10.2 for all strings affected following procedure steps in Section 10.1.

11.0 Enclosures

- 11.1 Sign-Off Sheet
- 11.2 Reference Data (None)

11.3 As Found String Checks

11.3.a ONS Site 1

- 11.3.b ONS Site 2
- 11.4 Calibration Data Sheets (None)

11.5 As Left String Checks

11.5.a ONS Site 1 11.5.b ONS Site 2







ENCLOSURE	E 11.1
IP/0/B/16	501/03
SIGN-OFF	SHEET

Prerequisites	Date Begun
4.1	Date Completed
4.2	W.R.#
4.3	Unit #

Double Verification of Wires Removed and Connected

	Wires removed and jumpers	installed on input to recorder.
,10.2.2	Jumpers removed and wires	replaced string checks.
11.3.a	11.5.a	
11.3.b	11.5.b	

Performed By _____

Init. and DateNotified Instrument Supervisor that a tolerance of 2%
was exceeded on the following components:Init. and DateAn evaluation was made on the above problem(s) and the
following corrective action taken:

Remarks:

ENCLOSURE 11.3.a

IP/0/B/1601/03

AS FOUND INTEGRATED STRING

VERIFICATION DATA SHEET

Item	Wind, Speed & Direction	Test Equipment Us	ed
Mfg	Teledyne Geotech	Item	SN
Туре	Series 40		
Calibrat	ion Tolerance $W/S \pm 0.4$ mph; $W/D \pm 5.0$	and the second second second second	
System _	Environmental	a and an	
Span	W/S 0-30 mph; W/D 0-540°		

Location Upper Meteorlogical Site (ONS Site 1)

Input	Required Reading W/S	AS Found W/S	Required Reading W/D	AS Found W/D
Rz	0		0	
Lo Cal	0.6 ± .1 mph		0	
Hi Cal	N/A	N/A	Full Scale	

Equipment Removed From Service _____,____

Equipment Returned To Service _____,____





ENCLOSURE 11.3.b

IP/0/B/1601/03

AS FOUND INTEGRATED STRING

VERIFICATION DATA SHEET

Item	Wind,	Speed	&	Direction
------	-------	-------	---	-----------

Mfg Teledyne Geotech

Test Equipment Used

SN

Item

Type ____ Series 40

Calibration Tolerance W/S ± 0.4 mph; W/D ± 5.0

System Environmental

Span ____ W/S 0-30 mph; W/D 0-540°

Location Lower Meteorlogical Site (ONS Site 2)

Input	Required Reading W/S	AS Found W/S	Required Reading W/D	AS Found W/D	
Rz	0		0		
Lo Cal	0.6 ± .1 mph		0		
Hi Cal	N/A	N/A	Full Scale		

Equipment Removed From Service _____,

Equipment Returned To Service _____,



ENCLOSURE 11.5.b

IP/0/B/1601/03

AS LEFT INTEGRATED STRING

VERIFICATION DATA SHEET

Used

SN

Item	Wind, Speed & Direction	Test Equipment
Mfg	Teledyne Geotecii	Item
Т;ре	Series 40	
Calibrat	tion Tolerance $W/S \pm 0.4 \text{ mph}; W/D \pm 5.0$	
System _	Environmental	
Span	W/S 0-30 mph: W/D 0-540°	

Location Lower Meteorlogical Site (ONS Site 2)

.

Input	Required Reading W/S	AS Found W/S	Required Reading W/D	AS Found W/D
Rz	0		0	
Lo Cal	0.6 ± .1 mph		0	
Hi Cal	N/A	N/A	Full Scale	

1

Equipment Removed From Service _____,____

Equipment Returned To Service _____,



......

ENCLOSURE 11.5.a

IP/0/B/1601/03

AS LEFT INTEGRATED STRING

VERIFICATION DATA SHEET

Item	Wind,	Speed	&	Direction
				And the fee fee for the day of 1

Mfg Teledyne Geotech

Test Equipment Used

SN

Item

Type Series 40

Calibration Tolerance W/S ± 0.4 mph; W/D ± 5.0

System Environmental

Span _____W/S 0-30 mph; W/D 0-540°

Location Upper Meteorlogical Site (ONS Site 1)

Input	Required Reading W/S	AS Found W/S	Required Reading W/D	AS Found W/D
Rz	0		0	
Lo Cal	0.6 ± .1 mph		0	
Hi Cal	N/A	N/A	Full Scale	

Equipment Removed From Service _____,

Equipment Returned To Service _____,



2 . . .

