

LER #: 50-366/1982-042
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1982-042

On April 27, 1982, with Hatch Unit 2 in cold shutdown for the refueling/maintenance outage, operations personnel noticed that the "A" loop RHR and RHR Service Water control room flow indicators (2E11-FI-R603A, 2E11-FI-R602A) were inoperable. As the "A" loop RHR and RHRSW flow indicators were inoperable, the "A" loops of RHR and RHRSW were declared inoperable. The "A" loop of RHR, RHRSW had been operating in the shutdown cooling mode with the "B" loop of RHR inoperable for Local Leak Rate Testing.

Investigation by maintenance personnel revealed that the spring clips on the fuse block energizing the control room "A" loop RHR, RHRSW flow indicators were loose. The spring clips on the fuse block, located in control room panel 2H11-P613, were tightened and the flow indicators returned to service. The "A" loop of RHR and RHRSW were declared operable on 4-27-82. There was no impact upon Unit 1. This is a non-repetitive event. The health and safety of the public was not affected by this event.