

THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

Serving The Best Location in the Nation

Dalwyn R. Davidson SYSTEM ENGINEERING AND CONSTRUCTION.

May 28, 1982

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> RE: Perry Nuclear Power Plant Docket Nos. 50-440; 50-441 Interim Report on Cable Tray and Conduit Support Welding Deficiencies [RDC 56(82)]

Dear Mr. Keppler:

This letter will serve as the interim report pursuant to 10CFR50,55(e) concerning defective welds for cable tray and conduit supports. On April 30, 1982, Mr. E. Riley of The Cleveland Electric Illuminating Company notified Mr. H. Wescott of your office that this problem was being evaluated.

This report contains a description of the deficiency, the background information, and the corrective action, including the evaluation currently being undertaken to determine the extent of the problem and the planned date for filing of the final report.

Description of Deficiency

The weld symbol type Y(t), as specified by the Engineer in fabrication of certain cable tray and conduit hanger joint configurations, has not been properly fit-up nor has weld preparation been completed in accordance with AWS standards. The areas of major concern address lack of the minimum weld penetration and the proper 45° fit-up bevel.

Background Information

This welding problem and interpretation of the Y(t) weld symbol was initially identified and addressed by the Construction Quality Section on February 21, 1980, per Action Request No. 207, with a corrective action plan issued on March 24, 1980. The corrective action plan required that an expanded inspection program be conducted with the completed inspection documentation submitted to the Engineer for evaluation/approval prior to close-out of the AR. This

206070450 820528

activity was completed on March 11, 1982. Evaluation of these findings by the Engineer resulted in issuance of Nonconformance Report Nos. CQC 2443 and CQC 2444 and the subsequent reporting of this matter as a potential significant deficiency.

Corrective Action

The immediate concerns regarding the interpretation, proper joint preparation, and fit-up requirements have been discussed with the Contractor and the Contractor has imposed a Stop Work regarding this activity. Pending resolution of these items, which require training of craft and QC personnel and minor revisions to the work procedures, the Contractor will reinstate welding operations to satisfy the Y(t) weld joint requirements. This action is expected to be completed by June 1, 1982.

In the interim, the Engineer (GAI) is currently analyzing all supports with a Y(t) weld on a case-by-case basis to determine the adequacy of the existing weld. The approach to the analysis will consist of three parts: 1) The first part of the analysis will conservatively assume that no strength is provided by the Y(t) weld portion of the joint. A typical joint is made up of a combination of a Y(t) weld and fillet weld. If the joint does not pass with this assumption, the contractor will be required to provide an "as-built" condition of each joint. 2) The Engineer will analyze the "as-built" condition to see if the joint is structurally adequate. If the joint still does not provide adequate strength, 3) The joint is then either reworked or repaired as required.

Clarification and subsequent acceptance or required rework resulting from the evaluation outlined above will be issued on revisions to the existing Nonconformance Reports.

It is anticipated that the final review and the required rework/repair of the necessary supports will be completed by March 31, 1983, at which time we will submit our final report.

frued L. Fanell for

Vice President

System Engineering and Construction

DRD: pab

cc: Mr. M. L. Gildner NRC Site Office

> Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

U.S. Nuclear Regulatory Commission c/o Document Management Branch Washington, D.C. 20555