LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N Y 1 A F 1 2 0 0 - 0 0 0 - 0 0 0 3 4 1 1 1 1 4 57 CAT 58 5
REPORT L 6 0 5 0 0 0 3 3 3 7 0 3 0 6 8 2 3 0 4 10 5 8 2 3 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During routine startup operations, the 100° F/hour heatup rate limit of TS 3.6.A.1
$[0][3]$ was exceeded by approximately 6° during a one (1) hour period. The heatup rate,
prior to and after the period in question, was well below the TS limit. No
ols significant hazard existed.
0 6 1
0 7 1
0 8
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE SUBCODE
Z Z 10 A 13 Z Z Z Z Z Z Z (14) Z (15) Z (16) SEQUENTIAL OCCUPATION REVISION
17 REPORT NO. 17 PE NO. 17
ACTION FUTURE SEFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. PRIME COMP SUPPLIER MANUFACTURER X 18 X 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
Personnel error was the cause. Personnel immediately reduced power to bring the
heatup rate to within TS limits. An engineering evaluation has been requested to
determine what effect, if any, the event has had on reactor vessel life. Personnel
involved were counselled and the event will be incorporated into the Licensed
Operator Requalification Program. LER 81-066 is a related event.
7 8 9 ACCILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION (32) 1 15 C (28) 0 0 1 (29) NA B (31) Surveillance
7 8 9 10 12 13 44 45 46 80 ACTIVITY CONTENT (36)
1 6 Z 3 Z 3 Z 34 NA NA 44 45 NA 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 8 9 PERSONNEL INJURIES NA 80
1 3 0 0 0 0 40 NA NA
LOSS OF OR DANAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY (A) B204150281 820405 PDR ADDCK 05000333
PDR w. Verne Childs 215-342-3840