

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of)

LONG ISLAND LIGHTING COMPANY)
(Shoreham Nuclear Power Station, Unit 1))

) Docket No. 50-322 O.L.
)
)
_____)

DIRECT TESTIMONY OF MARC W. GOLDSMITH

ON BEHALF OF SUFFOLK COUNTY REGARDING

SUFFOLK COUNTY CONTENTION NO. 9 - ECCS PUMP BLOCKAGE

April 13, 1982

SUMMARY OUTLINE OF SUFFOLK COUNTY

CONTENTION 9 TESTIMONY*

Suffolk County contends that the potential sources of Emergency Core Cooling pump suction strainer blockage at Shoreham have not been adequately analyzed with respect to their ability to cause suction strainer blockage during an accident. LILCO has not adequately demonstrated that drywell piping and equipment insulation loosened and/or damaged during a postulated loss-of-coolant accident will not unduly degrade the ECCS flow, preventing adequate core cooling.

This testimony outlines the basis for the Contention 9 concern, and identifies the specific problems and the actions necessary to remedy them. LILCO and Staff have assumed in an accident that the suction strainers would be no more than 50 percent blocked and will demonstrate adequate cooling capability even with 50 percent blockage prior to fuel load. However, neither LILCO nor the Staff have performed a systematic analysis to demonstrate that the 50 percent blockage assumption is appropriate. Absent a survey and analysis of drywell insulation which identifies the sources, quantities and characteristics of debris available for blockage such that the 50 percent blockage assumption is assured of being conservative, LILCO will not have demonstrated compliance with 10 CFR Part 50, Appendix A, General Design Criterion 35.

Exhibits*

1. NUREG-0606, Vol. 3, No. 4, November 16, 1981, pgs. 36 & 37.

*/ ASLB Memorandum and Order, March 15, 1982, p. 30.

April 13, 1982

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of)

LONG ISLAND LIGHTING COMPANY)
(Shoreham Nuclear Power Station, Unit 1))

Docket No. 50-322 O.L.

DIRECT TESTIMONY OF MARC W. GOLDSMITH

REGARDING SUFFOLK COUNTY CONTENTION 9 -

ECCS PUMP BLOCKAGE

Q Please state your name, address, occupation, and qualifications.

A My name is Marc W. Goldsmith, and my business address is 400-1 Totten Pond Road, Waltham, Massachusetts. I am the President of Energy Research Group, Inc. My qualifications have been separately provided to the Board.

Q Would you please state the contention on which you are testifying?

A Suffolk County Contention 9 reads as follows:

Suffolk County contends that LILCO has not adequately demonstrated that drywell piping and equipment insulation loosened and/or damaged during a postulated loss-of-coolant accident will not unduly degrade the ECCS flow through the ECCS suction strainers located in the suppression pool. Therefore, the Shoreham design does not satisfy 10 CFR 50, Appendix A, General Design Criteria 35.

Q What is the purpose of your testimony?

A The purpose of my testimony is to discuss the concern that Shoreham Emergency Core Cooling pump suction strainers may be blocked during an accident, thus preventing adequate core cooling and possibly leading to severe degradation of fuel. LILCO and the Staff have assumed that in an accident the suction strainers would be no more than 50 percent blocked and will have demonstrated adequate cooling capability even with such blockage prior to fuel load. However, neither LILCO nor the Staff to my knowledge has performed a systematic analysis to demonstrate that the 50 percent blockage assumption is appropriate. Therefore, a survey and analysis of drywell insulation should be made to determine the quantity of material available for blockage. Absent such analysis, LILCO will not have demonstrated compliance with GDC 35.

Q Please provide background on the ECCS pump suction blockage concern.

A The NRC in NUREG-0510 "Identification of Unresolved Safety Issues Relating to Nuclear Power Plants" revised and elevated the Containment Emergency sump issue to the highest priority as Generic Task A-43. Task Action Plan A-43 recognized this suction blockage problem initially, specifically with respect to containment emergency sump performance in pressurized water reactors and then expanded the concern to boiling water reactor suppression pool suction strainers.

During a loss-of-coolant accident, water is recirculated from the suppression pool back to the reactor through the emergency core cooling system pumps. These pumps take water through a suction strainer located in the suppression pool and pump the water back into the reactor or into the containment. This cooling is fundamental to the successful operation of both emergency core cooling systems (needed to cool the core) and the containment spray system (needed to reduce iodine and assist in maintaining containment integrity following a loss-of-coolant accident).

The potential sources of debris blockage of the suppression pool pump suction are equipment and pipe insulation in the drywell that may fail as a result of an accident. "In the event of a piping break, the subsequent violent release of the high pressure water in the reactor coolant system could rip off the insulation in the area of the break. This debris could then be swept into the sump, potentially causing damage." (NUREG-0510). Therefore, insulation (which is not classified as safety-related) may fail due to the impingement of high pressure water or steam within the drywell and that failed insulation may be carried through the downcomers into the suppression pool causing the strainers to be blocked.

General Design Criterion 35 of Appendix A to 10 CFR 50 requires that:

a system to provide abundant emergency core cooling shall be provided. A system safety function shall be to transfer heat from the reactor core following any loss of reactor cooling at a rate such that (1) fuel and clad damage that could interfere with continued effective core cooling is prevented and (2) clad metal-water reaction is limited to negligible amounts.

Suitable redundancy and components and features and suitable interconnections, leak detection, isolation, and containment capabilities shall be provided to assure that for onsite electric power system operation . . . the system safety function can be accomplished assuming a single failure.

This GDC specifies the need to assume a single failure. In this particular case, it could be a common mode failure that causes loosened insulation to fall into the suppression pool, blocking all of the suction strainers designed with the same size grids at roughly the same heights above the floor of the suppression pool, such that pump flow could be impeded or in fact shut off. This event, of course, would prevent compliance with GDC 35.

Q What are the specific problems of concern at Shoreham?

A At Shoreham, there are four residual heat removal pumps (LPCI mode), one high pressure coolant injection pump and two core spray pumps all of which take suction from the suppression pool. In addition, the reactor core isolation cooling pump suction strainer is also located in the suppression pool with a similar suction strainer arrangement (FSAR Section 6.3.2.20.2). In the event of a loss-of-coolant accident, blockage of these pump suctions could prevent adequate core cooling.

The specific concern is that there appears to be no basis for the choice of the 50% blockage assumed by LILCO as an appropriate design base for the strainers. The quantities, types and densities of insulation within the drywell of the Shoreham containment which might fail are not sufficiently known to determine the appropriateness of the strainer blockage assumption.

Q What actions are necessary to remedy the above problems?

A Since the prime source of material to plug the strainers is the piping and equipment insulation, it is necessary to inventory the quantity of this insulation in the Shoreham drywell and determine its potential failure probability and modes under accident conditions. This would determine whether the 50% assumption is appropriate.

In addition, an analysis of the insulation should be conducted to assure that there are either insufficient quantities, insufficient density, or too great a density for the particles to float into the strainer to assure that blockage would not exceed 50 percent or if not, to modify the 50% figure.

According to the status summary of Task Action Plan A-43, provided in NUREG-0606 Vol. 3, No. 4, Nov. 16, 1981, a calculational methodology has been developed for estimating quantities of debris generation due to a pipe break, and PWR plant specific calculations have been performed. The results show that plant specific characteristics may affect the blockage potential. This further indicates the need for this type of analysis at Shoreham.

Q What LILCO actions have you reviewed?

A I have reviewed LILCO commitment to verify the flow capability of both the HPCI and the RCIC pumps with the suction strainers 50% plugged during the preoperational test program (LILCO ltrs/SNRC-598 & SNRC-602). I have also reviewed the Response of LILCO to Suffolk County Interrogatories and to Suffolk County Second Set of Interrogatories, dated 3/26/82, where it states that LILCO correlated the strainer grid size with potential openings in RHR, RCIC, HPCI and containment spray nozzles to assure that any debris entering through the strainer would be smaller than the

nozzle sizes or any important pump equipment. I have also reviewed FSAR sections and responses to NRC questions. However, LILCO still needs to verify, pending the results of the preoperational tests, the quantity and characteristics of insulation that is potentially vulnerable to failure, thus resulting in suction strainer blockage.

Q What would satisfy the concerns expressed relative to ECCS suction strainer blockage?

A The concern can be resolved by LILCO's performing a systematic inventory of the drywell insulation to identify the sources, quantities and characteristics of debris available for blockage during a postulated loss-of-coolant accident. Such an inventory would be for the purpose of assuring that a strainer blockage assumption of 50 percent is conservative.

EXHIBIT 1

NUREG-0606, Vol. 3, No. 4

November 16, 1981, pgs 36 & 37

UNRESOLVED SAFETY ISSUES SUMMARY

AQUA BOOK

Manuscript Completed: November 1981
Date Published: December 1981

Prepared for: OFFICE OF NUCLEAR REACTOR REGULATION

Prepared by: OFFICE OF MANAGEMENT AND PROGRAM ANALYSIS
U.S. NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555



CONTAINMENT EMERGENCY SUMP PERFORMANCE (A-43)

AS OF WEEK ENDING NOVEMBER 16 1981

KEY PERSONNEL
 TASK MANAGER
 A. SIDKEL (D51) 224211

TASK REVIEWERS
 NAME BRANCH
 * ORN * REGR/31
 * NOKIAN * GIB/031
 M. BUTLER CBG/01

Our Bob's World
 MPA ANALYST
 D. SCHWARTZ 221108

SCHEDULED COMPLETION
 ORIGINAL Apr 8 1982
 CURRENT 11/16/82

*** PROBLEM DESCRIPTION**
 # Following a loss of Containment Accident (COA) by a PWR water piping system, the tank in the primary system made contact with the tank in the secondary system. During the injection mode, contact between the tanks was maintained for a period of time. The tanks were not designed to be in contact with each other. The tanks were not designed to be in contact with each other. The tanks were not designed to be in contact with each other.

*** ACRS INTERFACE INFORMATION**
 # The ACRS staff is kept abreast of findings and development on an informal basis. A list of findings on the accident findings and status of resolution is being maintained for December 1981.

*** TECHNICAL ASSISTANCE CONTRACTS**
 # The No. A123, "Containment Emergency Pump Performance" and the No. A124, "Containment Emergency Pump Performance" contracts are being funded by RES and NRR respectively. These contracts are being funded by the OIB Task Manager and these contracts are expected to be concluded in FY82.

*** RES INTERFACE INFORMATION**
 # None. UER A-43 being reviewed by the Grants Office Branch 10181.

*** FIN NO. CONTRACTOR OBLIGATED EXPENDED**

FIN NO.	CONTRACTOR	OBLIGATED	EXPENDED
FY 81			
# A123	Bechtel	\$128,000	\$188,000
# A124	Bechtel	\$120,000	\$148,000
		\$248,000	\$336,000
			\$207,000
			Total
			\$178,000 Planned
			\$190,000 Planned
			\$172,000 for subcontracted work, the difference is
			contracted work \$28,000

*** POTENTIAL PROBLEMS**
 # 1) OIB is in receipt of plant hardware & second hole (Boltchak B) and a plant layout drawing of connecting piping several plants (eg. Tanks 1 & 2, Tank 11, Boltchak B) has become a non-unionized plant.
 # 2) Issue of the NUREG on pump repair (Boltchak B) has become a non-unionized plant.
 # 3) The results of the NUREG on pump repair (Boltchak B) has become a non-unionized plant.
 # 4) The results of the NUREG on pump repair (Boltchak B) has become a non-unionized plant.

*** STATUS SUMMARY**
 # 1) ACRS Research Laboratory (ARL) has made positive to show very low levels of radionuclides in the "bottom section" being designed. The radionuclides are being tracked and will be reported to the OIB Task Manager during the 1982 testing completion period.
 # 2) Containment methodology for the quantities of debris generated during the test was not completed. The methodology and results have been submitted to RES, CB&I and NRR for review of the methodology. The comments regarding use in A-43 specific laboratory hardware are being developed. These results are being used for the assessment of the results of the test.
 # 3) The effect of an injection & particulate on pump performance is being assessed under Boltchak B. Although ACRS is being assessed under Boltchak B, the results of the test are being used for the assessment of the results of the test.
 # 4) The results of findings to date, & procedures attached, indicate that both resolution of UER A-43 in FY82 is feasible.

*** PROBLEM DESCRIPTION**
 # Following a loss of Containment Accident (COA) by a PWR water piping system, the tank in the primary system made contact with the tank in the secondary system. During the injection mode, contact between the tanks was maintained for a period of time. The tanks were not designed to be in contact with each other. The tanks were not designed to be in contact with each other. The tanks were not designed to be in contact with each other.

