

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

| | |
|---|---|
| 0 | 1 |
| 7 | 8 |

REPORT SOURCE

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|----|---------------|---|---|---|---|---|---|---|---|---|----|----|------------|---|---|---|---|----|----|-------------|---|---|---|--|----|
| L | 6 | 0 | 5 | 0 | - | 0 | 3 | 2 | 4 | 7 | 0 | 3 | 0 | 4 | 8 | 2 | 8 | 0 | 3 | 2 | 9 | 8 | 2 | 9 | | |
| 60 | 61 | DOCKET NUMBER | | | | | | | | | | 68 | 69 | EVENT DATE | | | | | 74 | 75 | REPORT DATE | | | | | 80 |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During routine surveillance, it was discovered that suppression chamber water level in-
0 3 | dicator, 2-CAC-LI-3342, located on the remote shutdown panel, indicated a level of
0 4 | -33". Actual level as read at the local indicator was -29.5". A similar event was
0 5 | reported in LER 2-82-2 on February 1, 1982. This event did not affect the health and
0 6 | safety of the public.

Technical Specifications 3.3.5.2, 6.9.1.9b

| | | | | | | | | | | | | |
|--------------|----------------------|-----------------------------|-----------------|-----------------------------|---|------------------------------------|--|----------------------------------|------------------|-------------------------|-------------------------|------------------------|
| 0 | 9 | SYSTEM CODE I C (11) | | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE I N S T R U (14) | | | | COMP. SUBCODE T (15) | VALVE SUBCODE Z (16) | |
| 7 | 8 | | | | | | | | | | | |
| (17) | LER/RQ REPORT NUMBER | EVENT YEAR 8 2 (21) (22) | | | SEQUENTIAL REPORT NO. 0 4 7 (24) (25) (26) | | | OCCURRENCE CODE 0 3 (28) (29) | | REPORT TYPE L (30) | | REVISION NO. 0 (32) |
| | | | | | | | | | | | | |
| ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS (22) | | | | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER | |
| X (18) | C (19) | Z (20) | Z (21) | 0 0 0 0 (37) (38) (39) (40) | | | | Y (23) | Y (24) | N (25) | R 3 6 9 (26) | |
| 23 | 34 | 35 | 36 | 37 | | | | 41 | 42 | 43 | 44 | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A change in trickle flow to the wet reference leg of the indicator transmitter

1 1 2-CAC-LT-3342, Model No. 1152, caused the transmitter to be out of calibration. The

1 2 trickle flow was properly established, the transmitter was calibrated and the indicator

1 3 was returned to service. Plant modification 80-78 has been developed to eliminate

1 4 further similar events. Installation is scheduled for the next refueling outage.

| FACILITY STATUS | | | | | | | | | | % POWER | | | | | | | | | | OTHER STATUS | | | | | | | | | | METHOD OF DISCOVERY | | | | | | | | | | DISCOVERY DESCRIPTION | | | | | | | | | |
|-------------------------------|---|---|----|------------|--------|-----|-------|----------|-----|---------------------|----|-----------------------|--|--|--|--|--|--|--|--------------------|--|--|--|--|--|--|--|----|--|---------------------|--|--|--|--|--|--|--|--|--|-----------------------|--|--|--|--|--|--|--|--|--|
| 1 | 5 | E | 28 | 0 | 8 | 0 | 29 | NA | 30 | A | 31 | Operator Surveillance | | | | | | | | | | | | | | | | | | 32 | | | | | | | | | | | | | | | | | | | |
| ACTIVITY CONTENT | | | | | | | | | | RELEASED OF RELEASE | | | | | | | | | | AMOUNT OF ACTIVITY | | | | | | | | | | LOCATION OF RELEASE | | | | | | | | | | | | | | | | | | | |
| 1 | 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36 | | | | | | | | | | | | | | | | | | | 36 | | | | | | | | | | | | | | | | | | | | | |
| PERSONNEL EXPOSURES | | | | | | | | | | NUMBER | | | | | | | | | | TYPE | | | | | | | | | | DESCRIPTION | | | | | | | | | | | | | | | | | | | |
| 1 | 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 | | | | | | | | | | | | | | | | | | | 39 | | | | | | | | | | | | | | | | | | | | | |
| PERSONNEL INJURIES | | | | | | | | | | NUMBER | | | | | | | | | | DESCRIPTION | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | 8 | 0 | 0 | 0 | 40 | NA | 41 | NA | 42 | | | | | | | | | | | | | | | | | | | 41 | | | | | | | | | | | | | | | | | | | | | |
| LOSS OF OR DAMAGE TO FACILITY | | | | | | | | | | TYPE | | | | | | | | | | DESCRIPTION | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | 9 | Z | 42 | NA | 43 | NA | 44 | NA | 45 | | | | | | | | | | | | | | | | | | | 43 | | | | | | | | | | | | | | | | | | | | | |
| PUBLICITY | | | | | | | | | | ISSUED | | | | | | | | | | DESCRIPTION | | | | | | | | | | NRC USE ONLY | | | | | | | | | | | | | | | | | | | |
| 2 | 0 | N | 44 | 8204160203 | 820329 | PDR | ADOCK | 05000324 | PDR | | | | | | | | | | | | | | | | | | | 45 | | | | | | | | | | | | | | | | | | | | | |

M. J. Pastva, Jr.
NAME OF PREPARER _____

PHONE: (919) 457-9521

LER ATTACHMENT - RO #2-82-47

Facility: BSEP Unit No. 2

Event Date: March 4, 1982

As a result of similar events involving this type of instrumentation and post-TMI requirements, a plant modification package (80-79 for Unit No. 1 and 80-78 for Unit No. 2) has been developed. This modification will install a condensing pot in the reference leg in order to increase the accuracy and reliability of these instruments, and remove the requirement to have flow in the reference leg to ensure that it is full.