* .	LICENSEE EVENT REPORT
	CONTROL BLOCK: [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	N C B E P 1 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 1 5 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 - 0 3 2 5 0 0 3 0 4 8 2 8 0 3 2 9 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During plant operation, while performing the calibration of RHRSW differential
0 3	pressure instrumentation located on the remote soutdown panel, PT-55.9PC, it was
0 4	discovered that the output of RHRSW d/P transmitter, 1-E11-PDT-NOO2BX, remained
0 5	constant regardless of the input signal. As a result, the transmitter and its
0 6	associated indicator, 1-Ell-PDI-3344, were declared inoperable in accordance with
0 7	T.S. This event did not affect the health and safety of the public.
08	Technical Specifications 3.3.5.2, 6.9.1.9b  SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE S
	17   REPORT   21   22   23   24   26   27   28   29   30   31   31   32   33   34   34   36   36   36   36   37   37   40   41   31   42   43   42   43   43   44   47   47   6   6   6   6   6   6   6   6   6
rice trans	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  A failure of the transmitter sensor module occurred due to corrosion of the module
110	
	diaphragm resulting in the constant transmitter output signal. The sensor module was
1 2	replaced. The transmitter, Model No. 1152, was calibrated and the PT was satisfac-
1 3	terily completed. Plant documentation does not show any prior history of similar
	events involving this instrument. No further corrective action is required or planned.  BO  FACILITY STATUS  POWER  OTHER STATUS  OTHER STATUS
1 6	BO TO THE
1 7	9 PERSONNEL INJURIES NA BO NA DESCRIPTION 41
7 8	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	PUBLICITY ISSUED DESCRIPTION 45
7 8	NA See 59 80 5 80 5 80 5 80 5 80 5 80 5 80 5 8
	BUONE (919) 457-9521