

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 6  
 2 1 A L B R F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
 8 9 14 15 25 26 30 37 CAT 52  
 LICENSE CODE LICENSE NUMBER LICENSE TYPE

REPORT SOURCE L 6 0 5 0 0 0 2 5 9 7 0 3 0 8 8 2 6 0 4 0 5 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

1	2	During normal operation the unit operator observed reactor water indicator
1	3	LI-3-46A reading 0 inches. Other indicators showed water level to be normal.
0	4	LI-3-46A was declared inoperable. A 30-day LCO was entered per Tech Spec
0	5	Table 3.2.F. Redundant indicator LI-3-46B was operable and there was no
0	6	danger to the health or safety of the public.

SYSTEM CODE I B 11		CAUSE CODE X 17		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14				COMP SUBCODE I 15		VALVE SUBCODE Z 16			
EVENT YEAR 8 2 23		SEQUENTIAL REPORT NO. 0 1 7 26		OCCURRENCE CODE 0 3 29		REPORT TYPE L 30		REVISION NO. 0 32							
ACTION FUTURE TAKEN ACTION Z 18 Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRD 1 FORM SUB. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER Y 0 1 0 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

LI-3-46A, Yarway model 4455, level indicator signal cable was found unplugged in the rear of panel 9-5. When LI-3-46A was placed in service the level indication was the same as LI-3-46B. This loss of indication is considered random and no recurrence control is planned.

1 1 1 8 9 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 OTHER STATUS 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 METHOD OF DISCOVERY 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 DISCOVERY DESCRIPTION 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 Operator Observation 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 LOCATION OF RELEASE 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500

PERSONNEL EXPOSURES									
NUMER			TYPE		DESCRIPTION				
1	2	3	4	5	6	7	8	9	10
1	2	3	0	0	0	1	Z	36	NA

PUBLICITY		NBC USE ONLY	
ISSUED	DESCRIPTION		
N 44	NA		

8204160564 820405  
PDR ADCK 05000259  
S PDR

. T. Chambers

PHONE (205) 729-8100

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8217 Technical Specification Involved Table 3.2.F

Reported Under Technical Specification 6.7.2.b.2 \* Date Due NRC 4/6/82

Event Narrative:

Units 1 and 2 normal operation, unit 3 in refueling outage. Unit 1 was affected by this event. It was noted by the unit operator that LI-3-46A was reading 0 inches. All other indications of reactor water level indicated the true level to be about 33 inches. The unit operator notified the assistant shift engineer who initiated corrective action. Upon investigation, it was discovered that the signal cable to LI-3-46A had become unplugged in the rear of panel 9-5 resulting in loss of indication. A 30-day LCO of T.S. Table 3.2.F was entered. When the plug was reinserted LI-3-46A indicated normally (same as other indications). LI-3-46B is a redundant indication of reactor water level and remained operable throughout this event. There was no danger to the health or safety of the public, plant employees or equipment at any time because redundant indications of reactor water level were available and operable. Reason for signal cable being unplugged cannot be determined.

\* Previous Similar Events:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: JRP