LICENSEE EVENT REPORT

CONTROL BLOCK:
0 1 N C B E P 2 2 0 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 5 LICENSEE CODE 14 15 LICENSE NUMBER 26 LICENSE TYPE 30 57 CAT 58
CON'T O 1 REPORT L G O 5 O - O 3 2 4 7 O 3 O 2 8 2 8 O 3 2 9 8 2 9
o 3 control rod 06-43 was received. A check of the rod's hydraulic control unit (HCU)
[0]4] revealed an accumulator pressure of 650 psig. The affected accumulator was then
[0]5 declared inoperable in accordance with technical specifications. This event did not
o 6 affect the health and safety of the public.
07
Technical Specifications 3.1.3.5, 6.9.1.9b
SYSTEM CAUSE COMPONENT CODE SUBCODE
The low accumulator pressure occurred due to a valve packing leak on the accumulator
nitrogen charging inlet isolation valve, VIII. The valve packing was adjusted to
eliminate the leak and the accumulator was charged to a pressure of 1100 psig and
returned to service within one hour of the event discovery.
TT4 L 2 8 9 FACILITY (30) METHOD OF 80
STATUS & POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION (32) 1 6 E 28 0 5 8 29 NA A 31 Operational Event
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA PERSONNEL EXPOSURES AND 10 11 12 13 44 45 46 15
1 7 0 0 0 0 37 Z 38 NA NA
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 1 8 0 0 0 0 0 NA
7 8 9 11 12 LOSS OF DR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 1 9 Z 42 NA
80 NRC USE ONLY 8204160584 820329 PDR ADDCK 05000324 PDR S PDR ADDCK 05000324 S PDR ADDCK 05000324
M. J. PASTVA, JR.