

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | S | G | S | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T REPORT SOURCE: L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 0 | 2 | 1 | 5 | 8 | 2 | 8 | 0 | 4 | 0 | 1 | 8 | 2 | 9

02 | At 1100 hours, February 15, 1982, the Control Operator noticed that the fire alarm
03 | for the 84' Elevation, Charging Pump Area had annunciated on the LRP5 Fire Zone
04 | panel, but the coded audible alarm did not sound. The fire alarm was declared
05 | inoperable and Action Statement 3.3.3.6 was entered.

09 | SYSTEM CODE: A | B | 11 | CAUSE CODE: E | 12 | CAUSE SUBCODE: B | 13 | COMPONENT CODE: A | N | N | U | N | C | 14 | COMP SUBCODE: Z | 15 | VALVE SUBCODE: Z | 16

17 | LER RO REPORT NUMBER: 8 | 2 | 21 | EVENT YEAR: 8 | 2 | 22 | SEQUENTIAL REPORT NO.: 0 | 1 | 1 | 24 | OCCURRENCE CODE: 0 | 3 | 28 | REPORT TYPE: X | 30 | REVISION NO.: 1 | 32

10 | The control circuit relay from the 24 hour timer in the Miscellaneous Signal Cabinet
11 | was sticking. The audio/test switch on the timer was cycled, the relay cleared, and
12 | the coded audible alarm functioned properly. At 1420 hours, February 15, 1982
13 | Action Statement 3.3.3.6 was terminated. Subsequently, a relay was discovered
14 | loose in its socket and reseated. (81-122)

15 | FACILITY STATUS: H | 28 | % POWER: 0 | 0 | 0 | 29 | OTHER STATUS: N/A | 30 | METHOD OF DISCOVERY: B | 31 | DISCOVERY DESCRIPTION: Surveillance Test | 32

16 | ACTIVITY CONTENT RELEASED OF RELEASE: Z | 33 | Z | 34 | AMOUNT OF ACTIVITY: N/A | 35 | LOCATION OF RELEASE: N/A | 36

17 | PERSONNEL EXPOSURES NUMBER: 0 | 0 | 0 | 37 | TYPE: Z | 38 | DESCRIPTION: N/A | 39

18 | PERSONNEL INJURIES NUMBER: 0 | 0 | 0 | 40 | DESCRIPTION: N/A | 41

19 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z | 42 | DESCRIPTION: N/A | 43

20 | PUBLICITY ISSUED DESCRIPTION: N | 44 | DESCRIPTION: N/A | 45 | PDR ADOCK 05000272 | 68 | 69 | NRC USE ONLY

GPO 917-926