



LER No.: 50-321/1982-050  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket No.: 50-321

Narrative Report  
for LER 50-321/1982-050

On May 14, 1982, with the reactor shutdown and in the refuel mode due to solvent intrusion, the IRM functional test, HNP-1-3052, was last performed on 5-5-82. The next weekly surveillance should have been done by 5-12-82 midnight, but was performed approximately 34 hours later. Tech. Specs. Section 4.1-1 Item 3 requires the test to be performed weekly during refueling or fuel movement. Public health and safety was not affected. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-321/1981-116.

The cause of the event was personnel error. The procedure, HNP-1-3052, IRM Functional Test, was performed satisfactorily upon discovery and the equipment (IRM's) was returned to service. Personnel involved in the performance of daily surveillance were counseled on the importance of timely performance of procedures.