

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C | A | D | I | C | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 5 | 7 | 0 | 3 | 3 | 0 | 8 | 2 | 8 | 0 | 6 | 1 | 0 | 7 | 8 | 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | Prior to fuel load, during normal surveillance testing, the Steam Generator
03 | Blowdown Tank Liquid Radiation Monitor RM-23 failed the quarterly functional
04 | test required by Technical Specification 4.3.3.9.1. Subsequent investiga-
05 | tion revealed that the photo multiplier tube had failed. Technical Speci-
06 | fication Action Statements were satisfied. This event has in no way affected
07 | public health and safety, and is reportable per Technical Specification
08 | 6.9.i.13.b.

09 | M | I | C | 11 | E | 12 | F | 13 | I | N | I | S | T | R | U | 14 | E | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
17 | LER/RO REPORT NUMBER | 18 | 2 | 19 | - | 20 | 0 | 1 | 5 | 21 | / | 22 | 0 | 3 | 23 | X | 24 | - | 25 | 1 |
26 | L | 27 | Z | 28 | Z | 29 | 0 | 0 | 0 | 0 | 30 | N | 31 | N | 32 | L | 33 | H | 0 | 6 | 5 | 34
35 36 37 38 39 40 41 42 43 44 45 46 47 48
EVENT YEAR SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Photomultiplier tube failed due to end of lifetime. Manufacturer states
11 | tube life is about 5 years. Tube was manufactured approximately 8 years
12 | ago. Just prior to receiving the Operating License, RM-23 was released
13 | to operations from construction; channel calibrations required by Technical
14 | Specifications will now detect incipient detector failures.

15 | B | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Routine Surveillance Testing | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36 | LOCATION OF RELEASE | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL INJURIES NUMBER DESCRIPTION

19 | Z | 42 | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 | N | 44 | NA | 45 | 8206210160 820607 PDR ADOCK 05000275 PDR
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER W. B. Scott PHONE (805) 595-7351