

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I I D C C I I 2 0 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 _____ 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58

CON'T
0 1 REPORT SOURCE 60 61 0 5 0 0 0 3 1 5 7 0 5 2 4 8 1 2 8 0 6 1 8 8 2 9
7 8 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 DURING NORMAL OPERATION, THE CONTAINMENT AIR PARTICULATE RADIATION MONITORING SYSTEM
0 3 (R-11) FAILED TO THE LOWER END OF THE METER INDICATING SCALE AND BEGAN OPERATING ERRATI-
0 4 CALLY. R-11 WAS DEENERGIZED AND DECLARED INOPERABLE AT 1145 HOURS ON MAY 24, 1982.
0 5 THIS EVENT IS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.3.2.1 TABLE
0 6 3.3-3, 3.3.3.1 AND 3.4.6.1. HEALTH AND SAFETY OF THE PLANT WAS NOT AFFECTED.
0 7 _____
0 8 _____

0 9 SYSTEM CODE 9 10 B B 11 CAUSE CODE 11 E 12 CAUSE SUBCODE 12 G 13 COMPONENT CODE 13 I N S T R U 14 COMP. SUBCODE 19 E 15 VALVE SUBCODE 20 Z 16
17 LER/RO REPORT NUMBER 21 8 2 22 EVENT YEAR 23 - 24 0 4 2 25 SEQUENTIAL REPORT NO. 26 27 [] 28 0 3 29 OCCURRENCE CODE 30 L 31 [] 32 REVISION NO. 33 C 18 34 Z 19 35 Z 20 36 Z 21 37 0 0 0 0 40 HOURS 41 N 23 42 Y 24 43 N 25 44 A 5 8 7 47 26 COMPONENT MANUFACTURER
ACTION TAKEN 33 C 18 34 Z 19 EFFECT ON PLANT 35 Z 20 SHUTDOWN METHOD 36 Z 21 ATTACHMENT SUBMITTED 41 N 23 PRIME COMP. SUPPLIER 43 N 25
FUTURE ACTION 34 Z 19

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 INVESTIGATION FOUND THAT THE LOW VOLTAGE DC POWER SUPPLY ASSOCIATED WITH R-11, HAD
1 1 HIGH AC RIPPLE ON THE OUTPUT CAUSING THE SYSTEM TO OPERATE ERRATICALLY. THE LOW VOLT-
1 2 AGE DC POWER SUPPLY, MANUFACTURED BY AUL INSTRUMENTS, MODEL PSD-15 WAS REPLACED. THE
1 3 SYSTEM WAS VERIFIED TO BE OPERATING CORRECTLY AND RETURNED TO SERVICE AT 1515 HOURS ON
1 4 MAY 24, 1982. NO FURTHER ACTION IS PLANNED.

1 5 FACILITY STATUS 8 E 28 9 10 1 0 0 0 29 11 NA 12 OTHER STATUS 30 METHOD OF DISCOVERY 45 B 31 46 OPERATOR OBSERVATION 47 32 DISCOVERY DESCRIPTION 80

1 6 ACTIVITY CONTENT 8 Z 33 9 10 Z 34 11 NA 12 AMOUNT OF ACTIVITY 35 13 NA 14 LOCATION OF RELEASE 36 80

1 7 PERSONNEL EXPOSURES 8 0 0 0 37 9 10 Z 38 11 NA 12 DESCRIPTION 39 80

1 8 PERSONNEL INJURIES 8 0 0 0 40 9 10 NA 11 DESCRIPTION 41 80

1 9 LOSS OF OR DAMAGE TO FACILITY 8 Z 42 9 NA 10 DESCRIPTION 43 80

2 0 PUBLICITY 8 N 44 9 NA 10 DESCRIPTION 45 80
ISSUED DESCRIPTION 45
8206240275 820618
PDR ADOCK 05000315
S PDR

NAME OF PREPARER R. A. Palmer PHONE 616-465-5901

NRC USE ONLY

GPO 41 7-826

SUPPLEMENT TO LER# 82-041/03L-0

SUPPLEMENT TO EVENT DESCRIPTION:

THE UNIT WAS IN THE INITIAL STAGES OF DILUTION DURING UNIT STARTUP AND THE LOW FLOW FEEDWATER MODIFICATION WAS BEING UTILIZED TO SUPPLY THE SMALL QUANTITIES OF HEATED FEEDWATER NEEDED TO MEET SYSTEM REQUIREMENTS.

SEAT LEAKAGE OF FRV-220, #12 STEAM GENERATOR FEEDWATER REGULATING VALVE, PREVENTED ADEQUATE CONTROL OF FEED TO THE SYSTEM. FMO-202, THE #12 STEAM GENERATOR FEEDWATER ISOLATION VALVE, WAS UTILIZED TO REGULATE FEEDWATER FLOW. DURING CYCLING TO MAINTAIN THE DESIRED FEED FLOW CONTROL, THE VALVE FAILED AT APPROXIMATELY 40% OPEN.

AUXILIARY FEED WAS PLACED IN SERVICE. THE VALVE WAS REPAIRED, TESTED, AND MADE AVAILABLE FOR SERVICE. STARTUP OPERATIONS WERE THEN RESUMED. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.