LICENSEE EVENT REPORT

EIGENSEE EVENT HEFORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M D C C N 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58 5
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 1 8 7 0 5 2 2 8 2 8 0 6 2 1 8 2 9
At 0830, during normal plant operation, pressurizer level deviated
slightly from the design program level by more than +/-5% due to an
apparent malfunction of the Reactor Regulating System (T.S. 3.4.4).
Pressurizer level control was shifted to the redundant channel
which returned to level to within +/-5% of the program level at
0855. This is not a repetitive event.
08
SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
9 10 11 12 13 18 19 20 REVISION REPORT NO. 17 REPORT 8 2 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER 2 9 9 9 9 9 9 9 9 9
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) No obvious cause was found for the pressurizer level deviation. The
symptoms indicated a possible bad contact in the Reactor Regulating
System selector switch. Troubleshooting indicated no problem with
the selector switch Preventive action will be to replace the switch
during the Fall refueling outage.
7 8 9 FACILITY STATUS TO BE 28 10 18 15 29 NA TO BE 28 10 12 13 TO
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 NA NA NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA 44 45 NA BO RELEASE 36 NA BO RELEASE 36 NA BO RELEASE 36 NA NA NA NA NA NA NA NA NA N
1 7 0 0 0 37 Z 38 NA
1 8 9 11 12 NA NA
1 9 Z 42 NA
PUBLICITY SSUED DESCRIPTION 45 NA S PDR ADOCK 05000318 PDR ADOCK 05000318 PDR ADOCK 05000318
NAME OF PREPARER M. A. Junge/L. F. Basso PHONE: 301-269-4969/4933