

RECEIVED
JUN 16 1982

ARIZONA



PUBLIC SERVICE COMPANY

STA. 3003

P.O. BOX 21666 - PHOENIX, ARIZONA 85036

June 16, 1982

ANPP-21209-GHD/BSK

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Chief
Reactor Construction Projects Branch

Subject: Final Report - DER 82-5
A 50.55(e) Report Relating to Unit 2 Reactor Coolant Pump
Delivered With Sand In Cooler Chamber Housing
File: 82-019-026
D.4.33.2

Reference: (A) Telephone Conversation between J. Berdoin and
J. Cook on March 3, 1982

(B) ANPP-20613, dated April 5, 1982 (Interim Report)

Dear Sir:

Attached, is our final written report of the deficiency referenced
above, which has been determined to be Not Reportable under the
requirements of 10CFR50.55(e).

Very truly yours,

E. E. Van Brunt

E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects
ANPP Project Director

EEVBJr/GHD:db

Attachment

cc: See Attached Page 2

IE27

U. S. Nuclear Regulatory Commission
Attention: Mr. T. W. Bishop, Chief
June 16, 1982
ANPP-21209-GHD/BSK
Page 2

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. A. Roedel
D. B. Fasnacht
G. C. Andognini
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. A. Brand
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli

Lynne Bernabei, Esq.
Harmon & Weiss
1725 "I" Street, NW
Suite 506
Washington, D. C. 20006

R. L. Greenfield
Assistant Attorney General
Bataan Memorial Building
Santa Fe, New Mexico 87503

FINAL REPORT - DER 82-5

DEFICIENCY EVALUATION 50.55(e)

ARIZONA PUBLIC SERVICE COMPANY (APS)

PVNGS UNIT 2

I. Description of Deficiency

Unit 2 Reactor Coolant Pump 1110-B supplied by Combustion Engineering (C-E) was delivered to the jobsite with foreign matter in the cooler chamber housing. Two handfuls of material which appears to be blasting sand saturated with oil was in the scupper near the overflow nozzle. It was felt by Bechtel Construction that this material could have been introduced into the pump lubrication system if not found during field assembly of the pump.

However, C-E's evaluation indicates that the existence of sand was the result of a sandblasting and repainting condition which occurred after testing and prior to delivery of this particular pump. The blasting sand could not enter the pumps lubrication system, since the pump must be field assembled and cleanliness inspected prior to installation. Also, the cooler chamber housing is sealed from the pump internals, thereby precluding any sand from inadvertently entering the pumps lubrication system at a later date.

II. Analysis of Safety Implications

APS and Bechtel agree with C-E that the disposition is Not Reportable. Reference attached letter V-CE-16247 dated 4/8/82. Should this condition have remained undetected it would not represent a safety significant condition.

III. Corrective Action

Nonconformance Report NC-724 will be dispositioned to remove the blasting sand from the cooler chamber housing and continue with the assembly.