

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [C] [A] [S] [0] [S] [2] (2) [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] (3) [4] [1] [1] [1] [1] (4) [ ] [ ] (5)

CON'T  
 [0] [1] [L] (6) [0] [5] [0] [0] [0] [3] [6] [1] (7) [0] [5] [1] [2] [8] [2] (8) [0] [6] [1] [1] [8] [2] (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] [ ] With the plant in Mode 4, Diesel Generator 2G003 tripped during the monthly  
 [0] [3] [ ] surveillance test. The diesel was declared inoperable. Inspection revealed  
 [0] [4] [ ] that the Power Supply Module to the Governor Control Module was the cause for the  
 [0] [5] [ ] failure. The redundant diesel generator 2G002 was started within 50 minutes and  
 [0] [6] [ ] satisfactorily completed the operability test. This test was repeated every 8  
 [0] [7] [ ] hours. Thus, the public health and safety were not affected. This was an isolated  
 [0] [8] [ ] incident.  
 7 8 9 80

[0] [9] SYSTEM CODE [E] [E] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [E] [N] [G] [I] [N] [E] (14) COMP. SUBCODE [Z] (15) VALVE SUBCODE [Z] (16)

[17] LER/RO REPORT NUMBER [8] [2] (17) EVENT YEAR [ ] [ ] (21) SHUTDOWN METHOD [Z] (21) HOURS [0] [0] [0] [0] (22)

ACTION TAKEN [A] (18) FUTURE ACTION [Z] (19) EFFECT ON PLANT [Z] (20) ATTACHMENT SUBMITTED [N] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [X] (25) COMPONENT MANUFACTURER [G] [1] [0] [0] (26)

SEQUENTIAL REPORT NO. [0] [1] [5] OCCURRENCE CODE [0] [3] (29) REPORT TYPE [L] (30) REVISION NO. [0] (32)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] [ ] The cause of the failure was a resistor within the Power Supply Module which failed  
 [1] [1] [ ] in the open position thereby cutting power to the Governor Control Module.  
 [1] [2] [ ] Corrective action taken included replacement of the entire Power Supply Module,  
 [1] [3] [ ] shipping the affected unit to the manufacturers for analysis and tests by SCE on  
 [1] [4] [ ] the resistor of the replacement unit.  
 7 8 9 80

[1] [5] FACILITY STATUS [B] (28) % POWER [0] [0] [0] [0] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION [Operator Observation] (32)

[1] [6] ACTIVITY CONTENT [Z] (33) RELEASED OF RELEASE [Z] (34) AMOUNT OF ACTIVITY [NA] (35) LOCATION OF RELEASE [NA] (36)

[1] [7] PERSONNEL EXPOSURES NUMBER [0] [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION [NA] (39)

[1] [8] PERSONNEL INJURIES NUMBER [0] [0] [0] [0] (40) DESCRIPTION [NA] (41)

[1] [9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43) 8207080159 820610 PDR ADOCK 05000361 PDR S

[2] [0] PUBLICITY ISSUED [IN] (44) DESCRIPTION [NA] (45)

NAME OF PREPARER H. B. Ray

PHONE 714/492-7700