NRC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION (7.77)LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: H 0 0 0 0 0 AE I 0 0 0 0 -LICENSE NUMBER CON'T 9 6 6 (7) 0 6 2 1 (8)0 L(6) 0 1 0 0 SOURCE REPORT DATE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On 6/17/82, with Unit 2 in Run Mode at 2400 MWT, Division I RHRSW was 0 junable to achieve rated flow and discharge pressure and was declared 0 inoperative. T.S.3.7.1.1 requires two independent subsystems of RHRSW 0 4 be operable; Division II of RHRSW was operable and available at the time of this event. The plant was placed in a 72-hour LCO. The health and safety of the public was not affected by this non-repetitive event SYSTEM CODE COMP. CAUSE CAUSE VALVE SUBCODE COMPONENT CODE SUBCODE CIF E (12) F (13) A L VI E X (14) X (15 L (16) OCCURRENCE REVISION SEQUENTIAL REPORT EVENT YEAR REPORT NO. CODE NO. TYPE LER RO 8 3 2 0 6 1 L 0 COMPONENT MANUFACTURER NPRD-4 FORM SUB PRIME COMP. ACTION FUTURE TAKEN ACTION EFFECT ON PLANT ATTACHMENT SUBMITTED SUPPLIER X (25 N (24) (26)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of failure of the event has been attributed to the valve. The failure was due to ruptured gaskets and float deformation. Division I RHRSW was returned to operability, thus terminating the LCO on 6/18/82. No further corrective action is required. 4 80 METHOD OF FACILITY DISCOVERY DESCRIPTION (32) % POWER OTHER STATUS DISCOVERY 9 8 29 B (31) Surveillance Test NA 80 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED\_OF RELEASE Z 33 Z (34) 80 4.4 PERSONNEL EXPOSURES DESCRIPTION (39 0 Z 0 80 DESCRIPTION (41) (40)80 (43) Z (42) 8207150350 820629 PDR ADOCK 05000366 80 PUBLICITY NRC USE ONLY DESCRIPTION (45) PDR N (44) NA NAME OF PREPARER S. B. Tipps PHONE (912) 367-7851

LER #: 50-321/1982-061 Licensee: Georgia Power Company Facility Name: Edwin I. Hatch Docket #: 50-321

Narrative Report for LER 50-321/1982-061

On June 17, 1982, with Unit Two in Run Mode at 2400 MWT, Division I RHR Service Water subsystem was found inoperable. While establishing the initial conditions for the "PRIMARY CONTAINMENT HYDROGEN RECOMBINER SYSTEM FUNCTIONAL TEST (HEATUP TO 600° F)", an operator found Division I RHRSW unable to achieve rated flow and discharge pressure. Division I RHRSW was declared inoperable and the functional test on the primary containment hydrogen recombiners was postponed pending return to service of Division I of RHRSW. The redundant subsystem of RHRSW was operable. With one subsystem of RHRSW inoperable, the plant failed to maintain the requirements of Tech. Spec. 3.7.1.1. which states that two independent subsystems of RHRSW must be operable. The plant was placed in a 72-hour LCO as a result of this event. The health and safety of the public was not affected. This event was not repetitive.

The cause of this event has been attributed to failure of the air release valve. The failure was due to ruptured gaskets and float deformation. The gaskets and float in the air release valve have been replaced. Division I RHRSW was returned to service with successful completion of "RHR SERVICE WATER PUMP OPERABILITY", thus terminating the LCO on June 18, 1982. No further corrective action is required.