

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | T | P | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 36

CON T

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 0 | 7 | 0 | 6 | 0 | 9 | 8 | 2 | 3 | 0 | 7 | 0 | 9 | 8 | 2 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During power operation, the 3A High Head Safety Injection (HHSI) pump

0 3 | failed to start from manual operation of the normal Unit 3 control switch.

0 4 | The other HHSI pump were available and Unit 4 was in a cold shutdown

0 5 | condition at the time. The health and safety of the public was not

0 6 | affected. This is reportable pursuant to Tech. Spec. 6.9.2.b.2.

0 7 | _____

0 8 | _____

0 9 | S | F | 11 | E | 12 | X | 13 | P | U | M | P | X | X | 14 | X | 15 | Z | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP TUBCODE VALVE SUBCODE

17 LER/RO REPORT NUMBER 21 EVENT YEAR 22 23 24 SEQUENTIAL REPORT NO. 25 OCCURRENCE CODE 26 REPORT TYPE 27 REVISION NO.

18 X 19 Z 20 Z 21 Z 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0

12 X 13 Z 14 Z 15 Z 16 Z 17 0 18 0 19 0 20 0 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The breaker control panel fuses were replaced and the breaker was racked

1 1 | out and back in. The pump was then successfully started. The pump and

1 2 | control circuits were inspected and breaker 3AA13 was checked with no

1 3 | unusual indication. The root cause could not be determined. This

1 4 | problem has not reoccurred.

1 5 | E | 18 | 1 | 0 | 0 | 29 | N/A | A | 31 | Operator Observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 6 | 2 | 33 | 34 | N/A | 35 | N/A | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)

1 8 | 0 | 0 | 0 | 40 | N/A

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

PERSONNEL INJURIES NUMBER DESCRIPTION (41)

1 9 | Z | 42 | N/A

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

2 0 | N | 44 | N/A

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY

NAME OF PREPARER P.L. Pace PHONE (305) 552-3654

8207150483 820709
PDR ADOCK 05000250
S PDR