LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 G A E I H 2 2 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 1 4 5 6 7 8 0 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T O 1 SOURCE L 6 0 5 0 0 0 3 6 6 7 0 6 2 2 8 2 8 0 7 0 6 8 2 9 FEPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
While the plant was in steady state operation at 2334 MWT, the control
room received a low pressure alarm on hydraulic control unit 26-19. Tech.
Specs. 3.1.3.5 states that all control rod scram accumulators shall be
operable. All other HCU's were operable. The plant was placed in an 8
hour LCO as a result of this event. Public health and safety were not
affected. This is a repetitive event as last reported on Reportable
Occurrence Report No. 50-366/1982-008, Rev. 1.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
SEQUENTIAL REPORT NO. REPORT NUMBER SEQUENTIAL REPORT NO. LER/RO EVENT YEAR SEQUENTIAL REPORT NO. LER/RO EVENT YEAR SEQUENTIAL REPORT NO. LO 3 4
ACTION FUTURE ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED SUBMITTE
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of this event has been attributed to setpoint drift. The HCU
pressure switch was found to actuate at 990 psig. Tech. Specs. 4.1.3.5.b.2
states that the setpoint is 955 ± 15 psig. The switch was recalibrated
successfully per the "CRD HCU Pressure Indicator and Switch Calibration"
and returned to service.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 OPERATOR OPE
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTIC PDR ADOCK 05000366 PDR NA
NAME OF PREPARER R. T. Nix, Supt. of Maintenance PHONE 912-367-7781

LER No.: 50-366/1982-034 Facility: Edwin I. Hatch

Licensee: Georgia Power Company

Docket No.: 50-366

Narrative Report for LER 50-366/1982-034

On June 22, 1982, while the plant was in steady state power at 2334 MWT, the Control Room received a low pressure alarm on hydraulic control unit 26-19. Tech. Specs. 3.1.3.5 states that all control rod scram accumulators shall be operable. All other HCU's were operable. The plant was placed in an 8 hour LCO as a result of this event. The LCO was cleared after 7 hours and 23 minutes, and declared operable. Public health and safety were not affected. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-366/1982-008, Rev. 1.

The cause of this event has been attributed to setpoint drift. The HCU pressure switch was found to actuate at 990 psig. Tech. Specs. 4.1.3.5.b.2 states that the setpoint is 955 ± 15 psig. The switch was recalibrated successfully per the "CRD HCU Pressure Indicator and Switch Calibration" and returned to service. The switch is checked per BOP calibration.