

## GULF STATES UTILITIES COMPA


POST OFFICE BOX 2951 + BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 9, 1982 RBG-12,986 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:



On March 2, 1982, Gulf States Utilities Company (GSU) telephoned the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the insufficient end gap of a beam between the drywell wall and primary shield wall. Our architect engineer, Stone & Webster, has determined from their investigation that a more detailed evaluation is necessary to determine the reportability of this deficiency. GSU will provide a final status report of this deficiency by October 8, 1982.

Sincerely.

J. E. Booker

Manager-Engineering & Licensing River Bend Nuclear Group

E Booker

JEB/RK/kt

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

3