

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

V A S P S 1 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
9 14 15 25 26 30 37 CAT 58CONT
REPORT SOURCE L 6 0 5 0 0 0 2 8 0 7 0 6 2 0 8 2 8 0 7 1 4 8 2 9
60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

With Unit 1 at 100%, "A" S.I. Accumulator was inadvertently drained to a level below the T.S. minimum while "B" S.I. Accumulator's discharge valve was in the closed position for surveillance testing. This is contrary to T.S.3.3.A.2 and is reportable per T.S.6.6.2.b(2). The "C" S.I. accumulator remained available and an operator had administrative control over the "B" S.I. accumulator discharge valve. All other S.I. systems remained operable. Therefore, the health and safety of the public were not affected.

SYSTEM CODE S F 11 CAUSE CODE A 12 CAUSE SUBCODE A 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE F 15 VALVE SUBCODE X 16
LER/RO REPORT NUMBER 17 EVENT YEAR 8 2 SEQUENTIAL REPORT NO. 0 7 2 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0
ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED Y 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER C 6 3 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The draining of the "A" S.I. Accumulator was due to an operator opening a test valve on the accumulator discharge line. The "B" S.I. accumulator discharge valve was opened and the "A" S.I. accumulator level was returned to the requirements of the Tech. Spec.

FACILITY STATUS E 28 % POWER 1 1 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation. 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION 8207230289 820714 PDR ADOCK 05000280 S PDR NRC USE ONLY

NAME OF PREPARED J. L. Wilson

PHONE (804) 357-3184

ATTACHMENT 1

SURRY POWER STATION, UNIT NO. 1

DOCKET NO: 50-280

REPORT NO: 82-072/03L-0

EVENT DATE: 06-20-82

TITLE OF EVENT: "A" S.I. Accumulator Level Below T.S. Limit with "B" S.I. Acc. Discharge Valve Closed

1. DESCRIPTION OF EVENT:

With Unit 1 at 100% power, during the performance of P.T. 18.5 (Flushing of Sensitized Stainless Steel Piping), "A" Safety Injection Accumulator was inadvertently drained to a level below the Tech. Spec. minimum. Also, at this time, "B" S.I. Accumulator discharge valve (MOV-1865B) was under administrative control, in the closed position, to facilitate performance of PT 18.5. This is contrary to Tech. Spec. 3.3.A.2 and is reportable per Tech. Spec. 6.6.2.b(2).

2. PROBABLE CONSEQUENCES and STATUS of REDUNDANT EQUIPMENT:

The "C" S.I. accumulator remained available during the event. An operator had administrative control over the "B" S.I. Accumulator discharge valve and immediately opened the valve after the discovery of the event. Also, the "B" accumulator discharge valve would have automatically opened on a safety injection signal. The "A" S.I. Accumulator level was returned to the Tech. Spec. requirements well within the four hour Tech. Spec. limit and all other Safety Injection Systems were available during the event. Therefore, the health and safety of the public were not affected.

3. CAUSE:

The cause of the event was due to an operator opening the wrong test valve during the performance of the P.T. This action may have been enhanced by the arrangement of the accumulator test valve switches on the control board.

4. IMMEDIATE CORRECTIVE ACTION:

The "A" accumulator test valve, HCV-1850B, was closed and the "B" accumulator discharge valve, MOV-1865B, was opened. Also, the "A" accumulator was refilled to its proper level.

5. SUBSEQUENT CORRECTIVE ACTION:

The arrangement of the accumulator test valve switches will be incorporated into the NUREG 0700 review process.

6. ACTION TAKEN TO PREVENT RECURRENCE:

The operator involved was disciplined and reinstructed on the importance of following procedures.

7. GENERIC IMPLICATIONS:

None.