



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20545

October 30, 1990

Docket No. 50-336

Mr. Edward J. Mroczka  
Senior Vice President  
Nuclear Engineering and Operations  
Connecticut Yankee Atomic Power Company  
Northeast Nuclear Energy Company  
P. O. Box 270  
Hartford, Connecticut 06141-0270

Dear Mr. Mroczka:

SUBJECT: PLUG IN PLUG (PIP) REPAIRS FOR STEAM GENERATOR TUBE PLUGS  
MILLSTONE UNIT 2

This is to confirm our conversation with your staff on October 18, 1990, concerning the possibility of an unanalyzed condition relating to the PIP repairs made on the steam generator plugs in March 1989. We are providing this to more clearly identify our concerns.

PIP repairs to 446 plugs were performed in March 1989 at Millstone 2. The PIPs were of an initial design that was tested to exhibit an average leak rate of 0.003 gpm (Reference WCAP-12244 Rev. 1, "Steam Generator Tube Plug Integrity Summary Report, April 1989"). A later design was tested to exhibit average leak rates of two orders of magnitude less than 0.003 gpm. These repairs were developed pursuant to 10 CFR 50.59.

PIPs are intended to provide "leak limiting" rather than "leak tight" repairs of steam generator tube plugs. Should the original plug fail (such as at North Anna 1), the PIP ensures that there is insufficient energy imparted to the plug top (by the primary fluid) to cause the plug top to become a high energy projectile. If either the plug or the affected tube is not cracked entirely through wall, there will be no leakage through the PIP. If both the plug and the affected tube are cracked through wall, then the PIP will leak at an average of .003 gpm as established by test.

Taking no credit for the leak tight integrity of the repaired plugs or the affected tubes, total primary-to-secondary leakage through the 446 PIPs would be 1.33 gpm. This number could be somewhat higher during steam line break (SLB) accidents due to the larger pressure differential.

As a practical matter, many of the repaired plugs and affected tubes will be leak-tight during normal operation such that the Technical Specification limit is not likely to be exceeded. However, it should be noted that the tubes were plugged because they were no longer fit to serve as the reactor coolant system boundary. The plugs were repaired for the same reason. There is no reason to expect that the tubes and plugs will not leak under the larger pressure loadings associated with a SLB.

9011130322 901030  
PDR ADOCK 05000336  
P PDC

000112

DF01  
1/0

Mr. Edward J. Mroccka  
Northeast Nuclear Energy Company

Millstone Nuclear Power Station  
Unit No. 2

cc:

Gerald Garfield, Esquire  
Day, Berry and Howard  
Counselors at Law  
City Place  
Hartford, Connecticut 06103-3499

R. M. Kacich, Manager  
Generation Facilities Licensing  
Northeast Utilities Service Company  
Post Office Box 270  
Hartford, Connecticut 06141-0270

W. D. Romberg, Vice President  
Nuclear Operations  
Northeast Utilities Service Company  
Post Office Box 270  
Hartford, Connecticut 06141-0270

D. O. Wordquist  
Director of Quality Services  
Northeast Utilities Service Company  
Post Office Box 270  
Hartford, Connecticut 06141-0270

Kevin McCarthy, Director  
Radiation Control Unit  
Department of Environmental Protection  
State Office Building  
Hartford, Connecticut 06106

Regional Administrator  
Region I  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, Pennsylvania 19406

Bradford S. Chase, Under Secretary  
Energy Division  
Office of Policy and Management  
80 Washington Street  
Hartford, Connecticut 06106

First Selectmen  
Town of Waterford  
Hall of Records  
200 Boston Post Road  
Waterford, Connecticut 06385

S. E. Scace, Nuclear Station Director  
Millstone Nuclear Power Station  
Northeast Nuclear Energy Company  
Post Office Box 128  
Waterford, Connecticut 06385

W. J. Raymond, Resident Inspector  
Millstone Nuclear Power Station  
c/o U. S. Nuclear Regulatory Commission  
Post Office Box 811  
Niantic, Connecticut 06357

J. S. Keenan, Nuclear Unit Director  
Millstone Unit No. 2  
Northeast Nuclear Energy Company  
Post Office Box 128  
Waterford, Connecticut 06385

Charles Brinkman, Manager  
Washington Nuclear Operations  
C-E Power Systems  
Combustion Engineering, Inc.  
12300 Twinbrook Pkwy  
Suite 330  
Rockville, Maryland 20852

In addition to the 446 PIPs installed in March 1989, hundreds of additional PIPs have recently been installed at Millstone. These PIPs are of the more recent design that exhibit two orders of magnitude less leakage than 0.003 gpm and they do add to cumulative postulated primary-to-secondary leakage.

Based on the above, we are concerned that leakage through the PIPs during a SLB accident could exceed the 1.0 gpm value assumed in the safety analyses for purposes of assessing the consequences of a SLB relative to Part 100. We believe this issue should be resolved and request that you advise us accordingly. Please provide us a schedule for resolving this issue within 15 days from receipt of this letter.

Sincerely,

original signed by

Guy S. Vissing, Senior Project Manager  
Project Directorate I-4  
Division of Reactor Projects - I/II  
Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION

~~DOCKET FILE~~

- PDI-4 File
- GVissing
- SNorris
- NRC & L PDRs
- SVarga
- BBoger
- OGC
- EJordan MNBB 3701
- ACRS (10)
- EMurphy
- CYCheng

\*See previous concurrence

OFC	:PDI-4:LA	:PDI-4:PM	:PDI-4:D	:EMCB	:	:
NAME	:SNorris *	:GVissing/Bah	:JStolz *	:CYCheng *	:	:
DATE	:10/26/90	:10/30/90	:10/30/90	:10/26/90	:	:

OFFICIAL RECORD COPY  
Document Name: PLUG IN PLUG