LICENSEE EVENT REPORT

-1.8	
	CONTROL BLOCK: 1 1 1 1 1 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
C 11	I L Z I S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 CAT 58 5
CON'T	SOUNCE L 60 5 0 0 0 3 0 4 7 0 9 1 5 7 8 8 10 1 3 7 8 9
0 2	During normal operation, received a NIS channel deviation alarm. Inves-
0 3	tigation showed power range channel N42 reading 93% instead of 100%
0 4	power. This is non-conservative for the Power Range High Flux Reactor
05	Trip as indicated in Table 3.1-1 of Tech. Spec. Associated bistables
0 6	were tripped and required surveillance per T.S.4.2.2.C.2 was conducted.
0 7	Redundant channels were available and operable. The health and safety
7 B	of the public was not affected.
0 9 7 8	CODE CODE SUBCODE SUBC
	LERIND EVENTYEAR REPORT NO. R
110	A 25 volt power supply in the N42 power range drawer was found defective
	and replaced. Channel N42 was functionally checked and returned to
[12]	operation. Failure of low voltage power supplies of this type are
113	infrequent. No further action is required.
7 8	
1 5	ACILITY STATUS OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) E 28 1 0 0 29 NA A A A A A A A A A A A A A A A A A A
1 6 RE	LEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (31) NA NA
7 , Б	9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA 7811240 270
2 8	PERSONNEL INJURIES 60
1 8	NUMBER DESCRIPTION (41) NA
	LOSS OF OH DANAGE TO FACILITY (43) TYPE DESCRIPTION 80
1 9	PURISITY NA
3 0	NBC USE ONLY NA
7 8	68 69 80.2
	NAME OF PREPARER Terrance A. Rieck PHONE 312-746-2084 X348