

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 W I L B R 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE L 6 0 5 0 - 0 4 0 9 7 1 1 2 6 7 8 8 1 1 2 7 7 8 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 PERIODIC LEAKAGE RATE TEST FOR THE EMERGENCY AIRLOCK DID NOT MEET TYPE B
03 TEST CRITERIA AS SPECIFIED BY TECHNICAL SPECIFICATIONS. THE LEAKAGE RA
04 TE WAS DETERMINED TO BE 1.037 SCFH. THE ALLOWABLE LEAKAGE RATE IS 0.749
05 SCFH. SIMILAR OCCURRENCE RO-77-02 (MAIN PERSONNEL AIRLOCK). THE INDIC
06 ATED SOURCE OF LEAKAGE WAS THE OUTER EQUALIZING VALVE NO. 37-30-004. PR
07 IMARY CONTAINMENT INTEGRITY WAS MAINTAINED BY INNER DOOR OF AIRLOCK.

09 SYSTEM CODE S A 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE P E N E T R 14 COMP SUBCODE A 15 VALVE SUBCODE 16
17 SER NO REPORT NUMBER 7 8 21 22 SEQUENTIAL REPORT NO. 0 1 2 24 26 OCCURRENCE CODE 0 1 28 29 REPORT TYPE T 30 REVISION NO. 0 32
ACTION TAKEN B 18 Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB N 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 THE VALVE LEAKAGE WAS DUE TO SLIGHT SCRATCHES ON TEFLON VALVE SEATS. TH
11 E VALVE IS A JAMESBURY VALVE MODEL 3D-14. THE BALL AND TEFLON SEATS ARE
12 BEING REPLACED. A RETEST WILL BE CONDUCTED. VALVE REPAIR CONSTITUTES
13 CORRECTIVE ACTION.

14 FACILITY STATUS C 19 H. POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION NA 32

15 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

16 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

17 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

18 TYPE OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

19 TYPE OR DAMAGE TO FACILITY TYPE Z 44 DESCRIPTION NA 45