

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | C | R | P | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | - | - | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

CON'T  
0 1 | L | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 1 | 1 | 2 | 5 | 7 | 8 | 1 | 2 | 1 | 4 | 7 | 8 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

0 2 | At 1035 during the routine operation of air handling fans AHF-14A&C, it was  
0 3 | discovered that the flow recorder was indicating a low flow condition.  
0 4 | AHF-14A&C were secured. Operability was restored on 30 November 1978. No  
0 5 | effects upon public health and safety as a redundant set of fans, AHF-14B&D  
0 6 | were available and operable. Fan inoperability created an event contrary  
0 7 | to Technical Specification 3.7.8.1. Four previous reportable occurrences,  
0 8 | but first occurrence of this type.

0 9 | A | A | E | C | B | L | O | W | E | R | Z | Z | 7 | 8 | 0 | 6 | 4 | 0 | 3 | L | 0 | J | 1 | 2 | 7 | 26  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 0 | The cause of this event was attributed to the suction shroud breaking  
1 1 | loose and carrying into the fan blade assembly. Remaining fans AHF-14A, B, and  
1 2 | D were checked for similar defects. No corrective action deemed necessary  
1 3 | as the broken blades on AHF-14C were replaced and rebalanced.

1 4 | \_\_\_\_\_  
1 5 | E | 0 | 9 | 8 | NA | A | Operator observation  
1 6 | Z | Z | NA | NA  
1 7 | 0 | 0 | 0 | Z | NA  
1 8 | 0 | 0 | 0 | NA  
1 9 | Z | NA  
2 0 | NA

NAME OF PREPARER: J. Cooper PHONE: (904) 795-6486

7812270243

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

Report No.: 50-302/78-064/03L-0

Facility: Crystal River Unit #3

Report Date: 14 December 1978

Occurrence Date: 25 November 1978

Identification of Occurrence:

One pair of Auxiliary Building exhaust ventilation fans inoperable contrary to Technical Specification 3.7.8.1.

Conditions Prior to Occurrence:

Mode 1 power operation (98%)

Description of Occurrence:

At 1035, during routine operation of air handling fans AHF-14A&C, it was discovered that the flow recorder was indicating a low flow condition. AHF-14A&C were subsequently secured and AHF-14B&D were started. AHF-14A&C were restored to operable status, following maintenance and testing on 30 November.

Designation of Apparent Cause:

The cause of this event is attributed to the suction shroud breaking loose and carrying into the fan blade assembly.

Analysis of Occurrence:

There was no safety hazard to the plant or general public, as the redundant set of fans AHF-14B&D were available and operable.

Corrective Action:

No corrective action deemed necessary as the broken blades on AHF-14C were replaced and rebalanced.

Failure Data:

Four previous reportable occurrences, but first occurrence of an event of this type.

/rc