

Mr. Boyce H. Grier, Director  
Office of Inspection & Enforcement, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

-30-19/3L

Dear Mr. Grier:

This LER concerns the failure of MO-3-10-25A, LPCI injection valve to open during surveillance testing. The governing Technical Specifications are 3.5.A.5 and 3.5.A.7.

U. S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P A P B S 3 7 0 0 - 0 0 0 0 0 - 0 0 0 4 1 1 1 1 4 5  
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
CON'T

CONT'D	REPORT SOURCE	L 6 0 5 0 - 0 2 7 8 7 0 8 0 6 8 0 7 0 9 0 5 8 0 9
0 1		61 62 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80 81
S		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing a surveillance test on the RHR system with the unit at  
0 3 power, MO-j-10-25A LPCI injection valve failed to open. The valve was  
0 4 satisfactorily stroked at reduced differential pressure and surveillance  
0 5 frequency increased. On 8/12/80 the valve was declared inoperable due  
0 6 to increasing operating current. The remaining LPCI subsystem and both core  
0 7 spray systems were verified operable per Tech Spec. 3.5.A.5. On 8/15/80

the unit was shut down within the requirements of Tech Spec. 3.5.A.7.

3	9	8	SYSTEM CODE	S I F	11	CAUSE CODE	B	12	LAUSE SUBCODE	B	13	COMPONENT CODE	V A L V O P	14	COMP SUBCODE	A	15	VALVE SUBCODE	Z	16			
LER-RO REPORT NUMBER				EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE			REPORT TYPE			REVISION NO.							
(17)				3	0	0	1	9	0	1	3	0	1	0	1	0	0	0	0				
ACTION TAKEN				FUTURE ACTION			EFFECT ON PLANT			SHUTDOWN METHOD			HOURS			ATTACHMENT SUBMITTED			IGRDI-4 FORM SUBM.				
C	18	Z	19				A	20		A	21		0	1	1	3	N	22	Y	24	PRIME COMP SUPPLIER		
33	34	35					36	37		38	39		40	41	42		43				L 2 0 0		
SAFETY INFORMATION AND OPERATING INSTRUCTIONS																							

Cause was multiple full penetration circumferential cracks of the lower thrust bearing on the drive sleeve of the type SMB-4 Limitorque operator. The limitorque operator was replaced and satisfactory stroke and leak tests were performed.

ACTIVITY CONTENT  
RELEASED, OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1	6	2	33	2	34	NA		NA		
9	9	10	11				44		45	
RECORDING, EXAMINEE										

17 000 (37) 2 (38) NA

PERSONNEL INJURIES  
NUMBER **000**(40) DESCRIPTION **NA** **AS 11**  
8 9 11 12  
CLASS OF PERSONNEL TO EXAMINE **0**

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION (43)  
1 0 2 (43) NA  
8 9 10

20	ISSUED TO	DESCRIPTION	45	NA	<i>M. J. Clegg</i>	NOTE USE ONLY
	N	44				

8009160 439