

BOSTON EDISON COMPANY

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

TELECOPY MESSAGE

To: 215-337-5324  
Telephone Number

Date/Time: October 31 / 1980

To: Director, Region I  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station  
KFD #1 Rocky Hill Road  
Plymouth, MA 02300

Subject: PROMPT REPORTABLE OCCURRENCE  
Docket Number 50-293; License DFR-35  
Assigned LER Number 80-078/01X-0 (Reported per Technical Specification 6.9.K.1.1)

Event Description: On October 30, 1980 the ORC reviewed the results of an analysis of  
the Salt Service Water System conducted in response to IE Bulletin 79-14. The results  
indicate that a design deficiency exists because of the installation of a SSW anchor  
point outside the area's tornado missile barrier protection.

Cause and Corrective Action: The rationale for this construction is being investigated.  
Every effort to expeditiously relocate this anchor point within the missile barrier is  
being extended. A contingency plan in the event of a tornado in the immediate vicinity  
is to shutdown the reactor.

Facility Status:

- c) Routine Startup \_\_\_\_\_
- d) Routine Shutdown \_\_\_\_\_
- e) Steady State X \_\_\_\_\_
- f) Load Changing \_\_\_\_\_

- 100 X Thermal MW
- g) Shutdown \_\_\_\_\_
- h) Refueling \_\_\_\_\_
- i) Other \_\_\_\_\_
- j) Not Applicable \_\_\_\_\_

A written follow-up report will be sent within two weeks.

NRC person notified Mr. Jon Johnson

Prepared by Mr. M. Thomas McLoughlin

8011070409

S

MAD  
5.0/1

Mail (2) copies to:  
Director  
Office of Management Information and Program Control  
U. S. Nuclear Regulatory Commission