

LICENSEE EVENT REPORT

CONTROL BLOCK: | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | |
|---|---------------------|----------------------|---------------------------|
| 0 1 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 | LICENSEE CODE 14 15 | LICENSE NUMBER 28 26 | LICENSE TYPE J0 37 CAT 54 |
|---|---------------------|----------------------|---------------------------|

CONT'

| | | | | |
|---|-------|--------------------|------------------|----------------|
| 0 1 REPORT SOURCE L 6 0 5 0 1 0 0 3 2 7 7 1 0 1 1 6 8 0 1 1 1 4 8 0 9 | 60 61 | OCKET NUMBER 66 69 | EVENT DATE 74 75 | REPORT DATE 80 |
|---|-------|--------------------|------------------|----------------|

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

- 0 | 2 | Unit in Mode 4. SI-28, Test of Containment Air Return Fan, requires starting the
 0 | 3 | B-B air return fan with the inlet damper secured closed. During the test, the lower
 0 | 4 | inlet doors to the ice condenser were inadvertently opened. The action statement of
 0 | 5 | LCO 3.6.5.3 was entered. There was no effect upon public health or safety. Previous
 0 | 6 | occurrences - none.

0 | 7 |

0 | 8 |

| SYSTEM CODE 9 10 | CAUSE CODE D 11 | CAUSE SUBCODE Z 12 | COMPONENT CODE V A L V E X 14 | COMP. SUBCODE L 15 | VALVE SUBCODE A 16 |
|--|-----------------------------|---|---|------------------------------|----------------------------------|
| 17 LER/RO REPORT NUMBER 8 0 21 22 | EVENT YEAR 1 7 23 | SEQUENTIAL REPORT NO. 1 7 7 24 26 | OCCURRENCE CODE 0 3 27 29 | REPORT TYPE L 30 | REVISION NO. 0 32 |
| ACTION FUTURE TAKEN ON PLANT 1 8 33 34 | EFFECT ON PLANT 2 20 35 | SHUTDOWN METHOD 1 7 31 35 | HOURS 0 0 0 0 37 40 | NPPD-4 FORM SUB. N 23 41 | PRIME COMP. SUPPLIER L 25 43 |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 | | | | | |

- 1 | 0 | The inlet damper was not properly secured closed allowing leakage through the damper
 1 | 1 | In cause the ice condenser lower inlet doors to open. The ice condenser doors were
 1 | 2 | closed 63 minutes later. The damper was resecured and the test was rerun satisfactorily.
 1 | 3 | The procedure has been revised to place a cover over the inlet damper during future
 1 | 4 | testing to preclude a similar occurrence.

| | | | | |
|--|-----------------------------------|----------------------|----------------------------|---|
| FACILITY STATUS G 28 | POWER 0 0 0 29 | OTHER STATUS NA 30 | METHOD OF DISCOVERY B 31 | DISCOVERY DESCRIPTION Operator observation 32 |
| ACTIVITY CONTENT 10 12 | AMOUNT OF ACTIVITY 0 0 0 33 | 44 | 45 46 | |
| RELEASED OR RELEASE 2 30 | PERSONNEL EXPOSURES 1 10 11 | DESCRIPTION 0 33 | NA | LOCATION OF RELEASE 0 36 |
| PERSONNEL INJURIES 1 11 12 13 | NUMBER 1 10 11 | TYPE 2 34 35 | DESCRIPTION NA 33 | 8 |
| LOSS OF OR DAMAGE TO FACILITY 1 17 12 13 | NUMBER 1 10 11 | TYPE 2 34 35 | DESCRIPTION NA 33 | 8 |
| PUBLICITY ISSUED 1 10 11 12 | DESCRIPTION 0 44 | NA | | NRC USE ONLY |

8011240337

FEB 1980 1980