P. O. BOX 33189

DUKE POWER COMPANY

TELEPHONE: AREA 704 373-4011

GENERAL OFFICES 422 SOUTH CHURCH STREET CHARLOTTE, N. C. 28242

August 12, 1982

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief Licensing Branch No. 4

Re: Catawba Nuclear Station Docket Nos. 50-413 and 50-414

Dear Mr. Denton:

As a result of a June 4, 1982 meeting with the Structural Engineering Branch, Duke Power agreed to provide the ultimate capacities of the Catawba containment vessel penetrations. Attachment 1 is a summary of the Catawba ultimate capacity analysis. Please note that information on the purge penetration isolation valves was not available and will be provided by August 31, 1982.

Very truly yours,

Hat B. Tucke

H. B. Tucker, Vice President Nuclear Production Department

ROS/php Attachment

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Mr. P. K. Van Doorn NRC Resident Inspector Catawba Nuclear Station

Mr. Robert Guild, Esq. Attorney-at-Law 314 Pall Mall Columbia, South Carolina 29201 8001

Mr. Harold R. Denton, Director August 12, 1982 Page 2

cc: Palmetto Alliance 2135½ Devine Street Columbia, South Carolina 29205

> Mr. Jesse L. Riley Carolina Environmental Study Group 854 Henley Place Charlotte, North Carolina 28207

Mr. Henry A. Presler, Chairman Charlotte-Mecklenburg Environmental Coalition 943 Henley Place Charlotte, North Carolina 28207

CATAWBA NUCLEAR STATION CONTAINMENT ULTIMATE CAPACITY ANALYSIS SUMMARY

. : -

LOCATION	ULTIMATE INTERNAL PRESSURE(PSI)	CRITERION
Containment Shell	72	Nonlinear Axisymmetric Analysis
Base Anchorage	81	Concrete Shear
Penetrations		
 a. Personnel Airloc b. Equipment Hatch c. Spares d. Bellows Assembli e. Electrical Penet tion Assemblies f. Purge Penetratio Isolation Valve 	k 79 91 1275 es >72 ra- >72 n s Later	Plastic Moment In Bulkhead Tensile Failure of Cover Flange Yield of Spare Cap Manufacturer's Recommendation Leak in Connector Module