



**GULF STATES UTILITIES COMPANY**

RIVER BEND STATION      POST OFFICE BOX 226      ST. FRANCISVILLE, LOUISIANA 70776  
AREA CODE 504      835-8094      346-8661

December 15, 1993  
RBG-39666  
File Nos. G9.5, G9.33.1

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

River Bend Station - Unit 1  
Docket No. 50-438

Gentlemen:

This letter provides information resulting from an evaluation conducted by Gulf States Utilities (GSU) of fixed and transient materials in the containment and drywell having a potential for being transported to the suppression pool during a Design Basis Accident (DBA). This issue developed from an investigation of degraded coatings in the drywell, and was identified as a concern during the latter portion (November 8 - 12, 1993) of the Operational Safety Team Inspection (OSTI) conducted at the River Bend Station (RBS). At the OSTI exit meeting, GSU committed to provide additional information related to plugging of emergency core cooling suction strainers as discussed in NRC Bulletin 93-02.

While performing an evaluation related to degraded coatings in the drywell, GSU identified additional materials in the drywell and containment which could have become debris and potentially blocked the Emergency Core Cooling System (ECCS) suction strainers in the event of a DBA Loss of Coolant Accident. These materials were categorized and evaluated through the use of detailed statistical and hydrodynamic analyses. The final disposition of this evaluation determined that the materials would not have produced an impairment to the operation of the ECCS.

Attachment 1 provides the characterization of identified material for primary containment and the drywell (drywell material is estimated based on previous inspections or extrapolated from containment inspection results) which could have become dislodged and migrated to the suppression pool. Attachment 2 provides the results of the strainer blockage evaluation for the "as-found" primary containment conditions based on the material inventory found in primary containment. Attachment 3 provides the results of the strainer blockage evaluation for the "as-left" primary containment conditions after loose material was removed from primary containment. The evaluations assumed that 100% of

Page 2 of 3  
Letter to U.S. Nuclear Regulatory Commission  
Document Control Desk  
December 15, 1993  
RBG-39666

the materials dislodged in containment migrated to the pool, while only a fraction of the drywell materials reached the pool. The transport mechanism analysis of the materials in the pool concluded that the ECCS suction strainers would have performed their design function and protected their respective safety-related pumps while allowing adequate flow to ensure minimum net positive suction head (NPSH) and system flow requirements.

GSU has developed and implemented a program to provide direction for control and use of temporary materials inside containment during power operations. This program was developed to address the concern identified above and to ensure that safety-related equipment in containment remains capable of performing its intended function.

These evaluations and conclusions are being provided for NRC information. If you have any questions or require further information concerning this matter, please contact David N. Lorfing at (504) 381-4157.

Very truly yours,



James J. Fisicaro  
Manager - Safety Assessment and  
Quality Verification  
River Bend Nuclear Group

Attachments

Page 3 of 3  
Letter to U.S. Nuclear Regulatory Commission  
Document Control Desk  
December 15, 1993  
RBG-39666

cc: U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

NRC Resident Inspector  
P.O. Box 1051  
St. Francisville, LA 70775

Mr. Edward T. Baker  
U.S. Nuclear Regulatory Commission  
M/S OWFN 13-H-15  
Washington, D.C. 20555

**ATTACHMENT 1**  
**MATERIAL CHARACTERIZATION**

DRYWELL TARGET	RISK	TRANSPORT		TRANSPORT		COMMENTS
		EVENT	METHOD	EVENT	METHOD	
PAINT	JET IMPINGEMENT	MSLB	VENT CLEARING	MSLB	VENT CLEARING	ANALYZED IN CR 93-0754 / ESTIMATED PER RG182 METHOD
HOUSEKEEPING	JET IMPINGEMENT	MSLB	VENT CLEARING	MSLB	VENT CLEARING	LESS TRAFFIC, MORE CONTROLS THAN CRMT, FORMAL CLOSE OUT
SH TEMP	JET IMPINGEMENT	MSLB	VENT CLEARING	MSLB	VENT CLEARING	ESTIMATED PER RG182 METHOD
UAP FLEX CONDUIT	THERMAL	SB LOCA	VENT CLEARING	SB LOCA	VENT CLEARING	LOW THERMAL DEGRADATION FOR DBA/LOCA
Thermal-CEL	N/A	N/A	N/A	N/A	N/A	STEEL JACKETED, LOW ENERGY LIFE
Thermal-CEL TAPE	N/A	N/A	N/A	N/A	N/A	STEEL JACKETED, LOW ENERGY LIFE
RP MATERIALS	JET/THERMAL	ANY	VENT CLEARING	MSLB	VENT CLEARING	LESS TRAFFIC, MORE CONTROLS THAN CRMT, FORMAL CLOSE OUT
CABLE JACKET	THERMAL	SB LOCA	VENT CLEARING	SB LOCA	VENT CLEARING	LOW THERMAL DEGRADATION FOR DBA/LOCA
PAPER TAGS	JET/THERMAL	ANY	VENT CLEARING	MSLB	VENT CLEARING	DISINTEGRATION IN DBA/LOCA IS NOT CREDITED
BLACK TIE WRAPS	JET IMPINGEMENT	MSLB	VENT CLEARING	MSLB	VENT CLEARING	ESTIMATED BASED ON CONTAINMENT INSPECTION
INSULATION	JET IMPINGEMENT	MSLB	VENT CLEARING	MSLB	VENT CLEARING	ESTIMATED PER RG182
THERMO LAG	N/A	N/A	N/A	N/A	N/A	NOT USED IN DRYWELL
GYPSUM CEMENT	N/A	N/A	N/A	N/A	N/A	NOT USED IN DRYWELL
UC FILTERS	N/A	N/A	N/A	N/A	N/A	TRANSIENT, REMOVED AFTER OUTAGES
CONTAINMENT		TRANSPORT		TRANSPORT		COMMENTS
TARGET	RISK	EVENT	METHOD	EVENT	METHOD	
PART	N/A	N/A	N/A	N/A	N/A	NO JET IMPINGEMENT OR CONTAMINATION
HOUSEKEEPING	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	REMOVED < = 114' EL.
SH TEMP	N/A	N/A	N/A	N/A	N/A	ENVIRONMENTALLY QUALIFIED FOR ALL EVENTS
UAP FLEX CONDUIT	N/A	N/A	N/A	N/A	N/A	ENVIRONMENTALLY QUALIFIED FOR ALL EVENTS
Thermal-CEL	N/A	N/A	N/A	N/A	N/A	ENVIRONMENTALLY QUALIFIED FOR ALL EVENTS
Thermal-CEL TAPE	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	REMOVED < = 114' EL., ANALYZED SAMPLES
RP MATERIALS	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	MINIMIZE < = 114' EL., ANALYZED FOR POOL SWELL
CABLE JACKET	N/A	N/A	N/A	N/A	N/A	ENVIRONMENTALLY QUALIFIED FOR ALL EVENTS
PAPER TAGS	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	DISINTEGRATION IN DBA/LOCA IS NOT CREDITED
BLACK TIE WRAPS	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	ANALYZED TO SURVIVE FOR CONTAINMENT DURING DBA/LOCA
INSULATION	N/A	N/A	N/A	N/A	N/A	ENVIRONMENTALLY QUALIFIED FOR ALL EVENTS, NO TRANSPORT
THERMO LAG	N/A	N/A	N/A	N/A	N/A	SEISMICALLY MOUNTED, ABOVE POOL SWELL
GYPSUM CEMENT	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	SEISMICALLY MOUNTED, ABOVE POOL SWELL
UC FILTERS	BACK DRAFT	N/A	GRAVITY	N/A	N/A	NO BACKDRAFT RISK PER G1318.2.1-45.0
POOL BOTTOM	POOL SWELL	DBA/LOCA	POOL SWELL	DBA/LOCA	DBA/LOCA	ESTIMATED BASED ON DIVER INSPECTIONS

## ATTACHMENT 2

## "AS-FOUND" STRAINER BLOCKAGE EVALUATION RESULTS

DRYWELL TARGET	MATERIAL DAMAGE (\$0 FT)	EXIT VENTS	TRANSPORT FRACTION	BLOCKAGE (\$0 FT)	COMMENTS
PART	615.75	104.68	0.0312	3.27	EST. D/W MATT AT MSIBDA LOCATION - CNTM1 MATT ON 95' FL.
HOUSEKEEPING	8.02	1.02	0.1963	0.20	
SH TEMP	67.00	11.39	0.0151	0.17	
UAP FLEX CONDUIT	45.00	0.00	0.1623	0.00	NO DAMAGE FOR MSIBDA LOCA
THERMA CEL	0.00	0.00	0.1623	0.00	
THERMA CEL TAPE	0.00	0.00	0.1623	0.00	
RP MATERIALS	17.38	2.94	0.2487	0.73	EST. D/W RP MATERIAL - CNTM1 RP MATT ON 95' FL.
CABLE JACKET	581.86	0.00	0.2065	0.00	NO DAMAGE FOR MSIBDA LOCA
PAPER TAGS	4.70	0.80	0.1138	0.09	EST. D/W PAPER TAGS - CNTM1 TIE WRAPS ON 95' FL.
BLACK TIE WRAPS	0.10	0.02	0.0295	0.00	EST. D/W TIE WRAPS AT MSIBDA LOCATION - CNTM1 TIE WRAPS IN POOL SHELL
INSULATION	37.70	8.41	0.3000	1.92	DAMAGE - 3 PIPE DIAM / 30% SUSPENDED (MEUREGCR 2791)
THERMO LAG	0.00	0.00	0.0000	0.00	
GYPSUM CEMENT	0.00	0.00	0.0000	0.00	
UC FILTERS	0.00	0.00	0.0000	0.00	
SUBTOTAL	1365.37	127.26	6.36		
CONTAINMENT TARGET	MATERIAL DAMAGE (\$0 FT)	POOL	TRANSPORT FRACTION	BLOCKAGE (\$0 FT)	
PART	0.00	0.00	0.0000	0.00	
HOUSEKEEPING	59.80	59.80	0.1893	11.74	NO CREDIT FOR GRATING
SH TEMP	15.50	15.50	0.0312	0.48	
UAP FLEX CONDUIT	0.00	0.00	0.0000	0.00	
THERMA CEL	0.00	0.00	0.0000	0.00	
THERMA CEL TAPE	10.00	10.00	0.1625	1.63	12" PIPE STARTS ON 116" & RUNS VERTICALLY UP
RP MATERIALS	129.10	0.00	0.2208	0.00	CREDIT FASTENERS ON RP MATERIALS
CABLE JACKET	0.00	0.00	0.0000	0.00	
PAPER TAGS	29.90	29.90	0.1151	3.44	
BLACK TIE WRAPS	0.00	0.00	0.0151	0.00	
INSULATION	0.00	0.00	0.0000	0.00	
THERMO LAG	0.00	0.00	0.0000	0.00	
GYPSUM CEMENT	0.00	0.00	0.0000	0.00	
UC FILTERS	0.00	0.00	0.0000	0.00	
POOL BOTTOM	20.00	20.00	0.1963	3.93	
SUBTOTAL	264.30	135.20	12.12	21.21	
TOTAL	1619.67			27.60	PREVIOUS - 20% BLOCKAGE

## ATTACHMENT 3

## "AS-LEFT" STRAINER BLOCKAGE EVALUATION RESULTS

CONTAMINANT TARGET	MATERIAL DAMAGE (60 FT)	EXIT VENTS	TRANSPORT FRACTION	BLOCKAGE	
				(60 FT)	COMMENTS
PART	615.75	104.88	0.0312	3.27	EST. OWN MATT. AT 10% LOCATION - CREDIT RP MATERIAL ON 95' EL.
HOUSE KEEPING	8.02	1.02	0.1983	0.20	
SUR TEMP	87.00	11.38	0.0161	0.17	
UAP FLEX CONDUIT	45.00	0.00	0.1623	0.00	NO DAMAGE FOR MISIBORA LOCA
THERMA CEL	0.00	0.00	0.1623	0.00	
THERMA CEL TAPE	0.00	0.00	0.1623	0.00	
RP MATERIALS	17.30	2.94	0.2487	0.73	EST. OWN RP MATERIAL - CREDIT RP MATERIAL ON 95' EL.
CABLE JACKET	561.80	0.06	0.2055	0.00	NO DAMAGE FOR MISIBORA LOCA
PAPER TAGS	4.70	0.80	0.1139	0.09	EST. OWN PAPER TAGS - CREDIT PAPER ON 95' EL.
BLACK TIE WRAPS	0.10	0.02	0.0206	0.00	EST. OWN TIE WRAPS AT 10% LOCATION - CREDIT TIE WRAPS IN POOL SWELL
INSULATION	37.70	6.41	0.3800	1.92	DAMAGE - 3 PIPE DIAM / 30% SUSPENDED (HUREGCR 2791)
ThERMO LAG	0.00	0.00	0.0000	0.00	
GYPSUM CEMENT	0.00	0.00	0.0000	0.00	
UC FILTERS	0.00	0.00	0.0000	0.00	
<b>SUBTOTAL</b>	<b>1365.37</b>	<b>127.26</b>		<b>6.38</b>	
CONTAMINANT TARGET	MATERIAL DAMAGE (60 FT)	POOL	TRANSPORT FRACTION	BLOCKAGE	
				(60 FT)	
PART	0.00	0.00	0.0000	0.00	
HOUSEKEEPING	0.00	0.00	0.1055	0.00	NO CREDIT FOR GRATING
SUR TEMP	0.00	0.00	0.0133	0.00	
UAP FLEX CONDUIT	0.00	0.00	0.0000	0.00	
THERMA CEL	0.00	0.00	0.0000	0.00	
THERMA CEL TAPE	0.00	0.00	0.1895	0.00	12" PIPE STARTS ON 116' & RUNS VERTICALLY UP
RP MATERIALS	129.10	0.00	0.2207	0.00	CREDIT FASTENERS ON RP MATERIALS
CABLE JACKET	0.00	0.00	0.0000	0.00	
PAPER TAGS	15.00	15.00	0.1120	1.68	
BLACK TIE WRAPS	0.00	0.00	0.0204	0.00	
INSULATION	0.00	0.00	0.0000	0.00	
ThERMO LAG	0.00	0.00	0.0000	0.00	
GYPSUM CEMENT	0.00	0.00	0.0000	0.00	
UC FILTERS	0.00	0.00	0.0000	0.00	
POOL BOTTOM	20.00	20.00	0.1955	3.91	
<b>SUBTOTAL</b>	<b>164.10</b>	<b>35.00</b>		<b>5.59</b>	
<b>TOTAL</b>				<b>11.97</b>	CURRENT - 11% BLOCKAGE