

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALBRF 2 00-000000-000 341111 4

CON'T 01 REPORT SOURCE L 6 05000260 7 011981 8 012881 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
07 During normal operation while performing SI-4.1.A-7, reactor water level
03 switches LIS-3-203A switch 1, LIS-3-A, B, C, and D switches 2 were found
04 outside T.S. 3.1.A and 3.2.B limits by 2.3%; 0.6%; 1.5%; 2.1%, and 3.6%
05 respectively. Redundant switches LIS-3-203 B, C, and D switches were
06 operating within limits. There was no effect on the health or safety of the
07 public. Previous events: 260/8029.

09 SYSTEM CODE I A 11 CAUSE CODE X 12 CAUSE SUB CODE Z 13 COMPONENT CODE INSTRU 14 COMP SUBCODE S 15 VALVE SUBCODE Z 16
17 LCR NO REPORT NUMBER 81 18 SEQUENTIAL REPORT NO 004 19 OCCURRENCE CODE 01 20 REPORT TYPE T 21 REVISION NO 0
ACTION TAKEN E 18 FAILURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED Y 23 NPRO 4 FORM SUB N 24 PRIME COMP SUPPLIER L 25 COMPONENT MANUFACTURER B080

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
11 The Barton model/288 switches drifted due to air impact drilling next to
the panel on which they were mounted. This drilling was necessary to install
panel stanchion guards. Each switch was inspected, recalibrated, functionally
tested and returned to service. No recurrence control can be identified at
this time.

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Testing
16 ACTIVITY CONTENT Z 32 RELEASED OR RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39
18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
20 PUBLICLY ISSUED DESCRIPTION N 44 NA 45

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 814 Technical Specification Involved 3.1.A and 3.2.B
Reported Under Technical Specification 6.7.2.A(1)
Date of Occurrence 1/19/81 Time of Occurrence 0930 Unit 2

Identification and Description of Occurrences:

LIS-3-203A switch 1 and LIS-3-A, B, C, and D switches 2 were found outside of technical specification limits by 2.3%; 0.6%; 1.5%; 2.1%; and 3.6%, respectively.

Conditions Prior to Occurrence:

Unit 1 at 99% power.
Unit 2 at 100% power.
Unit 3 at 20% power.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Impact air drilling next to the instrument panel caused instruments to drift.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to plant or equipment, and no resulting significant chain of events.

Corrective Action:

Inspected, recalibrated, functionally tested, and returned switches to service. These switches will be replaced with analog transmitters by DCR 1398.

Failure Data:

259/7322, 259/7341, 259/7333, 259/7824, 259/741, 260/804, 296/8028, and 260/8029

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision:

