

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
 7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 8 | 0 | 1 | 8 | 2 | 8 | 0 | 8 | 1 | 3 | 8 | 2 | 9  
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | A Limiting Condition for Operation was entered on July 29 due to inoperability of the  
 0 3 | fuel handling area ventilation effluent monitoring system. The sampler pumps were  
 0 4 | removed from service for replacement. The sampling requirements of T.S.3.3.7.12-1  
 0 5 | were not performed until August 1. Noble gas, iodine, and particulate samples should  
 0 6 | have been taken on July 29, July 30, and July 31. The event is reportable pursuant  
 0 7 | to T.S.6.9.1.12.

0 8 | \_\_\_\_\_ 80

|  |
|--|
| 0 9   M   C   11   A   12   A   13   P   U   M   P   X   X   14   Z   15   Z   16  |
| 7 8 9 10 11 12 13 14 15 16 17 18 19 20   |
| 17   LER/RO REPORT NUMBER   8   2   21   22   -   23   0   1   9   24   26   /   27   0   1   28   29   T   30   -   31   0   32 |
| 18   X   19   Z   20   Z   21   0   0   0   0   22   Y   23   N   24   A   25   G   0   8   0   26                               |
| 33 34 35 36 37 40 41 42 43 44 47   |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Chemistry personnel did not perform sampling until August 1. Shift Superintendents  
 1 1 | had initialed the LCO report indicating tests were being performed on July 29, July 30,  
 1 2 | and July 31. Copies of future Incident Reports will be routed to the Chem/Rad  
 1 3 | supervisor for review.

1 4 | \_\_\_\_\_ 80

|  |
|--|
| 1 5   H   28   0   0   0   29   NA   30   A   31   Incidental Observation   32 |
| 7 8 9 10 12 13 44 45 46 80   |

|   |
|---|
| 1 6   Z   33   Z   34   NA   35   NA   36 |
| 7 8 9 10 11 44 45 80                      |

|   |
|---|
| 1 7   0   0   0   37   Z   38   NA   39 |
| 7 8 9 11 12 13 80                       |

|                                |  |
|--------------------------------|--|
| 1 8   0   0   0   40   NA   41 | 8208200067 820813<br>PDR ADOCK 05000416<br>S PDR |
| 7 8 9 11 12 80                 |  |

|                        |
|------------------------|
| 1 9   Z   42   NA   43 |
| 7 8 9 10 80            |

|   |              |
|---|--------------|
| 2 0   N   44   NA   45                    | NRC USE ONLY |
| 7 8 9 10 80 81 82 83 84 85 86 87 88 89 90 |              |

NAME OF PREPARER Original Signed by Ron Byrd

PHONE \_\_\_\_\_

Supplementary Information to  
LER 82-019/01 T-0

Licensee: Mississippi Power & Light Company  
Facility: Grand Gulf Nuclear Station - Unit 1  
Docket No.: 50-416

Background

On July 29, 1982, the fuel handling area ventilation monitoring sampler pump "B2" was removed from service for replacement. The work order was initiated on July 21 after preventive maintenance activities revealed that the "B1" pump had an oil leak. The maintenance work order was mistakenly written for "B2" rather than for pump "B1". Both pumps were replaced and the system was restored to operable status on August 10, 1982. The system inoperability will be discussed in a separate report pursuant to T.S.6.9.1.13.b.

Discussion

This report concerns a Technical Specification violation in which the action required by the above LCO was not initially performed. T.S.3.3.7.12-1 requires noble gas sampling at least once per 8 hours and particulate and iodine sampling continuously when the system is inoperable. Shift Superintendents had initialed the LCO report indicating that tests were performed on their shift on July 29, July 30, and July 31. On August 1 it was determined by a Shift Superintendent that no tests were being performed.

In the future, copies of Incident Reports which require testing or action by Chemistry or Health Physics personnel will be forwarded to the Chem/Rad Supervisor for review.