

LER No. 82-016
Omaha Public Power District
Fort Calhoun Station Unit No. 1
Docket No. 05000285

Attachment No. 1

Safety Analysis

The Fort Calhoun Station Reactor Protective System (RPS) is designed such that no single channel failure can prevent the safe shutdown of the plant if required. During the inoperability of the Axial Power Distribution (APD) "B" channel, the three remaining APD trip channels (A, C, and D) were operable and functioning at their appropriate setpoints. Since the "B" channel was immediately placed in the bypassed condition, the APD channels were then operable in a two-out-of-three trip logic until the "B" channel was repaired and retested for proper operation per applicable sections of Surveillance Test ST-RPS-12, F.2.

The upper and lower trip setpoints for the APD channels of the RPS are checked each shift with axial shape index indications per Surveillance Test ST-RPS-12, F.1. The APD channel pre-trip and trip setpoints are also tested and verified monthly per Surveillance Test ST-RPS-12, F.2. These surveillance tests ensure the APD channels and trip setpoints are properly functioning and will detect setpoint drifting or system malfunction.

LER No. 32-016
Omaha Public Power District
Fort Calhoun Station Unit No. 1
Docket No. 05000285

Attachment No. 2

Corrective Action

Resulting from the maintenance order investigation, it was postulated that the "B" channel "Flow Dependent Setpoint Selector Switch" had a dirty contact which was causing the Axial Shape Index negative setpoint to drift. Since this switch is sealed in an enclosure, the switch contact could not be cleaned via normal methods. However, the switch contact was cleaned/burnished by rotating the switch several times between the "4-pump" and "3-pump" positions. This resulted in adequate cleaning as the setpoint for the negative Axial Shape Index returned within tolerance. The applicable sections of Surveillance Test ST-RPS-12, F.2 were then satisfactorily performed to verify the correct system setpoints and the "B" channel for Axial Power Distribution was returned to service.

No further corrective action, other than continued monitoring of the RPS setpoints via shift channel checks and surveillance testing, as detailed in Attachment No. 1, is planned or scheduled at this time.

LER No. 82-016
Omaha Public Power District
Fort Calhoun Station Unit No. 1
Docket No. 0500285

Attachment No. 3

Failure Data

This is the first occurrence at the Fort Calhoun Station of a Flow Dependent Setpoint Selector Switch contact causing an APD channel to drift out-of-setpoint tolerance.