	CONTROL BLOCK: THE STATE OF THE ALL REQUIRED INFORMATION
0 1	F L C R P 3 2 0 0 - 0 0 0 0 - 0 0
0 i	SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 60
0 2	At 0045, during a thunderstorm, it was discovered that the windspeed and
0 3	temperature channels for both 33 and 175 ft. Meterological Tower Elevations
0 4	were not functioning properly. This is contrary to Technical Specification
0 5	1 3.3.3.4. There was no effect upon public health or safety. These are the
0 6	L second and sixth occurrences for the 33 and 175 ft. Wind Channels, respec-
0 7	L tively. It is also the fourth and fifth occurrence for the 33 and 175 ft.
08	Temperature Channel, respectively. This is the 22nd report under this specification.
0 9	CODE SUBCODE S
	17 REPORT NUMBER SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 4 8 9 9 9 9 9 9 9 9 9
	ACTION FUTURE OFFECT SHUTDOWN HOURS (22) ATTACHMENT SUBMITTED FORM SUB. SUPPLIER SUP
10	These instruments were affected by a lightning strike. Damaged equipment
	was removed, repaired, and calibrated. The instruments were returned to
1 2	L service on 7/19/82. An evaluation is in progress to determine methods to J
1 3	prevent recurrence of this type of event.
14	ļ
1 5	STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 OPERATOR OBSERVATION 32
R	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
7 8	Z (33) Z (34) N/A
1 7	NUMBER DESCRIPTION (39) N/A
	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	Z @ N/A
	PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY N/A
2 0	N/A
	NAME OF PREPARER Charles G. Brown PHONE (904) 795-6486