



LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81072 Technical Specification Involved Table 3.2.B  
Reported Under Technical Specification 6.7.2.b(2) \* Date Due NRC 12/12/81  
Date of Occurrence 11/12/81 Time of Occurrence 1520 Unit 1

Identification and Description of Occurrence:

Pressure transmitter 1-PT-74-65 was found out of tolerance.

Conditions Prior to Occurrence:

Unit 1 at 99%.

Unit 2 at 100%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Instrument drift.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The GE model 551 pressure transmitter was recalibrated, functionally tested, and returned to service. This is considered a random event and no further recurrence control is required.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: 